Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

211011011011111111111111111111111111111							
5.	Lease Serial No. NMSF078513						
_	TOT 11 A 11	m 'l N					

abandoned wel	6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name						
SUBMIT IN T	7. If Unit or CA/Agr	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well	8. Well Name and No ARNAUD A 4	8. Well Name and No.						
Oil Well Gas Well Oth		9. API Well No.						
<ol><li>Name of Operator BP AMERICA PRODUCTION</li></ol>		30-045-28682-00-S1						
3a. Address 501 WESTLAKE PARK BLVD HOUSTON, TX 77079	. THREE ELDRIGE PLACEPh: 2:	10. Field and Pool or Exploratory Area BLANCO PICTURED CLIFFS						
4. Location of Well (Footage, Sec., T.	11. County or Parish	11. County or Parish, State						
Sec 20 T32N R9W NENE 118 37.007111 N Lat, 107.843460	SAN JUAN CO	SAN JUAN COUNTY, NM						
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize ☐	Deepen	☐ Production (Start/Resume)	■ Water Shut-Off				
_	☐ Alter Casing	Hydraulic Fracturing	□ Reclamation	☐ Well Integrity				
Subsequent Report	☐ Casing Repair	New Construction	☐ Recomplete	☐ Other				
☐ Final Abandonment Notice	☐ Change Plans	▼ Plug and Abandon	□ Temporarily Abandon					
SY	☐ Convert to Injection ☐	Plug Back	■ Water Disposal					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Please see the attached plugging operations performed on the subject well November- December 2017.  OIL CONS. DIV DIST. 3  DEC 1 3 2017								
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #396930 verified by the BLM Well Information System  For BP AMERICA PRODUCTION COMPANY, sent to the Farmington  Committed to AFMSS for processing by ABDEL GADIR ELMADANI on 12/11/2017 (17AE0256SE)								
Name (Printed/Typed) TOYA CO	LVIN	Title REGULA	ATORY ANALYST					
Signature (Electronic S	submission)	Date 12/05/20	Date 12/05/2017					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By ACCEPT	ED		DIR ELMANDANI JM ENGINEER	Date 12/11/2017				
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive to the conductive terms of the con	itable title to those rights in the subject le	ease	Office Farmington					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



## **BP America Production Company**

### Plug And Abandonment Report

#### Arnaud A 4

1180' FNL & 1100' FEL, Section 20, T32N, R9W San Juan County, NM / API 30-045-28682

#### **Work Summary:**

- 11/28/17 Made BLM, and NMOCD P&A operations notifications at 1:00 PM MST.
- 11/29/17 MOL and R/U P&A unit. Checked well pressures: Tubing 240 psi, Casing 500 psi and Bradenhead 0 psi. Blew down well. N/D wellhead, N/U BOP and function tested. TOH and tallied production string. P/U casing scraper and round tripped casing scraper above top perforation at 3655'. Shut-in well and shut down for the day. Darryl Priddy was BLM representative on location.
- 12/1/17

  TIH and set CR at 3608'. Tested tubing to 1000 psi in which it successfully held pressure. Stung out of CR and circulated hole clean with 60 bbl fresh water. Tested casing to 900 psi in which it successfully held pressure. Pressure test witnessed by BLM rep Darryl Priddy. R/U Drake Energy Services and pumped balanced plugs 1-4 Plug #1: (Pictured Cliffs Perforations and Formation Top 3608'-3549', 6 Sacks Class B Cement)

Mixed 6 sx Class B cement and spotted a balanced plug to cover Pictured Cliffs perforations and formation top.

Plug #2: (Fruitland Formation Top 3280'-3130', 12 Sacks Class B Cement)

Mixed 12 sx Class B cement and spotted a balanced plug to cover Fruitland formation top.

Plug #3: (Kirtland and Ojo Alamo Formation Tops 2397'-2117', 19 Sacks Class B Cement)

Mixed 19 sx Class B cement and spotted a balanced plug to cover Kirtland and Ojo Alamo formation tops.

# Plug #4: (Nacimiento Formation Top 844'-677', 12 Sacks Class B Cement)

Mixed 12 sx Class B cement and spotted a balanced plug to cover Nacimiento formation top.

Loaded Bradenhead with approximately ¼ bbl of fresh water and tested to 300 psi in which it successfully held pressure. Pumped surface plug from 264' to surface: Plug #5: (Surface 264'-surface, 100 Sacks Class B Cement)

N/D BOP. Cut-off wellhead and topped-off surface. Installed P&A marker per BLM and NMOCD standards. R/D MOL



## **Wellbore Diagram**

Arnaud A 4
API #: 3004528682
San Juan, New Mexico

#### Plug 5

264 feet - Surface 264 feet plug 100 sacks of Class B Cement

#### Plug 4

844 feet - 677 feet 167 feet plug 12 sacks of Class B Cement

#### Plug 3

2397 feet - 2117 feet 280 feet plug 19 sacks of Class B Cement

#### Plug 2

3280 feet - 3130 feet 150 feet plug 12 sacks of Class B Cement

#### Plug 1

3608 feet - 3549 feet 59 feet plug 6 sacks of Class B Cement

#### **Perforations**

3655 feet - 3724 feet 3760 feet - 3770 feet

#### **Formation**

**Surface Casing** 

8.625" 24# @ 264ft

Fruitland Coal - 3236 feet Pictured Cliffs - 3652 feet

Retainer @ 3608 feet

Production Casing 4.5" 11.6# @ 3923 ft

