Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMSF078147

6.	If Indian,	Allottee	or Tribe	Name

abandoned wel	o. II maini, mionee oi	THE TAME					
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No. 14080012052						
Type of Well	8. Well Name and No. MOORE LS 3						
Name of Operator HILCORP ENERGY COMPAN	9. API Well No. 30-045-60060-00-S1						
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002		3b. Phone No Ph: 505-32	. (include area code) 4-5188		10. Field and Pool or Exploratory Area BLANCO MESAVERDE		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description,)			11. County or Parish, S	tate	
Sec 13 T32N R12W NWSW 1 36.983612 N Lat, 108.051590	SAN JUAN COUNTY, NM						
12. CHECK THE AP	PPROPRIATE BOX(ES)	TO INDICA	ΓE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	OF SUBMISSION TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	□ Deep	oen	☑ Product	ion (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	ation	■ Well Integrity	
Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	lete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	□ Tempor	arily Abandon		
	☐ Convert to Injection	Plug	Back	☐ Water D	Disposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. This well was re-delivered on 12/8/2017 and produced natural gas and entrained hydrocarbons. NOTES: WELL WAS SHUT IN FOR MORE THAN 90 DAYS DUE TO WORKOVER. RETURNED TO PRODUCTION. TP: 166 CP: 233 Initial MCF: 191 Meter No: 70913 Gas Co.: ENT Proj Type: REDELIVERY							
	Electronic Submission #3	NERGY COMP	ANY, sent to the	Farmington	SANGE CO.		
Name (Printed/Typed) PRISCILL	A SHORTY	Title OPERA	TIONS REC	SULATORY TECH			
Signature (Electronic S	ubmission)	W.	Date 12/21/20	017			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE		
Approved By ACCEPT	WILLIAM T TitlePETROLE	AMBEKOU UM ENGINE	EER	Date 01/18/2018			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Office Farming	ton			
Title 18 U.S.C. Section 1001 and Title 43 V States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any pe	rson knowingly and	willfully to ma	ke to any department or a	gency of the United	

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

