

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

OIL CONS. DIV DIST. 3

MAN 0 2 2018 BRADENHEAD TEST REPORT

.....

(Submit 2 copies to above address)

Date of Test	08/16/17	Operator	BP	America Production (API #	3004522762		
Property Name	STATE GC	J 001A-MV		Location: Unit F	Section 36	Township	30 Rar	nge 9
	(Well Name a	and Number)						
Pressure (Shut-i	n or Producing)	Tubing 1	7.9	Intermediate	Casing	34.7 Br	radenhead	33.7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

	Bradenhead			Interme	diate		Bradenhead	Intermediate
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0.1	34.3				Steady Flow	nd stead	
10 minutes	0.1	34.3				Surges		
15 minutes	0.1	34.3				Down to Nothing		
20 minutes	0.1	34.2				No Flow		
25 minutes	0.1	34.2				Gas		
30 minutes	0.1	34.2				Gas and Water		
5 minute SI	12.5					Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

Compressor on location running cosing closed pulled gas sample on all strings tubing, casing and bradenhead.

By

Matthew Yazzie

Witness

NMOCD Test Area: A