District 1th 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Form C-144

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

Pit, Below-Grade Tank, or

OIL CONS. DIV DIST. 3

Form C-144 Revised April 3, 2017

Revised April 3, 2017

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Proposed Alternative Method Permit or Closure Plan Application
Type of action: Below grade tank registration Permit of a pit or proposed alternative method Closure of a pit, below-grade tank, or proposed alternative method Modification to an existing permit/or registration Closure plan only submitted for an existing permitted or non-permitted pit, below-grade tank,
or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
Operator: BP America Production Company OGRID #: 778
Address: 200 Energy Court, Farmington, NM 87401
Facility or well name: WARREN 004
API Number: 3004523970 OCD Permit Number:
API Number: 3004523970 OCD Permit Number: U/L or Qtr/Qtr P Section 13 Township 28N Range 09W County: San Juan
Center of Proposed Design: Latitude 36.65736 Longitude -107.73495 NAD83
Surface Owner: 🔳 Federal 🗌 State 🔲 Private 🔲 Tribal Trust or Indian Allotment
☐ Pit: Subsection F, G or J of 19.15.17.11 NMAC Temporary: ☐ Drilling ☐ Workover ☐ Permanent ☐ Emergency ☐ Cavitation ☐ P&A ☐ Multi-Well Fluid Management Low Chloride Drilling Fluid ☐ yes ☐ no ☐ Lined ☐ Unlined Liner type: Thickness mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other ☐ String-Reinforced
Below-grade tank: Subsection I of 19.15.17.11 NMAC TANK A Volume: 95 bbl Type of fluid: Produced Water Tank Construction material: Steel Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off Visible sidewalls and liner Visible sidewalls only Other Single wall/ Double bottom; sidewalls not visible Liner type: Thickness mil HDPE PVC Other
4. Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.
5. Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify Alternate.

Oil Conservation Division

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other	
Monthly inspections (If netting or screening is not physically feasible)	
Signs: Subsection C of 19.15.17.11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19.15.16.8 NMAC	
Variances and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
9. Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptance are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	ptable source
General siting	
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
 Within an unstable area. (Does not apply to below grade tanks) Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ☐ No
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	☐ Yes ☐ No
Below Grade Tanks	
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial application.	☐ Yes ☐ No
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No

Temporary Pit Non-low chloride drilling fluid Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or plays lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site - Visual inspection (certification) of the proposed site, 24rail photo; Satellite image Within 500 feet of ma a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application. - NM Office of the State Engineer - INVATES database search; Visual inspection (certification) of the proposed site - Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site - Visual inspection (certification) of the proposed site, Aerial photo; Satellite image Within 500 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site - Within 500 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site - Within 500 feet from a permanent residence, school, hospital, institution, or church in existence at the time of ini	Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
or playa lake (measured from the ordinary high-water mark). Topographic map, Visual inspection (certification) of the proposed site Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 300 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. Visual inspection (certification) of the proposed site horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Temporary Pit Non-low chloride drilling fluid	
- Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Yes No No No No No No No N	or playa lake (measured from the ordinary high-water mark).	Yes No
watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 300 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Topographic map; Visual inspection (certification) of the proposed site Within 500 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 feet for a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a welland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Within 500 feet of a welland US Fish and Filosophy of the proposed site with map o		☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map, Visual inspection (certification) of the proposed site Visual inspection (certification) of the proposed site yes No Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image yes No Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Yes No Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Yes No Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.10 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Previously Approved Design (attach copy of design) API Number:	watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application;	☐ Yes ☐ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NMOffice of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Yes No **NOOFfice of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.10 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number:		☐ Yes ☐ No
lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site New Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Stiting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number: "Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC Hydrogeologic Data - based upon the appropri	Permanent Pit or Multi-Well Fluid Management Pit	
Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Yes No	lake (measured from the ordinary high-water mark).	Yes No
initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site		☐ Yes ☐ No
US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site Yes No	initial application.	☐ Yes ☐ No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: Or Permit Number: Or Permit Number: Or Permit Number: Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.19 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.10 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC		Yes No
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 N Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC	NMAC
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC		
La rivinous frapriores Design (attach copy of design) Transfer. Of Termit Number.	Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19. and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the	documents are
attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.	
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well F Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method	luid Management Pit
14.	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be a closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
15.	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. Fig. 15.17.10 NMAC for guidance.	cce material are Please refer to
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	Yes No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 300 feet of a wetland.	
US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	

adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	
Within a 100-year floodplain.	Yes No
- FEMA map	L res No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17. Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cann Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	11 NMAC 15.17.11 NMAC
17. Operator Application Certification:	
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and beli	ef.
Name (Print): Title:	
Signature: Date:	
e-mail address:	
18. OCD Approval: ☐ Permit Application (including closure plan) ☑ Closure Plan (only) ☐ OCD Conditions (see attachment)	/ / -
OCD Representative Signature: Approval Date:	19/18
Title: Louisonmental Spal OCD Permit Number:	
Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date: 12/5/2017	
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-lo If different from approved plan, please explain.	op systems only)
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please incomark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure for private land only) Plot Plan (for on-site closures and temporary pits)	dicate, by a check

22. ^R	
Operator Closure Certification:	
	itted with this closure report is true, accurate and complete to the best of my knowledge and icable closure requirements and conditions specified in the approved closure plan.
Name (Print): Erin Garifalos	Title: Field Environmental Coordinator
Signature:UTIN GOTIFIALOS	Date: January 26, 2018
e-mail address: erin.garifalos@bp.com	Telephone: (832) 609-7048

BP AMERICA PRODUCTION COMPANY SAN JUAN BASIN, NORTHWEST NEW MEXICO

BELOW-GRADE TANK CLOSURE PLAN

WARREN 004

API No. 3004523970

Unit Letter P Section 13 T 28N R 09W

This plan will address the standard protocols and procedures for closure of below-grade tanks (BGTs) on BP America Production Company (BP) well sites. As stipulated in Paragraph A of 19.15.17.13 NMAC, BP shall close a BGT within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the New Mexico Oil Conservation Division (NMOCD) requires because of imminent danger to fresh water, public health, safety or the environment. If deviations from this plan are necessary, any specific changes will be included on form C-144 and approved by the NMOCD. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofit with a BGT that complies with the BP NMOCD approved BGT design attached to the BP Design and Construction Plan. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC, if not previously retrofitted to comply with the BP NMOCD approve BGT Design attached to the BP Design and Construction Plan, prior to any sale or change in operator pursuant to 19.15.9.9 NMAC. BP shall close the permitted BGT within 60 days of cessation of the BGTs operation or as required by the transitional provisions of Subsection B, D, or E of 19.15.17.17 NMAC.

General Closure Plan

1. BP shall notify the surface owner by certified mail that it plans to close a BGT. Evidence of mailing of the notice to the address of the surface owner shown in the county tax records demonstrates compliance with this requirement.

Notice is attached.

2. BP shall notify the division District III office verbally or by other means at least 72 hours, but not more than one (1) week, prior to any closure operation. The notice shall include the operator's name, and the location to be closed by unit letter, section, township and range. If the BGT closure is associated with a particular well, then the notice shall also include the well's name, number and API number.

Notice was provided and is attached.

- 3. BP shall remove liquids and sludge from the BGT prior to implementing a closure method and dispose of the liquids and sludge in a NMOCD's division-approved facility. The facilities to be used are:
 - a. BP Crouch Mesa Landfarm, Permit NM-02-003 (Solids)
 - b. JFJ Landfarm, Permit NM-01-010(B) (Solids and Sludge)
 - c. Basin Disposal, Permit NM-01-0005 (Liquids)
 - d. Envirotech Inc Soil Remediation Facility, Permit NM-01-0011 (Solids and Sludge)
 - e. BP Operated E.E. Elliott SWD #1, API 30-045-27799 (Liquids)

- f. BP Operated 13 GCU SWD #1, API 30-045-28601 (Liquids)
- g. BP Operated GCU 259 SWD, API 30-045-20006 (Liquids)
- h. BP Operated GCU 306 SWD, API 30-045-24286 (Liquids)
- i. BP Operated GCU 307 SWD, API 30-045-24248 (Liquids)
- j. BP Operated GCU 328 SWD, API 30-045-24735 (Liquids)
- k. BP Operated Pritchard SWD #1, API 30-045-28351 (Liquids)

All liquids and sludge in the BGT were removed and sent to one of the above NMOCD approved facilities for disposal.

4. BP shall remove the BGT and dispose of it in a NMOCD approved facility or recycle, reuse, or reclaim it in a manner that the NMOCD approves. If a liner is present and must be disposed of it will be cleaned by scraping any soils or other attached materials on the liner to a de minimus amount and disposed at a permitted solid waste facility, pursuant to Subparagraph (m) of Paragraph (1) of Subsection C of 19.15.35.8 NMAC. Documentation as to the final disposition of the removed BGT will be provided in the final closure report.

The BGT was transported for recycling.

5. BP shall remove any on-site equipment associated with a BGT unless the equipment is required for well production.

All equipment associated with the BGT has been removed.

6. BP shall test the soils beneath the BGT to determine whether a release has occurred. BP shall collect at a minimum: a five (5) point composite sample and individual grab samples from any area that is wet, discolored or showing other evidence of a release and analyze for BTEX, TPH and chlorides. The testing methods for those constituents are as follows;

Constituents	Testing Method	Release Verification	Sample
	95 bbl BGT	(mg/Kg)	results
Benzene	US EPA Method SW-846 8021B or 8260B	10	< 0.017
Total BTEX	US EPA Method SW-846 8021B or 8260B	50	< 0.069
TPH	US EPA Method SW-846 418.1 or 8015 extended	100	<49
Chlorides	US EPA Method 300.0 or 4500B	620	<30

Notes: mg/Kg = milligram per kilogram, BTEX = benzene, toluene, ethylbenzene, and total xylenes, TPH = total petroleum hydrocarbons. Other EPA methods that the division approves may be applied to all constituents listed. Chloride closure standards will be determined by which ever concentration level is greatest.

Soil under the BGT was sampled for chloride, TPH and BTEX with all concentrations below the stated limits. The field report and laboratory reports are attached.

7. BP shall notify the division District III office of its results on form C-141.

C-141 is attached.

8. If it is determined that a release has occurred, then BP will comply with 19.15.30 NMAC and 19.15.29 NMAC, as appropriate.

Sampling results indicate a release has not occurred. Attached is a laboratory report and C-141.

9. If the sampling demonstrates that a release has not occurred or that any release does not exceed the concentrations specified above, then BP shall backfill the excavation, with compacted, non-waste containing, earthen material; construct a division-prescribed soil cover, re-contour and re-vegetate the location. The location will be reclaimed if it is not with in the active process area

Sampling results indicate a release has not occurred. Attached is a laboratory report and field report. The location will be reclaimed when the well is plugged and abandoned.

10. BP shall reclaim the BGT location and all areas associated with the BGT including associated access roads to a safe and stable condition that blends with the surrounding undisturbed area. BP shall substantially restore the impacted surface area to the condition that existed prior to oil and gas operations by placement of the soil cover as provided in Subsection H of 19.15.17.13 NMAC, re-contour the location and associated areas to a contour that approximates the original contour and blends with the surrounding topography and re-vegetate according to Subsection I of 19.15.17.13 NMAC.

The area has been backfilled and a 105 BBL shallow low profile above-grade tank set atop BGT location. The location will be reclaimed once the well is plugged and abandoned.

11. The soil cover for closures where the BGT has been removed or remediated to the NMOCD's satisfaction shall consist of the background thickness of topsoil or one foot of suitable material to establish vegetation at the site, whichever is greater. The soil cover will be constructed to the site's existing grade and all practicable efforts will be made to prevent ponding of water and erosion of the cover material.

The area has been backfilled and a 105 BBL shallow low profile above-grade tank set atop BGT location. The location will be reclaimed once the well is plugged and abandoned.

12. BP shall seed the disturbed area the first growing season after closure of the BGT. Seeding will be accomplished by drilling on the contour whenever practical or by other division-approved methods. Vegetative cover will be, at a minimum, 70% of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation), consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintenance of that cover through two successive growing seasons. During the two growing seasons that prove viability, there shall be no artificial irrigation of the vegetation.

The area has been backfilled and a 105 BBL shallow low profile above-grade tank set atop BGT location. The location will be reclaimed once the well is plugged and abandoned.

13. BP shall seed, plant and re-seed pursuant to Paragraph (3) of Subsection I of 19.15.17.13 NMAC, until the location successfully achieves the required vegetative cover.

The area has been backfilled and a 105 BBL shallow low profile above-grade tank set atop BGT location. The location will be reclaimed once the well is plugged and abandoned.

14. Pursuant to Paragraph (5) of Subsection I of 19.15.17.13 NMAC, BP shall notify the NMOCD when it has seeded or planted and when it successfully achieves revegetation.

The area has been backfilled and a 105 BBL shallow low profile above-grade tank set atop BGT location. The location will be reclaimed once the well is plugged and abandoned.

- 15. Within 60 days of closure completion, BP shall submit a closure report on NMOCD's form C-144, and will include the following;
 - a. proof of closure notification (surface owner and NMOCD)
 - b. sampling analytical reports; information required by 19.15.17 NMAC;
 - c. disposal facility name and permit number
 - d. details on back-filling, capping, covering, and where applicable re-vegetation application rates and seeding techniques and
 - e. site reclamation, photo documentation.

Closure report on C-144 form is included including photos of reclamation completion.

16. BP shall certify that all information in the report and attachments is accurate, truthful, and compliant with all applicable closure requirements and conditions specified in the approved closure plan.

Certification section of C-144 has been completed.

District 7
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

				58	inta F	e, MWI 8/3	503					
			Rele	ease Notific	cation	n and Co	orrective A	ction	1			
						OPERA	TOR		Initia	al Report		Final Report
					-		n Garifalos	70.10				
	Teter Section Township Range Get from 13 28N 09W 1,140			on, NM 87401			No. (832) 609- be: Natural Ga					
	The of Company BP America Production Coderess 200 Energy Court, Farmington, NM ility Name WARREN 004 Face Owner: Federal Manage Feet from 13 28N 09W 1,14 Latitude 36.66 Township Range Feet from 13 28N 09W 1,14 Latitude 36.66 Township Range Feet from 14 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66 Township Range Feet from 15 28N 09W 1,14 Latitude 36.66						c. Natural G	as vve		000450	0070	`
Surface Ow	mer: Fed	eral				Federal			API No	300452	3970)
**************************************	[C	m 11	D			N OF RE		Fact/	West Line	Country		
					_	/South Line	Feet from the		West Line	County	an	Juan
Р	13	28IV		-	Sou		1,710	Eas	Sl		ari	Juan
			Latitud	le 36.65736	L	ongitude1	07.73495	NAD	83			
				NAT	URE	OF REL	EASE					
Type of Rele	ase:: none	9					Release: unkno			Recovered::		
Source of Re	lease: belo	w grade ta	nk - 95	bbl		Date and I	Hour of Occurrence	ce:	Date and n/a	Hour of Dis	covery	:
		Given?				If YES, To	Whom?		1			
			Yes ✓	No Not Re	equired							
By Whom?	course Read	ched?				Date and I	Hour olume Impacting t	the Wat	ercourse		_	
was a water	course read		Yes 🗸	No		II ILS, V	Stuffe Impacting	ine wat	creourse.			
If a Watercon	urse was Im	pacted, Descr	ibe Fully.	*								
Describe Co.	usa of Probl	am and Dama	dial Action	n Tokon *								
Describe Cat	ise of Probl	em and Keme	diai Actio	Sam	-		beneath the				_	
					-		d for Chloric					
					ire sta	andards. I	Field reports	and	aborato	ry results	are	attached.
Describe Are	a Affected	and Cleanup	Action Tak	cen.* No actio	n nec	essary F	inal laborate	orv a	nalvsis d	determin	ed n	0
						on is requ		o. y a.	idi y did d			
regulations a	ll operators	are required t	o report ar	nd/or file certain r	elease n	otifications a	nd perform correc	ctive act	tions for rela	eases which	may er	ndanger
				otance of a C-141	report d	loes not reliev	e the operator of	respons	ibility for co	ompliance w	ith any	other
lederal, state	, or local la	ws and/or regu	nations.				OIL CON	SERV	ATION	DIVISIO	N	
1	orin a	wilale	24				012 001.			27,12010		
Signature:	Samo	o o				Approved by	Environmental S	nacialia	t •			
Printed Name	e: Erin G	arifalos				Approved by	Environmental S	pecians				
				rdinator		Approval Da	te:		Expiration 1	Date:		
		garifalos							-Apriation 1	Jaco.		
						Conditions o	Approvai:			Attached		
Date: Janu	ary 26, 2	018	Phone:	(832) 609-70	J48							

^{*} Attach Additional Sheets If Necessary

bp



BP America Production Company 200 Energy Court Farmington, NM 87401

November 27, 2017

Bureau of Land Management Whitney Thomas 6251 College Suite A Farmington, NM 87402

VIA EMAIL

Re: Notification of plans to close/remove a below grade tank

Well Name: WARREN 004

API #: 3004523970

Dear Mrs. Thomas,

As part of the NM "Pit Rule": 19.15.17.13 Closure Requirements, Paragraph J. BP America Production Company (BP) is required to notify the surface owner of BP's plans to close/remove a below grade tank. BP wishes to inform you of our plans to close/remove the below grade tank on its well pad located on your surface. BP plans to commence this work on or about November 30, 2017. If there aren't any unforeseen problems, the work should be completed within 10 working days.

As a point of clarification, BP will be closing the below grade tank and either operating without one or replacing it with an above ground tank, the well site will continue to operate.

If witnessing of the tank removal is required please contact me for a specific time (832)-609-7048.

Sincerely,

Erin Garifalos

BP America Production Company

From:

Buckley, Farrah (CH2M HILL)

To:

Smith, Cory, EMNRD; Fields, Vanessa, EMNRD (Vanessa.Fields@state.nm.us)

Cc:

jeffcblagg@aol.com; blagg njv@yahoo.com; Garifalos, Erin

Subject: Date: RP Dit Close Notification - WAPPEN 004

BP Pit Close Notification - WARREN 004 Monday, November 27, 2017 4:24:01 PM

BP America Production Company

200 Energy Court Farmington, NM 87401 Phone: (505) 326-9200

SENT VIA E-MAIL TO: <u>CORY.SMITH@STATE.NM.US</u>; <u>VANESSA.FIELDS@STATE.NM.US</u>

November 27, 2017

New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

RE: Notice of Proposed Below-Grade Tank (BGT) Closure

WARREN 004 API 30-045-23970 (P) Section 13- T28N - R08W San Juan County, New Mexico

Dear Mr. Cory Smith and Mrs. Vanessa Fields,

In regards to the captioned subject and requirements of the NMOCD pit rule, this letter is notification that BP is planning to close a 95bbl BGT that will no longer be operational at this well site. We anticipate this work to start on or around November 30, 2017.

Should you have any questions, please feel free to contact BP at our Farmington office.

Sincerely,

Erin Garifalos

Field Environmental Coordinator – San Juan

Cell: 832-609-7048

Farrah Buckley BGT Project Support 970-946-9199 -cell

This email and any attachments are intended only for the addressee(s) listed above and may contain confidential, proprietary, and/or privileged information. If you are not an intended recipient, please immediately advise the sender by return email, delete this email and any attachments, and destroy any copies of same. Any unauthorized review, use, copying disclosure or distribution of this email and any attachments is prohibited.

* CLIENT: BP	NC. VI 87413	API #: 30045239 TANK ID (if applicble): A	970		
FIELD REPORT:		•	OTHER:	_	1
	28N RNG: 9W PM:	NM CNTY: SJ YPE: FEDERAL STATE	ST: NM	DATE FINISHED:)/17
LEASE #: SF077123 REFERENCE POINT		ONTRACTOR: BP-J. GO	45 X 107.73485	SPECIALIST(S): JC GL ELEV.: 5,9	931'
1) 95 BGT (SW/DB) 2) 3) 4)	GPS COORD.:		DISTANCE/BEA DISTANCE/BEA	RING FROM W.H.:	
SAMPLE ID: SAMPLE ID: SAMPLE ID:	SAMPLE DATE: 11/30 SAMPLE DATE: SAMPLE DATE: SAMPLE DATE:	SAMPLE TIME: 1350 SAMPLE TIME: SAMPLE TIME: SAMPLE TIME:	LAB ANALYSIS: LAB ANALYSIS: LAB ANALYSIS: LAB ANALYSIS:	15B/8021B/300.0 (CI)	OVM READING (ppm) 0.0
SOIL COLOR: DARK YEL COHESION (ALL OTHERS): NON COHESIVE / SLIGHTLY CONSISTENCY (NON COHESIVE SOILS): LO MOISTURE: DRY SLIGHTLY MOIST / WOIST / WOISTURE: TYPE: GRAB (COMPOSITE) # DISCOLORATION/STAINING OBSERVED: YES NO SITE OBSERVATION	LOWSH ORANGE Y COHESIVE / COHESIVE / HIGHLY COHESIVE DOSE (FIRM) DENSE (VERY DENSE) ET / SATURATED / SUPER SATURATED FOF PTS	PLASTICITY (CLAYS): NON PLASTI DENSITY (COHESIVE CLAYS & HC ODOR DETECTED: YES NO ANY AREAS DISPLAYING WETNE YES NO EXPLANATION -	IC / SLIGHTLY PLASTIC / C & SILTS): SOFT / FIRM / BEXPLANATION -	OHESIVE / MEDIUM PLASTIC / HIGHLY STIFF / VERY STIFF / HARD	
EQUIPMENT SET OVER RECLAIMED AREA: OTHER: BEDROCK WAS EXCAVATED TO	YES NO EXPLANATION - 105 BBI D INITIALLY INSTALL BGT. NMO	SHALLOW LOW PROFILE CD OR BLM REPS. NOT PR	ESENT TO WITNESS	S CONFIRMATION SAMPLING	3.
	Color Colo				
FENC	PROD. TANK	G. BERM	R V P P O Tar III A	ID: VHIXONEV11 J#: ermit date(s): 06/09/ CD Appr. date(s): 08/29/ NOVM = Organic Vapor Meter ppm = parts per million BGT Sidewalls Visible: Y / N	/10 /17
T.B. = TANK BOTTOM; PBGTL = PREVIOUS BEL APPLICABLE OR NOT AVAILABLE; SW - SINGLI	OW-GRADE TANK LOCATION; SPD = SAMPLE P E WALL; DW - DOUBLE WALL; SB - SINGLE BOT	OINT DESIGNATION; R.W. = RETAINING TOM; DB - DOUBLE BOTTOM.	GWALL; NA - NOT N	lagnetic declination: 10°	E

Analytical Report

Lab Order 1712003

Date Reported: 12/5/2017

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Blagg Engineering

Client Sample ID: 95 BGT 5-pt @ 4'

WARREN 4 Project:

Collection Date: 11/30/2017 1:50:00 PM

Lab ID: 1712003-001

Matrix: SOIL

Received Date: 12/1/2017 7:08:00 AM

Analyses	Result	PQL Qu	al Units	DF	Date Analyzed	Batch
EPA METHOD 300.0: ANIONS					Analyst:	MRA
Chloride	ND	30	mg/Kg	20	12/1/2017 11:48:33 AM	35263
EPA METHOD 8015M/D: DIESEL RANG	E ORGANICS				Analyst:	TOM
Diesel Range Organics (DRO)	ND	9.8	mg/Kg	1	12/1/2017 9:52:46 AM	35260
Motor Oil Range Organics (MRO)	ND	49	mg/Kg	1	12/1/2017 9:52:46 AM	35260
Surr: DNOP	98.6	70-130	%Rec	1	12/1/2017 9:52:46 AM	35260
EPA METHOD 8015D: GASOLINE RAN	GE				Analyst:	NSB
Gasoline Range Organics (GRO)	ND	3.4	mg/Kg	1	12/1/2017 12:31:42 PM	G47476
Surr: BFB	88.6	15-316	%Rec	1	12/1/2017 12:31:42 PM	G47476
EPA METHOD 8021B: VOLATILES					Analyst:	NSB
Benzene	ND	0.017	mg/Kg	1	12/1/2017 12:31:42 PM	B47476
Toluene	ND	0.034	mg/Kg	1	12/1/2017 12:31:42 PM	B47476
Ethylbenzene	ND	0.034	mg/Kg	1	12/1/2017 12:31:42 PM	B47476
Xylenes, Total	ND	0.069	mg/Kg	1	12/1/2017 12:31:42 PM	B47476
Surr: 4-Bromofluorobenzene	84.7	80-120	%Rec	1	12/1/2017 12:31:42 PM	B47476

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix
- Analyte detected in the associated Method Blank
- E Value above quantitation range
- Analyte detected below quantitation limits Page 1 of 5
- Sample pH Not In Range P
- RL Reporting Detection Limit
- Sample container temperature is out of limit as specified

CI	hain-c	of-Cus	stody Record	Turn-Around	Time:	SAME					AL			AI V	/TE	20	BA E	W E	N	FA		•
Client:	BLAG	G ENGR.	/ BP AMERICA	Standard	☑ Rush _	DAY)	-		H										AT			
-				Project Name						-							.com		411			
Mailing Ad	ddress:	P.O. BO	V 97		WARREN	# 4		**	04.1										•			
		-		Project #:	AAMINEIA	" "	1											3710	9			
			FIELD, NM 87413	Troject #.				Te	1. 50	05-3	45-3	-					-410	7				100
Phone #:		(505) 63	32-1199	D : 111				4			9.3	F	Anal	ysis	Red	ques	st					
email or F			AL MARKAGE ON	Project Manag	ger:									040	S			0.1)				
QA/QC Pa	5		Level 4 (Full Validation)		JEFFREY C.	BLAGG	FMB's (8021B)	(Aluo	DRO / MRO)			(S)		PO4,50	2 PCB's			ter - 300.1)			e	
Accreditat	ion:			Sampler:	JEFFREY C.	BLAGG	₹ 8	(Gas	RO,	1	1	OSIN		102	808			/ wa			du	
□ NELAP	,	□ Other			¥ Yes		1	TPH	-	418	504	827		03,1	18/8		(A)	0.00			e Sa	N
	ype)	T			erature 3.4-	$(3(CE)=2\cdot 1)$	1	+ 3	(GR(por	pot	or	etak	N,	cide	8	i-V	ii - 3		e e	osit	(γ)
Date	Time	Matrix	Sample Request ID	Container Type and #	Preservative Type	HEAL No.	X	BTEX + MTBE + TPH (Gas only)	TPH 8015B (GRO	TPH (Method 418.1)	EDB (Method 504.1)	PAH (8310 or 8270SIMS)	RCRA 8 Metals	Anions (F,Cl,NO3,NO2,PO4,SO4)	8081 Pesticides / 8082	8260B (VOA)	8270 (Semi-VOA)	Chloride (soil - 300.0 / water		Grab sample	5 pt. composite sample	Air Bubbles (Y or N)
-/-			0 = 2 (=	Meantket		11/2003	ВТЕХ	BTE	<u>d</u>	F	ED	PA	2	An	80	82	82	ਨ		Gre	5 p	Air
1/30/2017	1350	SOIL	95 BGT 4/ 5-PC Q 4	4 oz 1	Cool	-001	٧		٧.									٧			٧	
,																						
																		\Box		\Box		
		1.														\vdash					\Box	
	-	1					\vdash		_					_		\vdash		\vdash				
	-			1				\vdash				_										
						-	-	_		-	_						-	\vdash	\vdash	-	\dashv	
							-	_			_	_	_					\vdash	$\vdash\vdash$		\vdash	
	1.35		. , 4	-			_						_						\square	\square		
			,										_	_								
			1																			
Date: /1/30/2017	Time:	Relinquish	ed by: Blagg	Received by:	h 1-	Date Time		arks		& RE	FERE	VCE #	WHE	N APE	LICA	BLE;		VITH C	CORRE	SPON	DING	VID
Date:	1710 Time:	Relinquish	`	Received by:	40	Date Time	٥ ا			ERI				/ VA	NCE	HIX	NC					
11/20/17		1/16	HILLA	Sipl'	C- 12	101117 0708	Ref	eren				893										

If necessary, samples submitted to Hall Environmental may be subcontracted to other accredited laboratories. This serves as notice of this possibility. Any sub-contracted data will be clearly notated on the analytical report.

Hall Environmental Analysis Laboratory, Inc.

WO#:

1712003

05-Dec-17

Client:

Blagg Engineering

Project:

WARREN 4

Sample ID MB-35263

SampType: mblk

TestCode: EPA Method 300.0: Anions

Client ID:

PBS

Batch ID: 35263

PQL

RunNo: 47471

Prep Date:

12/1/2017

Analysis Date: 12/1/2017

SeqNo: 1516483

Units: mg/Kg

HighLimit

%RPD **RPDLimit**

Qual

Analyte Chloride

Result

ND 1.5

TestCode: EPA Method 300.0: Anions

Client ID:

LCSS

SampType: Ics Batch ID: 35263

RunNo: 47471

Units: mg/Kg

Prep Date:

Sample ID LCS-35263

12/1/2017

Analysis Date: 12/1/2017

SeqNo: 1516484

Analyte PQL SPK value SPK Ref Val %REC HighLimit

14

110

%RPD

RPDLimit

Qual

Chloride

1.5 15.00 92.7

SPK value SPK Ref Val %REC LowLimit

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- Sample Diluted Due to Matrix D
- Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- **PQL** Practical Quanitative Limit
- % Recovery outside of range due to dilution or matrix
- Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- Sample pH Not In Range
- RL Reporting Detection Limit
- Sample container temperature is out of limit as specified

Page 2 of 5

Hall Environmental Analysis Laboratory, Inc.

ND

8.4

WO#:

1712003

05-Dec-17

Client:

Blagg Engineering

Project:

Motor Oil Range Organics (MRO)

Surr: DNOP

WARREN 4

Sample ID LCS-35260	SampType: LCS TestCode: EPA Method 8015M/D: Diesel Range Organics							
Client ID: LCSS	Batch ID: 35260	RunNo: 47457						
Prep Date: 12/1/2017	Analysis Date: 12/1/2017	SeqNo: 1515167	Units: mg/Kg					
Analyte	Result PQL SPK valu	e SPK Ref Val %REC LowLimit	HighLimit %RPD RPDLimit Qu	ıal				
Diesel Range Organics (DRO)	45 10 50.0	0 0 89.8 73.2	114					
Surr: DNOP	3.8 5.00	0 75.8 70	130					
Sample ID MB-35260	SampType: MBLK	TestCode: EPA Method	8015M/D: Diesel Range Organics					
Client ID: PBS	Batch ID: 35260	RunNo: 47457						
Prep Date: 12/1/2017	Analysis Date: 12/1/2017	SeqNo: 1515168	Units: mg/Kg					
Analyte	Result PQL SPK valu	e SPK Ref Val %REC LowLimit	HighLimit %RPD RPDLimit Qua	ıal				
Diesel Range Organics (DRO)	ND 10							

83.7

70

130

10.00

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- Sample Diluted Due to Matrix
- Holding times for preparation or analysis exceeded
- Not Detected at the Reporting Limit
- Practical Quanitative Limit
- % Recovery outside of range due to dilution or matrix
- Analyte detected in the associated Method Blank В
- Value above quantitation range
- J Analyte detected below quantitation limits
- Sample pH Not In Range
- Reporting Detection Limit
- Sample container temperature is out of limit as specified

Page 3 of 5

Hall Environmental Analysis Laboratory, Inc.

1000

Blagg Engineering

Project: WARREN 4

Client:

Surr: BFB

Sample ID RB SampType: MBLK TestCode: EPA Method 8015D: Gasoline Range

Client ID: PBS Batch ID: G47476 RunNo: 47476

Prep Date: Analysis Date: 12/1/2017 SegNo: 1516064 Units: mg/Kg

Analyte Result PQL SPK value SPK Ref Val %REC LowLimit HighLimit %RPD RPDLimit Qual

Gasoline Range Organics (GRO) ND 5.0

Surr: BFB 880 1000 88.5 15 316

Sample ID 2.5UG GRO LCS SampType: LCS TestCode: EPA Method 8015D: Gasoline Range

Client ID: LCSS Batch ID: G47476 RunNo: 47476

Prep Date: Analysis Date: 12/1/2017 SeqNo: 1516065 Units: mg/Kg

1000

%RPD Analyte Result PQL SPK value SPK Ref Val %REC LowLimit HighLimit **RPDLimit** Qual Gasoline Range Organics (GRO) 25 5.0 25.00 99.8 75.9 131

104

Qualifiers:

* Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix

B Analyte detected in the associated Method Blank

E Value above quantitation range

J Analyte detected below quantitation limits

Analyte detected below quantita

Page 4 of 5

WO#:

316

15

1712003

05-Dec-17

P Sample pH Not In Range

RL Reporting Detection Limit

W Sample container temperature is out of limit as specified

Hall Environmental Analysis Laboratory, Inc.

WO#:

1712003

05-Dec-17

Client:

Blagg Engineering

Project:

WARREN 4

Sample ID RB	SampType: MBLK			TestCode: EPA Method 8021B: Volatiles						
Client ID: PBS	Batch ID: B47476			F	RunNo: 4	7476				
Prep Date:	Analysis Date: 12/1/2017			SeqNo: 1516095			Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.025								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	0.85		1.000		84.6	80	120			

Sample ID 100NG BTEX LC	S Samp1	ype: LC	s	TestCode: EPA Method 8021B: Volatiles						
Client ID: LCSS	Batcl	n ID: B4	7476	RunNo: 47476						
Prep Date:	Analysis Date: 12/1/2017			8	SeqNo: 1	516096	Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	0.93	0.025	1.000	0	92.6	77.3	128			
Toluene	0.93	0.050	1.000	0	92.7	79.2	125			
Ethylbenzene	0.92	0.050	1.000	0	92.3	80.7	127			
Xylenes, Total	2.8	0.10	3.000	0	94.1	81.6	129			
Surr: 4-Bromofluorobenzene	0.87		1.000		86.6	80	120			

Qualifiers:

- * Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- S % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
- P Sample pH Not In Range
- RL Reporting Detection Limit
- W Sample container temperature is out of limit as specified

Page 5 of 5



Hall Environmental Analysis Laboratory 4901 Hawkins NE Albuquerque, NM 87109

Sample Log-In Check List

TEL: 505-345-3975 FAX: 505-345-4107 Website: www.hallenvironmental.com BLAGG Work Order Number: 1712003 RcptNo: 1 Client Name: Received By: Sophia Campuzano 12/1/2017 7:08:00 AM anne Am Completed By: Anne Thorne 12/1/2017 7:54:28 AM 12/01/17 DDS Reviewed By: Chain of Custody No 🗌 Not Present V 1. Custody seals intact on sample bottles? Yes Ves V No 🗆 Not Present 2. Is Chain of Custody complete? 3. How was the sample delivered? Courier Log In No 🗌 NA 🗌 Yes V 4. Was an attempt made to cool the samples? 5. Were all samples received at a temperature of >0° C to 6.0°C Yes 🗸 No 🗌 NA 🗌 No 🗌 6. Sample(s) in proper container(s)? Yes V Yes 🗸 No 🗆 7. Sufficient sample volume for indicated test(s)? No 🗌 8. Are samples (except VOA and ONG) properly preserved? No V NA 🗌 9. Was preservative added to bottles? No VOA Vials No 🗌 10. VOA vials have zero headspace? Yes No 🗸 11. Were any sample containers received broken? # of preserved bottles checked for pH: No 🗌 12. Does paperwork match bottle labels? (<2 or >12 unless noted) (Note discrepancies on chain of custody) Adjusted? No 🗌 13. Are matrices correctly identified on Chain of Custody? No 🗌 Yes V 14. Is it clear what analyses were requested? Checked by: No 🗌 15. Were all holding times able to be met? Yes V (If no, notify customer for authorization.) Special Handling (if applicable) 16. Was client notified of all discrepancies with this order? NA V Yes No 🗌 Person Notified: Date [☐ eMail ☐ Phone ☐ Fax ☐ In Person By Whom: Regarding: Client Instructions: 17. Additional remarks: 18. Cooler Information

Seal Date

2.1

Cooler No Temp °C Condition Seal Intact Seal No

Good



