Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

NMSF-079522

Do not use this form for proposals abandoned well. Use Form 3160-3				
SUBMIT IN TRIPLICATE - Other in	nstructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well X Gas Well Other	8. Well Name and No. San Juan 28-5 Unit 71			
2. Name of Operator Hilcorp Energy Comp	pany	9. API Well No. 30-039-20037		
3a. Address PO Box 4700, Farmington, NM 87499	3b. Phone No. (include area code) 505-599-3400	10. Field and Pool or Exploratory Area Basin Dakota		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit B (NWNE), 835' FNL & 1525'	FEL, Sec. 34, T28N, R05W	11. Country or Parish, State Rio Arriba , New Mexico		
12. CHECK THE APPROPRIATE BOX(ES	S) TO INDICATE NATURE OF NO	TICE, REPORT OR OTHER DATA		
TYPE OF SUBMISSION	TION			
Notice of Intent Acidize Alter Casing Subsequent Report Casing Repair	Fracture Treat	Production (Start/Resume) Reclamation Water Shut-Off Well Integrity Recomplete X Other		
X Final Abandonment Notice Change Plans Convert to Injection	= =	emporarily Abandon FAN Water Disposal		
13. Describe Proposed or Completed Operation: Clearly state all pertinent de If the proposal is to deepen directionally or recomplete horizontally, giv Attach the bond under which the work will be performed or provide the following completion of the involved operations. If the operation result Testing has been completed. Final Abandonment Notices must be filed determined that the site is ready for final inspection.) The subject well was P&A'd on 12/29/05. Reclamation approval. The location was inspected and pass	re subsurface locations and measured and tre Bond No. on file with BLM/BIA. Require ts in a multiple completion or recompletion only after all requirements, including recla mation was completed and the on 1/19/2018 with Bob Switze	the vertical depths of all pertinent markers and zones. In disubsequent reports must be filed within 30 days in a new interval, a Form 3160-4 must be filed once imation, have been completed and the operator has be location is now ready for final closure		
remove this well from the Hilcorp Energy Comp	-			
	OIL CONS. DIV DIST.	B JAN 29 2013		
	2 2018	Farmington Field Office Bureau of Land Management		

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Etta Trujillo

Title Operations/Regulatory Technician Sr

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RCC Reclamation Comple	tio	n		Location Names SAN JINA 200	Æ.		
AP#: 30 + 03 9 - 20037		Location Name: SAN JUAN 28-5 71 UL-Sec-Twn-Rng: "B" 728N R5W Sec 34 Leasett SF-579522 Twin/Co-Locate Well Name & Operator:			Date: 1-19-2018 Revision 2 (3/7/17)		
Surface Owner: BLM			Leasett SE CES			Lat/Long: 36.62259, -107, 34221	
Pipeline Owner:				Twin/Co-Pageto Well No.			County/State: Kio ARKIBA NW
Qualta	Ap	PHC	, The	orbr: Operator:			
Disue: Eric Smith	1.0		712	Contractor:			Seed Mix:
Interim Reclamation	Completed	Incomplete	N/A.		Completed	Incomplete N/A	Remediation NA
Have pli sample results been approved	I_	\Box		3rd party pipeline removed	 		Essiliation de la Constitución d
Has water been removed from pit	4_	<u> </u>	 	Anchors removed .	1		Facilities stripped
Have pit marker photos been taken	1_	<u> </u>	Ш	Equipment and piping removed	1		Certificate of waste issued & approved
Has certificate of waste been issued & approved	4_	ـــ	 	Power poles removed	1	+-	Depth:
Have all pit contents been removed	4—	╙	Ш	Cathodic protection removed	17		Length:
Has semple after content removal been taken	4-	 _	┦	Vegetative cages removed	1	\dashv	
Is location contoured	4_	—	\sqcup	CMP ^a removed	ント		Date of Excavation Start: Date of Excavation End:
Is there 4' of cover over pit	╀~	L.	\sqcup	Non native gravel buried or removed	 	- 2	Date of Excavation End:
Has top soil been spread evenly	┦—	ــــ	Ш	Noxious weeds removed or sprayed	-	1	Date of Backill End:
Has all non-native gravel been buried or removed	╃—	<u> </u>	Ш	Insvasive weeds removed or sprayed	_	ΤĎ	Yards Hauled Out:
Has pit liner been removed Has all trash been removed	4—	<u> </u>	ш	Contouring complete	7	- -	Impacted Soil Hauled To:
Have all weeds been removed	╁—	Ь	ш	Top soll spread	//		Yards Haufed In:
	ـــ	<u> </u>	-	Diversions clean and functional	7 /	╌┼╌┤	Fresh Soil Hauled in From:
Teardrop allows vehicle access to all facilities	-	├	\vdash	Silt trap clean and functional	. /-	\dashv	Approval to backfill
Drainage ditches allow adequate run off		<u> </u>	\vdash	Cattle guard / gates removed	7	╅┤	
All non-traffic areas disked properly	-	<u> </u>	Ш	Cellar / mouse hole covered	./ -	$\dashv\dashv$	Back (III mechanically compacted Facilities reset
All non-traffic areas seeded	4—	<u> </u>	Ш	Erosion under control	\(\)	+	Trash and debri removed
Seeded areas have been mulched	 		Ш	Location properly ripped	:/ -	$\dashv\dashv$	Close Out Completed
Noxious weeds have been removed or sprayed	↓_	Щ	Ш	Location properly disked	'/ .	┯┥	
Invasive weeds have been removed or sprayed			LLI.	Location seeded	"		Soil Removal Sundry Ready to be Filed
Barriers set to deter traffic				Photo transect installed	√ /-	-1-1	
Silt traps are functional			П	Access road properly closed	-//	44	
Culverts are functional			П	Public use controlled	<u> </u>	44	
Upper diversion is functional	7			Barriers in place	<u> </u>	44	
Have wellhead cages and Jersey barriers been removed	7	\Box		Grazing controlled	4	44	
Have reclamation pictures been taken	1-		\vdash	P&A marker installed & legible	V/		
Growth at least 70%	T^-	Г	\vdash	Well sign removed	<u> </u>		
Agency Inspection Date:	1	 	\vdash	Growth at least 70%	V		
Sundry is ready to file	+-	Ι-	\vdash	Trash and debris removed from location	V.	\Box	
	+		H	Final reclamation photos taken	V	\sqcap	
	+	 	\vdash		71	\top	
	+-	Ι	\vdash	Agency Inspection Date:	_	1	
Comments:	ــــــــــــــــــــــــــــــــــــــ		Щ	FAN Ready to be filed	Z	+-1	
-				Comments: Subnit fan	<u> </u>		Comments:
₹.				·			
1							
				· · · · · · · · · · · · · · · · · · ·			<u></u>

,