Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

NM-04224

5. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. Field Office 7. If Unit DECK Approprient, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Quitzau 7 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-045-05503 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4700, Farmington, NM 87499 505-599-3400 **Ballard Pictured Cliffs** 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Surface Unit D (NWNW), 1284' FNL & 1284' FWL, Sec . 10, T25N, R8W San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Notice of Intent Acidize Production (Start/Resume) Deepen Well Integrity Alter Casing Fracture Treat Reclamation Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon FAN X Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) The subject well was P&A'd on 6/23/2010. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and passed on 1/25/2018 with Bob Switzer. Please remove this well from the Hilcorp Energy Company bond. IL COMS. DIV DIST. 3
FEB 09 2018 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Christine Brock** Operations/Regulatory Technician vistine Larock Date 1/29/2018 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify Office that the applicant holds legal or equitable title to those rights in the subject lease which would

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Instruction on page 2)

entitle the applicant to conduct operations thereon.

NMOCDV

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any

RCC Reclamation Completion		UL-Sec-Twn-Rng: "D" T 25H RBW Secio			Date: /- 25-2018 Revision 2 (377/17)		
AP#: 30-045-05503					Lat/Long: 36 4/867 -107, 67334 County/State: SAM JOHN NM		
Surface Owner: BLM		Lease# NM -04224			County/State: SAm JOHN NM		
Pipeline Owner:		Twin/Co-Locate Well Name & Operator:					
Onsite: Januar Agency Inspe					Seed Mix:		
Interim Reclamation	Completed Incomplete	Final Reclamation	Completed Incomplete	N/A	Remediation B	Incomplete	S
Have pil sample results been approved	+ + + + + + + + + + + + + + + + + + + +	3rd party pipeline removed	17	1	Facilities stripped		7
Has water been removed from pit	 	Anchors removed	1	\top	Certificate of waste issued & approved		_
Have pit marker photos been taken	 	Equipment and piping removed	12	\top	Depth:	\vdash	┥.
Has certificate of waste been Issued & approved	 	Power poles removed	 " 		Width:		_
Have all pit contents been removed	 	Cathodic protection removed	+		Length:	\vdash	_
Has sample after content removal been taken	1 1 1	Vegetative cages removed	100	+*	Date of Excavation Start:	 	7
s location contoured	1 	CMP's removed	1: 1	ᆟ	Date of Excavation End:	 	_
is there 4' of cover over pit	 - 	Non native gravet buried or removed		14	Date of Backfill Start:	 	
Has top soil been spread evenly	 -	Noxious weeds removed or sprayed	12	1-1	Date of Backill End;	+-+	\dashv
Has all non-native gravel been buried or removed	 	Insvasive weeds removed or sprayed	10	+	Yards Hauled Out:	+-+	-
Has all liner been removed	1 	Contouring complete	151	+	Impacted Soil Hauled To:	++	
Has all trash been removed	1-1-1-	Top soll spread		1-	Yerds Hauled In:	+	\dashv
Have all weeds been removed	 	Diversions clean and functional	1	+	Fresh Soil Hauled in From:	╁╼╌┼╴	-
Teardrop allows vehicle access to all facilities	╿┈╿╼╍╏╍╸	Silt trap clean and functional	 	╅┪	Approval to backfill	+	\dashv
Drainage dilches allow adequate run off	╂┈╂═╌┠═╌	Cattle guard / gates removed	 	14	Back fill mechanically compacted	╁╼╁╴	→
All non-traffic areas disked properly	 - - 	Celler / mouse hole covered	19	╌	Facilities reset	┿	
	 - 		<u> </u>	+		┿	-
All non-traffic areas seaded	 	Erosion under control	10	4-4	Trash and debri removed	++	
Seeded areas have been mulched	1	Location properly ripped	<u></u>		Close Out Completed	 	_
Noxious weeds have been removed or sprayed		Location properly disked	V	1-	Soll Removal Sundry Ready to be Filed	\bot	
nvasive weeds have been removed or sprayed	<u> </u>	Location seeded .	V	L			
Barriers set to deter traffic		Photo transect installed		V		T	1
Silt traps are functional		Access road properly closed	V	\top		\Box	
Culverta are functional		Public use controlled	V	1			
Upper diversion is functional	 	Barriers in place	1	77		+	
Have wellhead cages and Jersey barders been removed	1-1-1	Grazing controlled	1.4	+-1		+++	\dashv
Have reclamation pictures been taken	 	P&A marker installed & legible	10	┿┥		+-+	
Have reciamation pictures been taken Growth at least 70%	┿╅	Well sign removed				+++	
	 		-	4	 	+	-
Agency Inspection Date:	4 - 1 -	Growth at least 70%	14	4-4		┿	,
Sundry is ready to file	 	Trash and debris removed from location	14	4		4	_
<u></u>		Final reclamation photos taken	1/	┷		44	
		Agency Inspection Date: 1-25-2018	1/]
		FAN Ready to be filed					
Comments:		Comments:			Comments:		
							- 1
		SUBMIT FAN					