Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

AM 5 Lease Seria

NMSF-077382

Farmington Field Office SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an of Land Management abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well 8. Well Name and No. Other Hargrave A 3 2. Name of Operator 9. API Well No. 30-045-06558 Hilcorp Energy Company 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4700, Farmington, NM 87499 505-599-3400 **Kutz Pictured Cliffs** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Unit B (NWNE), 990' FNL & 1650' FEL, Sec . 16, T27N, R10W San Juan **New Mexico** Surface 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Notice of Intent Acidize Deepen Production (Start/Resume) Well Integrity Alter Casing Fracture Treat Reclamation New Construction Subsequent Report Casing Repair Recomplete Other FAN Change Plans Plug and Abandon Temporarily Abandon X Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) The subject well was P&A'd on 3/5/2004. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and passed on 1/23/2018 with Bob Switzer. Please remove this well from the Hilcorp Energy Company bond. OIL COMS. DIV DIST. 3 FEB 09 2018 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Signature Little Coperations/Regulatory Technician

Date 1/29/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Leting Title Supv NRS Date 2/2/2018

Conditions of approval, if any, are anached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)



RCC Reclamation Completion				Location Name: HARGRAVE A3				Date: 1-23-2018 Revision 2 (3/7/17)		
API#: 30-045-06558				UL-Sec-Twn-Rng: "B" T27H RIDW Sec. 16				LattLong: 36. 579766 -107. 89691		
Surface Owner: BLm				UL-Sec-Twn-Rng: B"T27H 1 10W Sec.16 Lease# SF- 077382				County/State: SMN JUAN NM		
				Twin/Co-Locate Well Name & Operator:	,		7			
	Age	ису	Lusp	Contractor:				Seed Mix:		1
Interim Reclamation	Completed	Incomplete	WA	Final Reclamation	Completed	Incomplete	¥Z	Remediation	Completed Incomplete	
Have pit sample results been approved			Н	3rd party pipeline removed	7		\neg	Facilities stripped		7
Has water been removed from pit			П	Anchors removed	4		╗	Certificate of waste issued & approved		٦
Have pit marker photos been taken			П	Equipment and piping removed	1		7	Depth:		7
Has certificate of waste been issued & approved			П	Power poles removed		П		Width:		7
Have all pit contents been removed				Calhodic protection removed	امر			Length:		_1
Has sample after content removal been taken		Г		Vegetative cages removed			~	Date of Excavation Start:		1
is location contoured				CMP's removed	П			Date of Excavation End:		٦
is there 4' of cover over pit			П	Non native gravel buried or removed	1		\neg	Date of Backfill Start:		٦
Has top soil been spread evenly				Noxious weeds removed or sprayed	1,0		\neg	Date of Backfill End:		7
Has all non-native gravel been buried or removed			П	Insvasive weeds removed or sprayed	1		\neg	Yards Hauled Out:		ヿ
Has pil liner been removed			М	Contouring complete	4	П	╗	Impacted Soil Hauled To:	-	
Has all trash been removed	П		П	Top soil spread	V		┑	Yards Hauled In:		7
Have all weeds been removed			П	Diversions clean and functional	V	П	┪	Fresh Soil Hauled in From:	· -	7
Teardrop allows vehicle access to all facilities	_		П	Sill trap clean and functional	1.0		7	Approval to backfill		ヿ゙
Drainage ditches allow adequate run off				Cattle guard / gates removed	10-	-	7	Back (ill mechanically compacted		7
All non-traffic areas disked property			Н	Cellar / mouse hole covered	1		~	Facilities reset		ヿ
All non-traffic areas seeded	\vdash	_	Н	Erosion under control	u	-	一1	Trash and debri removed		\dashv
Seeded areas have been mulched		_	Н	Location properly ripped	1./		ᅦ	Close Out Completed		1
Noxious weeds have been removed or sprayed	 	÷	Н	Location properly disked	۳.		┨	Soil Removal Sundry Ready to be Filed	 	-
Invasive weeds have been removed or sprayed			Н	Location seeded .	14	╌┤	⊣	Total Carrell, House, to bo , god	 - -	-1
Barriers set to deler traffic	 -	H	Н	Photo transect installed	1	Н	7			-1
	_		Ш		1	 	_			
Sill treps are functional			Ш	Access road properly closed	V		4			-
Culverts are functional	_	·	Ш	Public use controlled	10	\square	_			_
Upper diversion is functional	L		Ш	Barriers in place	1		_		$\sqcup \bot \bot$	_
Have wellhead cages and lersey barriers been removed		:	Ш	Grazing controlled	10	Ш			<u> </u>	
Have reclamation pictures been taken				P&A marker installed & legible	V		╝			╝
Growth at least 70%				Well sign removed	1					
Agency Inspection Date:			\Box	Growth at least 70%	V		\neg			\neg
Sundry is ready to file	Γ	\Box		Trash and debris removed from location	10		\neg			ヿ
	T	·	М	Final reclamation photos taken	1	1	⇥			7
· · · · · · · · · · · · · · · · · · ·		_	H	Agency Inspection Date: 1 2 5 2015	V	 - -	ᅱ		 	7
		┢	H	FAN Ready to be filed	1	┢┈┤	ᅱ		 	\dashv
Comments:	ـــــا	Ц	-		LK.	ш		Comments:	1	\dashv
		:		SUBMIT FAM						

)