



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

JAN 02 2018

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5.17.17 Operator BP America Production Company API # 3004523064

Property Name MUDGE LS 007A-MV Location: Unit C Section 23 Township 31 Range 11
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 17.1 Intermediate N/A Casing 35.9 Bradenhead 36.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>-0.1</u>	<u>38.4</u>				Steady Flow	<u>30 sec.</u>
10 minutes	<u>0.0</u>	<u>38.9</u>				Surges	
15 minutes	<u>0.0</u>	<u>38.8</u>				Down to Nothing	<u>In 17 sec.</u>
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 13.3 Intermediate N/A

REMARKS:

Compressor on site, took gas samples on BH, casing, + tubing
before test. ~~at~~ Compressor pulling well down 12 minutes into test.

By Eugenia Hamilton
Lead Tech.

(Position)

Witness _____