



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/3rdistrict.htm](http://emrdd.state.nm.us/ocd/District%20III/3rdistrict.htm)

NMOCB

MAR 09 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3/9/2018 Operator Hilcorp API #30-045-24475

Property Name San Juan 30-6 Unit Com Well No. 467 Location: Unit M Section 22 Township 30 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	5	9		
10 min	0		8		
15 min	0		9		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing	X		
Nothing			
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Bit through 1/2" opening, down to nothing 1 sec

By SLA

Witness James D. Kelly

(Position)

E-mail address _____