

**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONS. DIV DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

JAN 02 2018

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7.14.17	Operator	BP America Production Company	API #	3004526798
--------------	---------	----------	-------------------------------	-------	------------

Property Name DAVIS 001-PC **Location:** Unit E Section 23 Township 32 Range 11
 (Well Name and Number)

Pressure (Shut-in or Producing) Tubing N/A Intermediate N/A Casing 9.8 Bradenhead 34.9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	Ø	9.8	N/A	N/A	N/A	Steady Flow	1 min 20 sec	N/A
10 minutes	Ø	9.7				Surges		
15 minutes	Ø	9.7				Down to Nothing	48 sec.	
20 minutes						No Flow	nothing after	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

REMARKS: Took samples from bradenhead & casing, casing flowing, slim hole setup.

By Eugenia Hami Hon
Lead Tech.

Witness

(Position)

NMOCD Test Area: A

260