

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

	NMOCD
	HEAD TEST REPORT1 copy to above address)MAR 0 7 2018
Date of Test 3/7/2018 Operator Enduring Resources API #30-045-28542167 111 28792 Property Name Alberting 3 Well No. 2 Location: Unit Section 3 Township3 (Range 3	
Property Name Alberting 3 Well No. 2 Location: Unit Section 3 Township 3 [ Range ] 3	
Well Status(Shut-In or Producing) Initial PSI: Tubing 4 Intermediate NA Casing 1 Bradenhead 3.1	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg TIME D II 10 min D II	TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE Steady Flow Surges
15 min 0 1 1 1 1 1 20 min 25 min 30 min 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Down to Nothing
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEARFRESHSALTYSULFURBLACK 5 MINUTE SHUT-IN PRESSURE BRADENHEADINTERMEDIATE_NA REMARKS: BH_through /4 value, blew down in 2min,	
By	

\*