

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

MAR 09 2010

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

5. Lease Serial No. **NM-05791**

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

7. If Unit of CA/Agreement; Name and/or No.

8. Well Name and No.

Graham B WN Fed 6

2. Name of Operator

Hilcorp Energy Company

9. API Well No.

30-045-20360

3a. Address

PO Box 4700, Farmington, NM 87499

3b. Phone No. (include area code)

505-599-3400

10. Field and Pool or Exploratory Area

South Blanco Pictured Cliffs

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit N (SESW), 850' FSL & 1600' FWL, Sec. 3, T27N, R8W

11. Country or Parish, State

San Juan New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☐ Acidize

☐ Deepen

☐ Production (Start/Resume)

☐ Water Shut-Off

☐ Subsequent Report

☐ Alter Casing

☐ Fracture Treat

☐ Reclamation

☐ Well Integrity

☐ Casing Repair

☐ New Construction

☐ Recomplete

☒ Other

☐ Change Plans

☐ Plug and Abandon

☐ Temporarily Abandon

FAN

☒ Final Abandonment Notice

☐ Convert to Injection

☐ Plug Back

☐ Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 11/06/2002. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and passed on 3/08/2018 with Bob Switzer. Please remove this well from the Hilcorp Energy Company bond.

NMOC

MAR 22 2018

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Christine Brock

Title **Operations/Regulatory Technician**

Signature

Christine Brock

Date **3/9/2018**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Supv NRS

Title

Supv NRS

Date

3/16/18

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

KA

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOC

RCC Reclamation Completion			Location Name: GRAHAM BURN FEDERAL #6		Date: 3-8-2018	Revision 2 (3/7/17)	
API#: 30-045-20360			UL-Sec-Twn-Rng: N T27N R8W Sec 3		Lat/Long: 36.5983 -107.67159		
Surface Owner: BLM			Lease#: NM-05791		County/State: SAN JUAN NEW MEXICO		
Pipeline Owner: ENTERPRISE			Twirl/Co-Locate Well Name & Operator:				
Onsite: Sam Towner			Agency Inspector: Bob Swain		Contractor:		Seed Mbs:
Interim Reclamation			Final Reclamation			Remediation	
Have pit sample results been approved	Completed	Incomplete	3rd party pipelines removed	Completed	Incomplete	Facilities stripped	Completed
Has water been removed from pit			Anchors removed			Certificate of waste issued & approved	
Have pit marker photos been taken			Equipment and piping removed			Depth:	
Has certificate of waste been issued & approved			Power poles removed			Width:	
Have all pit contents been removed			Cathodic protection removed			Length:	
Has sample after content removal been taken			Vegetative cages removed			Date of Excavation Start:	
Is location contoured			CMP's removed			Date of Excavation End:	
Is there 4' of cover over pit			Non native gravel buried or removed			Date of Backfill Start:	
Has top soil been spread evenly			Noxious weeds removed or sprayed			Date of Backfill End:	
Has all non-native gravel been buried or removed			Invasive weeds removed or sprayed			Yards Hauled Out:	
Has pit liner been removed			Contouring complete			Impacted Soil Hauled To:	
Has all trash been removed			Top soil spread			Yards Hauled In:	
Have all weeds been removed			Diversions clean and functional			Fresh Soil Hauled In From:	
Teardrop allows vehicle access to all facilities			Silt trap clean and functional			Approval to backfill	
Drainage ditches allow adequate run off			Cattle guard / gates removed			Back fill mechanically compacted	
All non-traffic areas disked properly			Cellar / mouse hole covered			Facilities reset	
All non-traffic areas seeded			Erosion under control			Trash and debris removed	
Seeded areas have been mulched			Location properly ripped			Close Out Completed	
Noxious weeds have been removed or sprayed			Location properly disked			Soil Removal Sundry Ready to be Filed	
Invasive weeds have been removed or sprayed			Location seeded				
Barriers set to deter traffic			Photo transect installed				
Silt traps are functional			Access road properly closed				
Culverts are functional			Public use controlled				
Upper diversion is functional			Barriers in place				
Have wellhead cages and jersey barriers been removed			Grazing controlled				
Have reclamation pictures been taken			P&A marker installed & legible				
Growth at least 70%			Well sign removed				
Agency Inspection Date:			Growth at least 70%				
Sundry is ready to file			Trash and debris removed from location				
			Final reclamation photos taken				
			Agency Inspection Date: 3-8-2018				
			FAN Ready to be filed				
Comments:			Comments:			Comments:	
			WELL MARKER IS BELOW SURFACE UNAVAILABLE FOR PHOTOS				