



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-22-18 Operator Enduring Res. API #30-0 45-24392
Property Name CudonCom SWD Well No. 1 Location: Unit 27 Township 32 Range 13
Well Status(Shut-In or Producing) Initial PSI: Tubing 1550 Intermediate 59 Casing 05 Bradenhead 0.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0	59	-5	0	-4
10 min	0	59	-4	0	-4
15 min	0	59	-4	0	-4
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS: BH- nothing when opened. Nothing when
opened after 5 min shut in. Int- dead at 30 seconds.
Nothing when opened after 5 min shut in.

By [Signature]

Witness Monica Calkins

(Position)

E-mail address _____

requesting gas analysis
int. if you can get anything
of 68 Prod. Casing

NMDCO
MAR 22 2018
DISTRICT III