



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 3-13-18 Operator EM DURAN R6 SOURCE API # 30-045-33438

Property Name CHARGE Well No. H2-3 Location: Unit Section 2 Township 31N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 2.6 Intermediate N/A Casing 7.5 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH



FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

DOWN TO ZERO in 1 min.

By [Signature]

Witness

AIR QUALITY SPECIALIST
(Position)

E-mail address Sbarrett@enduringresources.com

NMOCD

122 2018

DISTRICT III