

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test_ 2-ADN-2013 Operator_ ENCANA API #30-0 45- 35487
Property Name Good TIMB Well No. 30 / H Location: Unit Section 7 Township 24 Range 9
Well Status(Shut-In or Producing) Initial PSI: Tubing 77 Intermediate MACasing 80 Bradenhead
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE FLOW CHARACTERISTICS Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE BH Int Csg Int Csg
TIME 5 min
Water If bradenhead flowed water, check all of the descriptions that apply below:
CLEAR FRESH SALTY SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O. INTERMEDIATE MA
REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.
AND MAR
By Kary James Witness Muly Witness
(Position) NMOCD
E-mail address