

(Position)

E-mail address

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ood/District M/3distric.htm

NMOCD

BRADENHEAD TEST REPORT

APR 1 8 2018

			t 1 copy to above		DISTRICT III
Date of Test_	4-12-1	Opera	tor ENCANO	API #	#30-0 45-35525
Date of Test 4-12-18 Operator <u>ENCANA</u> API #30-0 45-35525 Property Name <u>Lybrook 0-35</u> Well No. <u>O/H</u> Location: Unit O Section 35 Township 33 NRange 8W					
Well Status(S' lut-In or Producing) Initial PSI: Tubing 81 Intermediate 11/A Casing 102 Bradenhead					
OPEN BR ADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
Testing BH	PRESSU Bradenhead Int Csg	RE INTERM Int Csg			ARACTERISTICS INTERMEDIATE
TIME 5 min .	N/A 102	//	Steady Flow_		
10 min	1 100	1//	Surges		IV/
15 min 0	- 100	1	Down to Noth	ing	1/1
20 min			Nothing	X	
25 min	11/4		Gas		
30 min	W/A	/ /	Gas & Water	Additional to the second secon	
/			Water		<u> </u>
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE					
REMARKS: Brokenhead had pothing- 109+ Shut					
By Tvthur Sullivan Witness					