



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3district.htm>

NMOC

APR 18 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 4-17-18 Operator ENCANA API #30-0 45-35527

Property Name Lybrook M-35 Well No. 02H Location: Unit M Section 35 Township 23N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 46 Intermediate 115 Casing 128 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME					
5 min	<u>0</u>	<u>115</u>	<u>125</u>	<u>115</u>	<u>125</u>
10 min	<u>0</u>	<u>115</u>	<u>130</u>	<u>115</u>	<u>130</u>
15 min	<u>0</u>	<u>115</u>	<u>128</u>	<u>115</u>	<u>128</u>
20 min					
25 min					
30 min		<u>115</u>			

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 115

REMARKS:

Nothing on Bradenhead - Left Shut

By

Art Sullivan

Witness

(Position)

E-mail address