Submit 1 Copy To Appropriate District	1001100110011003-6161Energy, Minerals and Natural Resources100512201003-617812201003-617812201003-6178Santa Fe1003-6178Santa Fe </th <th>Form C-103 Revised July 18, 2013</th>		Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-045-07678
811 S. First St., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Salita PC, INW 67	505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		7. Lease Name or Unit Agreement Name	
			Gallegos Canyon Unit 8. Well Number
		189	
2. Name of Operator BP America Production Company- L48			9. OGRID Number 000778
3. Address of Operator			10. Pool name or Wildcat
1515 Arapahoe St, Tower 1 Suite 700			
Denver, CO 80202			Basin Dakota
4. Well Location Unit Letter E : 2480 feet from the North line and 1160 feet from the West line			
Section 36 Township 29N Range 13W NMPM San Juan County			
Section     So     Foundation       11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
5685'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR			K ALTERING CASING
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB []
CLOSED-LOOP SYSTEM			
OTHER:	lated assesstings (Classic state all	OTHER:	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>			
DISTRICT 1/1			
Please see the attached P&A operations performed on the subject well April 2018			
Approved for plugging of wellbore only.			
F	Receipt of C-103 (Subsequent Report	of Well	0 3 8 W N
11/14/1064 n	Plugging) which may be found @ OCI age under forms	D web	
	www.emnrd.state.us/ocd		
FNB ONLY			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE LOLA COL- TITLE Regulatory Analyst DATE 4/26/2018			
Type or print name Toya Colvin E-mail address: Toya.Colvin@bp.com PHONE: 281-892-5369			
For State Use Only			
APPROVED BY: Bracker	TITLE Deput	y Oil & Gas In District #3	
Conditions of Approval (if any):	PV -		

# **BP America**

## Plug And Abandonment End Of Well Report

## GCU 189

### 2480' FNL & 1160' FWL, Section 36, T29N, R13W

San Juan County, NM / API 30-045-07678

### **Work Summary:**

- 4/16/18 Made BLM, and NMOCD P&A operations notifications at 9:00 AM MST.
- **4/17/18** MOL and R/U P&A unit. Checked well pressures: Tubing: 0 psi, Casing: 550 psi, Bradenhead: 0 psi. Bled down well. N/D wellhead and N/U BOP and function tested. TOH tallying production string. P/U casing scraper and TIH above top perforation at 6072'. Dropped standing valve and pressure tested tubing to 1000 psi in which it successfully held pressure. Retrieved standing valve and TOH to surface and L/D casing scraper. Shut-in well for the day.
- **4/18/18** Checked well pressures: Tubing 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. P/U CR, TIH and set at 6022'. Circulated hole clean with 65 bbls of fresh water. Pressure tested casing to 800 psi in which it failed to hold pressure. TOH with tubing and L/D stinger nose. R/U wireline services. Ran CBL from CR at 6022' to surface. CBL was sent to NMOCD office for review. R/D wireline. TIH with cementing sub to 6022'. Shut-in well for the day. Ready to start cementing services 4-19-18. Thomas Vermersch was NMOCD inspector on location.
- 4/19/18 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. R/U cementing services. Pumped Plug #1: (Dakota Perforations and Formation Top 6022'-5863', 10 Sacks Class G Cement) Mixed 10 sx Class G cement and spotted a balanced plug to cover Dakota perforations and formation top. WOC 4 hours. TIH and tagged plug #1 top at 5863'. R/U cementing services. Pumped Plug #2: (Gallup Formation Top 5228'-5011', 12 Sacks Class G Cement)

Mixed 12 sx Class G cement and spotted a balanced plug to cover Gallup formation top. WOC 4 hours. TIH and tagged plug #2 top at 5011'. R/U cementing services. **Pumped Plug #3:** (Mancos Formation Top 4310'-4060', 16 Sacks Class G Cement) Mixed 16 sx Class G cement and spotted a balanced plug to cover Mancos formation top. WOC overnight. Shut-in well for the day. Thomas Vermersh was NMOCD inspector on location.

4/20/18 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. TIH and tagged plug #3 top at 4060'. Pressure tested casing to 800 psi in which it failed to hold pressure. Pumped Plug #4: (Mesa Verde and Chacra Formation Tops 3130'-2400', 69 Sacks Class G Cement) Mixed 69 sx Class G cement and spotted a balanced plug to cover Mesa Verde and Chacra formation tops. WOC 4 hours. TIH and tagged plug #4 top at 2472'. Pressure tested casing to 800 psi in which it successfully held pressure. R/U cementing services and topped off plug #4 from 2472'-2400'. Pumped Plug #5: (Pictured Cliffs Formation Top 1547'-1400', 12 Sacks Class G Cement) Mixed 12 sx Class G cement and spotted a balanced plug to cover Pictured Cliffs formation top. PUH. Pumped Plug #6: (Fruitland and Kirtland Formation Tops 1194'-670', 42 Sacks Class G Cement) Mixed 42 sx of Class G cement and spotted a balanced plug to cover Fruitland and Kirtland formation tops. POOH. R/U wireline services. RIH and perforated squeeze holes at 570'. P/U CR, TIH and set at 538'. Stung into CR and attempted to establish injection rate but was unsuccessful. R/U cementing services. Pumped Plug #7: (Ojo Alamo Formation Top 570'-300', 19 Sacks Class G Cement) Mixed 19 sx of Class G cement and spotted a balanced plug to cover Ojo Alamo formation top. POOH. Pressure tested Bradenhead to 300 psi in which it failed to hold pressure. R/U wireline services. RIH and perforated squeeze holes at 100'. Attempted to establish injection rate but was unsuccessful. R/U cementing services. Pumped Plug #8: (Surface Shoe 100'-surface, 50 Sacks Class G Cement, 35 Sacks for top-off). N/D BOP and cut-off wellhead. Installed P&A marker per BLM and NMOCD standards. Shut-in well for the day. Thomas Vermersh was NMOCD inspector on location. Top-off well 4-23-18.

**4/23/18** Ran weighted tally tape down surface casing and tagged cement 40' down. RIH with ¾" poly pipe. R/U cementing services. Pumped 35 sx of Class G cement down ¾" poly pipe from 40' to surface and topped off well. Took picture of P&A marker in place and recorded its location via GPS coordinates. Thomas Vermersh was NMOCD inspector on location.

# Wellbore Diagram

Gallegos Canyon Unit 189 API #: 3004507678 San Juan, New Mexico

#### Plug 8

#### Surface Casing

8.625" 24# @ 348 ft

100 feet - Surface 100 feet plug 50 sacks of Class G Cement 35 sacks of cement for top off

<u>Plug 7</u> 570 feet - 300 feet 270 feet plug 19 sacks of Class G Cement

<u>Plug 6</u> 1194 feet - 670 feet 524 feet plug 42 sacks of Class G Cement

<u>Plug 5</u> 1547 feet - 1400 feet 147 feet plug 12 sacks of Class G Cement

<u>Plug 4</u> 3130 feet - 2400 feet 730 feet plug 69 sacks of Class G Cement

<u>Plug 3</u> 4310 feet - 4060 feet 250 feet plug 16 sacks of Class G Cement

<u>Plug 2</u> 5228 feet - 5011 feet 217 feet plug 12 sacks of Class G Cement

<u>Plug 1</u> 6022 feet - 5863 feet 159 feet plug 10 sacks of Class G Cement

> <u>Perforations</u> 6072 feet - 6092 feet 6154 feet - 6210 feet

Formation Pictured Cliffs - 1500 feet MesaVerde - 3080 feet Mancos - 4260 feet Gallup - 5178 feet Dakota - 6150 feet Dakota - 5722 feet

Retainer @ 6022 feet

Production Casing 4.5" 10.5# @ 6260 ft

