



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District II/district.htm](http://emrwd.state.nm.us/ocd/District%20II/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-11-2018 Operator Rim API #30-0 45-29096
Property Name Ropco Well No. 12-1 Location: Unit 5 Section 12 Township 29 Range 13-W
Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate N/A Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	/	6		
10 min	0	/	6		
15 min	0	/	6		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Daryl Wright Witness _____
Lease Operator
(Position)

E-mail address _____

DISTRICT III
MAY 14 2018
NMOC