

RECEIVED

Form 3160-5  
(August 2007)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

APR 27 2018

Farmington Field Office  
Bureau of Land ManagementFORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

2. Name of Operator

Hilcorp Energy Company

3a. Address

PO Box 4700, Farmington, NM 87499

3b. Phone No. (include area code)

505-599-3400

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit P (SESE), 1188' FSL &amp; 218' FEL, Sec. 33, T29N, R9W

5. Lease Serial No.

NM-079947

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Helen Jackson 2M

9. API Well No.

30-045-33919

10. Field and Pool or Exploratory Area

Basin DK/Blanco MV

11. Country or Parish, State

San Juan, New Mexico

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Interim Reclamation
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

**Hilcorp Energy Company conducted a legacy interim reclamation inspection on 4/18/2018 with BLM Inspector Randy McKee and received approval for the reclamation BMPs on the subject well.**

NMOC

MAY 10 2018

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Kandis Roland

Title Operations/Regulatory Technician

Signature

Kandis Roland

Date

4/27/2018

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Sum N. Lee

Title

Sup NRS

Date

5/2/18

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

RFW

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

RCC Reclamation Completion				Location Name: <u>Helen Jackson 2M</u>				Date: <u>4/18/18</u> <small>Revision 3 (3/21/17)</small>									
API#: <u>30-045-33919</u>				UL-Sec-Twn-Rng: <u>D-33-029N-009W</u>				Lat/Long: <u>36.6786 -107.7787</u>									
Surface Owner:				Lease# <u>NM-079947</u>				County/State: <u>San Juan, NM</u>									
Pipeline Owner: <u>ENT</u>				Twin/Co-Locate Well Name & Operator:				Seed Mix:									
Onsite: <u>Eric Smith</u>				Agency Inspector: <u>RM</u>				Contractor: <u>NRE</u>									
Interim Reclamation			Completed	Incomplete	N/A	Final Reclamation			Completed	Incomplete	N/A	Remediation			Completed	Incomplete	N/A
Have pit sample results been approved			<input checked="" type="checkbox"/>			3rd party pipeline removed						Facilities stripped					
Has water been removed from pit			<input checked="" type="checkbox"/>			Anchors removed						Certificate of waste issued & approved					
Have pit marker photos been taken			<input checked="" type="checkbox"/>			Equipment and piping removed						Depth:					
Has certificate of waste been issued & approved			<input checked="" type="checkbox"/>			Power poles removed						Width:					
Have all pit contents been removed			<input checked="" type="checkbox"/>			Cathodic protection removed						Length:					
Has sample after content removal been taken			<input checked="" type="checkbox"/>			Vegetative cages removed						Date of Excavation Start:					
Is location contoured			<input checked="" type="checkbox"/>			CMP's removed						Date of Excavation End:					
Is there 4' of cover over pit			<input checked="" type="checkbox"/>			Non native gravel buried or removed						Date of Backfill Start:					
Has top soil been spread evenly			<input checked="" type="checkbox"/>			Noxious weeds removed or sprayed						Date of Backfill End:					
Has all non-native gravel been buried or removed			<input checked="" type="checkbox"/>			Invasive weeds removed or sprayed						Yards Hauled Out:					
Has pit liner been removed			<input checked="" type="checkbox"/>			Contouring complete						Impacted Soil Hauled To:					
Has all trash been removed			<input checked="" type="checkbox"/>			Top soil spread						Yards Hauled In:					
Have all weeds been removed			<input checked="" type="checkbox"/>			Diversion clean and functional						Fresh Soil Hauled In From:					
Teardrop allows vehicle access to all facilities			<input checked="" type="checkbox"/>			Silt trap clean and functional						Approval to backfill					
Drainage ditches allow adequate run off			<input checked="" type="checkbox"/>			Cattle guard / gates removed						Back fill mechanically compacted					
All non-traffic areas disked properly			<input checked="" type="checkbox"/>			Cellar / mouse hole covered						Facilities reset					
All non-traffic areas seeded			<input checked="" type="checkbox"/>			Erosion under control						Trash and debris removed					
Seeded areas have been mulched			<input checked="" type="checkbox"/>			Location properly ripped						Close Out Completed					
Noxious weeds have been removed or sprayed			<input checked="" type="checkbox"/>			Location properly disked						Soil Removal Sundry Ready to be Filled					
Invasive weeds have been removed or sprayed			<input checked="" type="checkbox"/>			Location seeded											
Barriers set to deter traffic			<input checked="" type="checkbox"/>			Photo transect installed											
Silt traps are functional			<input checked="" type="checkbox"/>			Access road properly closed											
Culverts are functional			<input checked="" type="checkbox"/>			Public use controlled											
Upper diversion is functional			<input checked="" type="checkbox"/>			Barriers in place											
Erosion under control			<input checked="" type="checkbox"/>			Grazing controlled											
Photo transect installed					<input checked="" type="checkbox"/>	P&A marker installed & legible											
Have wellhead cages and jersey barriers been removed			<input checked="" type="checkbox"/>			Well sign removed											
Have reclamation pictures been taken			<input checked="" type="checkbox"/>			Growth at least 70%											
Growth at least 70%			<input checked="" type="checkbox"/>			Trash and debris removed from location											
Agency Inspection Date: <u>4/18/18</u>			<input checked="" type="checkbox"/>			Final reclamation photos taken											
Sundry is ready to file			<input checked="" type="checkbox"/>			Agency Inspection Date:											
						FAN Ready to be filed											
Comments:						Comments:						Comments:					