

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

APR 27 2018

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill on to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Hilcorp Energy Company

3a. Address

PO Box 4700, Farmington, NM 87499

3b. Phone No. (include area code)

505-599-3400

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface Unit E (SWNW), 1695' FNL & 636' FWL, Sec. 28, T29N, R09W

5. Lease Serial No.

SF-080245

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Hamner 2M

9. API Well No.

30-045-33995

10. Field and Pool or Exploratory Area

Basin DK / Blanco MV

11. Country or Parish, State

San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Interim Reclamation
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company conducted a legacy interim reclamation inspection on 4/18/2018 with BLM Inspector Randy McKee and received approval for the reclamation BMPs on the subject well.

NMOCD

MAY 10 2018

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Christine Brock

Title **Operations/Regulatory Technician**

Signature

Christine Brock

Date **4/27/2018**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

[Signature] **Supervisor**

Title

Supervisor

Date

5/7/18

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FFD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD

RCC Reclamation Completion				Location Name: <u>Hamner 2M</u>				Date: <u>4/18/18</u>				Revision 3 (3/21/17)														
API#: <u>30-045-33995</u>				UL-Sec-Twn-Rng: <u>E-28-029N-009W</u>				Lat/Long: <u>36.699 -107.7907</u>																		
Surface Owner:				Lease# <u>SE-080245</u>				County/State: <u>San Juan, NM</u>																		
Pipeline Owner: <u>ENT</u>				Twin/Co-Locate Well Name & Operator:																						
Onsite: <u>Eric Smith</u>				Agency Inspector: <u>RM</u>				Contractor: <u>NRE</u>				Seed Mix: <u>Backlands</u>														
Interim Reclamation				Completed	Incomplete	N/A	Final Reclamation				Completed	Incomplete	N/A	Remediation				Completed	Incomplete	N/A						
Have pit sample results been approved						<input checked="" type="checkbox"/>			3rd party pipeline removed						<input checked="" type="checkbox"/>			Facilities stripped						<input checked="" type="checkbox"/>		
Has water been removed from pit						<input checked="" type="checkbox"/>			Anchors removed						<input checked="" type="checkbox"/>			Certificate of waste issued & approved						<input checked="" type="checkbox"/>		
Have pit marker photos been taken						<input checked="" type="checkbox"/>			Equipment and piping removed						<input checked="" type="checkbox"/>			Depth:						<input checked="" type="checkbox"/>		
Has certificate of waste been issued & approved						<input checked="" type="checkbox"/>			Power poles removed						<input checked="" type="checkbox"/>			Width:						<input checked="" type="checkbox"/>		
Have all pit contents been removed						<input checked="" type="checkbox"/>			Cathodic protection removed						<input checked="" type="checkbox"/>			Length:						<input checked="" type="checkbox"/>		
Has sample after content removal been taken						<input checked="" type="checkbox"/>			Vegetative cages removed						<input checked="" type="checkbox"/>			Date of Excavation Start:						<input checked="" type="checkbox"/>		
Is location contoured						<input checked="" type="checkbox"/>			CMP's removed						<input checked="" type="checkbox"/>			Date of Excavation End:						<input checked="" type="checkbox"/>		
Is there 4' of cover over pit						<input checked="" type="checkbox"/>			Non native gravel buried or removed						<input checked="" type="checkbox"/>			Date of Backfill Start:						<input checked="" type="checkbox"/>		
Has top soil been spread evenly						<input checked="" type="checkbox"/>			Noxious weeds removed or sprayed						<input checked="" type="checkbox"/>			Date of Backfill End:						<input checked="" type="checkbox"/>		
Has all non-native gravel been buried or removed						<input checked="" type="checkbox"/>			Invasive weeds removed or sprayed						<input checked="" type="checkbox"/>			Yards Hauled Out:						<input checked="" type="checkbox"/>		
Has pit liner been removed						<input checked="" type="checkbox"/>			Contouring complete						<input checked="" type="checkbox"/>			Impacted Soil Hauled To:						<input checked="" type="checkbox"/>		
Has all trash been removed						<input checked="" type="checkbox"/>			Top soil spread						<input checked="" type="checkbox"/>			Yards Hauled In:						<input checked="" type="checkbox"/>		
Have all weeds been removed						<input checked="" type="checkbox"/>			Diversion clean and functional						<input checked="" type="checkbox"/>			Fresh Soil Hauled in From:						<input checked="" type="checkbox"/>		
Teardrop allows vehicle access to all facilities						<input checked="" type="checkbox"/>			Silt trap clean and functional						<input checked="" type="checkbox"/>			Approval to backfill						<input checked="" type="checkbox"/>		
Drainage ditches allow adequate run off						<input checked="" type="checkbox"/>			Cattle guard / gates removed						<input checked="" type="checkbox"/>			Back fill mechanically compacted						<input checked="" type="checkbox"/>		
All non-traffic areas disked properly						<input checked="" type="checkbox"/>			Cellar / mouse hole covered						<input checked="" type="checkbox"/>			Facilities reset						<input checked="" type="checkbox"/>		
All non-traffic areas seeded						<input checked="" type="checkbox"/>			Erosion under control						<input checked="" type="checkbox"/>			Trash and debris removed						<input checked="" type="checkbox"/>		
Seeded areas have been mulched						<input checked="" type="checkbox"/>			Location properly ripped						<input checked="" type="checkbox"/>			Close Out Completed						<input checked="" type="checkbox"/>		
Noxious weeds have been removed or sprayed						<input checked="" type="checkbox"/>			Location properly disked						<input checked="" type="checkbox"/>			Soil Removal Sundry Ready to be Filed						<input checked="" type="checkbox"/>		
Invasive weeds have been removed or sprayed						<input checked="" type="checkbox"/>			Location seeded						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Barriers set to deter traffic						<input checked="" type="checkbox"/>			Photo transect installed						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Silt traps are functional						<input checked="" type="checkbox"/>			Access road properly closed						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Culverts are functional						<input checked="" type="checkbox"/>			Public use controlled						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Upper diversion is functional						<input checked="" type="checkbox"/>			Barriers in place						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Erosion under control						<input checked="" type="checkbox"/>			Grazing controlled						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Photo transect installed						<input checked="" type="checkbox"/>			P&A marker installed & legible						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Have wellhead cages and jersey barriers been removed						<input checked="" type="checkbox"/>			Well sign removed						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Have reclamation pictures been taken						<input checked="" type="checkbox"/>			Growth at least 70%						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Growth at least 70%						<input checked="" type="checkbox"/>			Trash and debris removed from location						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Agency Inspection Date: <u>4/18/18</u>						<input checked="" type="checkbox"/>			Final reclamation photos taken						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Sundry is ready to file						<input checked="" type="checkbox"/>			Agency Inspection Date:						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
									FAN Ready to be filed						<input checked="" type="checkbox"/>									<input checked="" type="checkbox"/>		
Comments:									Comments:									Comments:								