



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 31-MAY 2018 Operator HILLTOP API # 30-039-3030

Property Name SAN JUAN 275 Well # 914 Location: Unit 8 Sec 8 Twn 27 Rge 5

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: 1000 PSI CASING, 60 MINUTE LEAK
THE CASING WAS PRESSURED UP TO 600 PSI AND
NO LEAKAGE YET FOR THE ENTIRE TEST

By [Signature] (Operator Representative) Witness [Signature] (NMOCD)

(Position)

NMOCD

MAY 31 2018

DISTRICT III

Revised 02-11-02