



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOCD

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 11 2018

DISTRICT III

Date of Test 6/11/2018 Operator Hilcorp Energy API # 30-045-06000
Property Name Huerfano Unit Well No. 013 Location: Unit N Section 1 Township 26 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 24 Intermediate 1 Casing 25 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	25	0	25
10 min	0	1	25	0	25
15 min	0.1	1	25	0	25
20 min	0.1	1	25		
25 min	0.1	1	25		
30 min	0.1	1	25		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges	X	
Down to Nothing		X
Nothing		
Gas		
Gas & Water		
Water	X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 4.5 INTERMEDIATE D

REMARKS:

BH through 1" fittings, Light puff 1sec, started flowing water @ 10 min 30 sec, slightly grey in color, light odor, produced 1.75 gal in 20 min; water analysis collected BH, no fluids produced on production strings. Int. through 1" fitting, blew down in 2 sec.

By Rogean J.

Witness Jonathan D. Kelly

Operator ST
(Position)

E-mail address _____