



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

JUN 12 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-12-18 Operator Hilcorp Energy Co. API #30-0 45-26112

Property Name McCond Well No. 11E Location: Unit 9 Section 9 Township 30 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 277 Intermediate N/A Casing 365 Bradenhead 187

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		360		
10 min	0		356		
15 min	0		356		
20 min	0		356		
25 min	0		356		
30 min	0		356		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	<u>Vapors.</u>
Surges	
Down to Nothing	
Nothing	
Gas <u>✓</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 5

INTERMEDIATE N/A

REMARKS:

hard blow to 28 seconds. then surging.
Vapors at 2 min 27 seconds - Vapors at 5-10-15-20
heaving surging abandon - 25

By B. J.

Witness Mona Kuehling

(Position)

E-mail address

Check pressure in 24 hours. Gas
analysis BHE all things.