

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

MAY 21 2018

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

5. Lease or Right No. **SF-079329**  
Bureau of Land Management  
6. If Indian, Allottee or Tribe Name

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

**SUBMIT IN TRIPLICATE - Other instructions on page 2.**

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

**Hilcorp Energy Company**

3a. Address

**382 Road 3100, Aztec, NM 87410**

3b. Phone No. (include area code)

**505-599-3400**

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

**San Juan 32 Federal 24 1A**

9. API Well No.

**30-045-32397**

10. Field and Pool or Exploratory Area

**Basin Fruitland Coal**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**Surface Unit J (NWSE), 1940' FSL & 1535' FEL, Sec. 24, T32N, R09W**

11. Country or Parish, State

**San Juan New Mexico**

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Interim Reclamation</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

**Hilcorp Energy Company conducted a legacy interim reclamation inspection on 5/08/2018 with BLM Inspector Bob Switzer and received approval for the reclamation BMPs on the subject well.**

NMOCB

JUN 06 2018

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

**Christine Brock**

Title **Operations/Regulatory Technician**

Signature

*Christine Brock*

Date **5/21/2018**

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

*Sarah N. Grant*

Title

*Supv NRS*

Date

*6/1/18*

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

*RS*

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCB

<b>RCC Reclamation Completion</b>			Location Name: <u>ST 32 Fed 24 #1A</u>			Date: _____			Revision 3 (3/21/17)		
API#: <u>30-045-32397</u>			UL-Sec-Twn-Rng: <u>T-24-032N-009W</u>			Lat/Long: <u>36.96796 -107.72681</u>					
Surface Owner: _____			Lease# <u>SF-079329</u>			County/State: <u>San Juan, NM</u>					
Pipeline Owner: <u>WPC</u>			Twin/Co-Locate Well Name & Operator: _____								
Onsite: <u>Eric Smith</u>			Agency Inspector: <u>Bob Switzer</u>			Contractor: _____			Seed Mix: _____		

  

Interim Reclamation	Completed	Incomplete	N/A	Final Reclamation	Completed	Incomplete	N/A	Remediation	Completed	Incomplete	N/A
Have pit sample results been approved	X			3rd party pipeline removed				Facilities stripped			
Has water been removed from pit	X			Anchors removed				Certificate of waste issued & approved			
Have pit marker photos been taken	X			Equipment and piping removed				Depth:			
Has certificate of waste been issued & approved	X			Power poles removed				Width:			
Have all pit contents been removed	X			Cathodic protection removed				Length:			
Has sample after content removal been taken	X			Vegetative cages removed				Date of Excavation Start:			
Is location contoured	X			CMP's removed				Date of Excavation End:			
Is there 4" of cover over pit	X			Non native gravel buried or removed				Date of Backfill Start:			
Has top soil been spread evenly	X			Noxious weeds removed or sprayed				Date of Backfill End:			
Has all non-native gravel been buried or removed	X			Invasive weeds removed or sprayed				Yards Hauled Out:			
Has pit liner been removed	X			Contouring complete				Impacted Soil Hauled To:			
Has all trash been removed	X			Top soil spread				Yards Hauled In:			
Have all weeds been removed	X			Diversion clean and functional				Fresh Soil Hauled In From:			
Teardrop allows vehicle access to all facilities	X			Silt trap clean and functional				Approval to backfill			
Drainage ditches allow adequate run off	X			Cattle guard / gates removed				Back fill mechanically compacted			
All non-traffic areas disked properly	X			Cellar / mouse hole covered				Facilities reset			
All non-traffic areas seeded	X			Erosion under control				Trash and debris removed			
Seeded areas have been mulched	X			Location properly ripped				Close Out Completed			
Noxious weeds have been removed or sprayed	X			Location properly disked				Soil Removal Sundry Ready to be Filled			
Invasive weeds have been removed or sprayed	X			Location seeded							
Barriers set to deter traffic	X			Photo transect installed							
Silt traps are functional	X			Access road properly closed							
Culverts are functional	X			Public use controlled							
Upper diversion is functional	X			Barriers in place							
Erosion under control	X			Grazing controlled							
Photo transect installed	X			P&A marker installed & legible							
Have wellhead cages and Jersey barriers been removed	X			Well sign removed							
Have reclamation pictures been taken	X			Growth at least 70%							
Growth at least 70%	X			Trash and debris removed from location							
Agency Inspection Date: <u>5/8/18</u>				Final reclamation photos taken							
Sundry is ready to file	X			Agency Inspection Date:							
				FAN Ready to be filed							
Comments:				Comments:				Comments:			