	RECEIVED
	MAY 2 1 2013
Form 3160-5 UNITED STATES	FORM APPROVED
(August 2007) DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEM	
BUREAU OF LAND MANAGEM	Bureau and Sariat Wanagement NMSF-078509
	NMSF-078509
SUNDRY NOTICES AND REPORTS O Do not use this form for proposals to drill o	
abandoned well. Use Form 3160-3 (APD) for	
SUBMIT IN TRIPLICATE - Other instructions of	
1. Type of Well	San Juan 32-9 Unit
Oil Well X Gas Well Other	8. Well Name and No.
2. Name of Operator	San Juan 32-9 Unit 275S 9. API Well No.
Hilcorp Energy Company	30-045-32546
	No. (include area code) 10. Field and Pool or Exploratory Area
	505-599-3400 Basin Fruitland Coal
<ol> <li>Location of Well (Footage, Sec., T.R.M., or Survey Description)</li> <li>Surface Unit E (SWNW), 1685' FNL &amp; 805' FWL, Sec. 29</li> </ol>	T32N. R09W San Juan . New Mexico
Surface Unit E (SWNW), 1685' FNL & 805' FWL, Sec. 29	, 152N, R09W San Juan , New Mexico
12. CHECK THE APPROPRIATE BOX(ES) TO INDI	CATE NATURE OF NOTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
Notice of Intent Acidize Deepe	
	re Treat Reclamation Well Integrity
	Construction Recomplete X Other
	Ind Abandon Temporarily Abandon Interim Reclama
Final Abandonment Notice Convert to Injection Plug E	
3. Describe Proposed or Completed Operation: Clearly state all pertinent details, includin	
Hilcorp Energy Company conducted a legacy interim rec Hererra and received approval for the reclamation BMPs	lamation inspection on 5/15/2018 with BLM Inspector Roger on the subject well.
	NM O C D
	JUN 0 6 2018
	DISTRICT III
4. I hereby certify that the foregoing is true and correct. Name ( <i>Printed/Typed</i> )	
Christine Brock	Title Operations/Regulatory Technician
	The Operations/Regulatory Technician
Signature Is Mistorio A Lock	Date 5/21/2018
Signature UNUSTONE BLOCK THIS SPACE FOR FEDE	· · · · · ·
	Date 5/21/2018
THIS SPACE FOR FEDE	Date 5/21/2018 RAL OR STATE OFFICE USE
Approved by SURLN SURT	Date 5/21/2018 RAL OR STATE OFFICE USE Title Supr NPS Date 5/30/
Approved by Swalph Swalt Conditions of approval, if any, are attached. Approval of this notice does not warrant or ce	Date 5/21/2018 RAL OR STATE OFFICE USE Title Support MPS Date 5/30/ Date 5/30/
THIS SPACE FOR FEDE Approved by Swall functions of approval, if any, are attached. Approval of this notice does not warrant or ce hat the applicant holds legal or equitable title to those rights in the subject lease which wo	Date 5/21/2018 RAL OR STATE OFFICE USE Title Support MPS Date 5/30/ Date 5/30/
THIS SPACE FOR FEDE Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or ce hat the applicant holds legal or equitable title to those rights in the subject lease which wo intitle the applicant to conduct operations thereon.	Date 5/21/2018 RAL OR STATE OFFICE USE Title Suppr MPS Date 5/30/ Date 5/30/ Date 5/30/ Date 5/30/
THIS SPACE FOR FEDE Approved by Swall fam, are attached. Approval of this notice does not warrant or ce hat the applicant holds legal or equitable title to those rights in the subject lease which wo	Date       5/21/2018         RAL OR STATE OFFICE USE         Title Supv MB         Date         Title Supv MB         Date         Office         Office         Troot knowingly and willfully to make to any department or agency of the United States ar

RCC Reclamation Comple	etio	n		Location Name: ST 37-9 Unit	27	5	5	Date: 05/15/18 Revisio		/21/1	
AP1#: 30-045-32546		UL-Sec-Twn-Rng: E - 29 - 032N - 00	Date: 05/15/18 Revision 3 (2)21/17) Lat/Long: 3(0,95833 -107,8086)								
Surface Owner:		Lease# NMSF - 078009				County/State: San Juan, NM					
Pipeline Owner: HEC				Twin/Co-Locate Well Name & Operator:							
Pripeline Owner. //2 C			Inst					Seed Mix:			
Onsile: Eric Smith	Ag		y Insj	Contractor:		Seeu Mix:					
Interim Reclamation	Completed	Incomplete	NIA	Final Reclamation	Completed	Incomplete	MN	Remediation	Completed	Incomplete	
Have pit sample results been approved	12	₹		3rd party pipeline removed		7	T-1	Facilities stripped		Y	
Has water been removed from pit	V	Ľ		Anchors removed				Certificate of waste issued & approved		1	1.
Have pit marker photos been taken	V	ſ		Equipment and piping removed	IZ			Depth:	V		T
Has certificate of waste been issued & approved	V	Ľ		Power poles removed	X	Ľ		Width:	A	T	Ľ
Have all pit contents been removed	V	1		Cathodic protection removed	1			Length:	1		
Has sample after content removal been taken	TV	た		Vegetative cages removed	1			Date of Excavation Start:		1	T
is location contoured	1/	1.		CMP's removed		<u> </u>		Date of Excavation End:	1		1-
Is there 4' of cover over ph	1/	r	+	Non native gravel buried or removed				Date of Backful Start:		1	<u> </u>
Has top soil been spread evenly	11	ᡟᢇ	+	Noxious weeds removed or sprayed		<b> </b>		Date of Backfill End:	+		+
Has all non-native gravel been buried or removed	12	┢	1 1	Insvasive weeds removed or sprayed				Yards Hauled Out:		+	+-
Has od liner been removed	1.2	<u>†                                    </u>	+ 1	Cantouring complete			H	Impacted Soil Hauled To:	+	+	+
Has all trash been removed	<del>ار</del>	≁	+	Top soil spread		<u> </u>	H	Yards Hauled In:	+-	+	
Have all weeds been removed	-11-	ᡟ	+-1	Diversions clean and functional			$\mathbf{H}$	Fresh Soll Hauled in From:	+-		
Teardrop allows vehicle access to all facilities	+	┢	1 - 1	Silt trap clean and functional		<u> </u>		Approval to back/il	+	+	+
Drainage diches allow adequate run off	ĸ	┢─	+	Cattle guard / gates removed	+	-		Back fill mechanically compacted		+	+
All non-traffic areas disked property	+.	┢─		Cellar / mouse hole covered		_	Н	Facilities reset	+	+	++
All non-traffic areas sected	-K	┢╾	1-1	Erosian under control	1 -	<u> </u>	1			╋	╋╌┥
	- <u>r</u>	┢	+			<b>.</b>		Trash and debri removed	+-	+	+
Seeded areas have been mulched	Ľ	1	∔	Location property ripped	$\vdash$	<u> </u>		Close Out Completed	+-		
Noxious weeds have been removed or sprayed	K			Location property disked		L		Soit Removal Sundry Ready to be Fred			
Invasive weeds have been removed or sprayed	1	ĺ	1 1	Location seeded							
Baniers set to deter traffic	V	1	1 1	Photo transect installed					ſ		
Silt traps are functional	V	ł		Access road property closed					Т	1	
Culverts are functional	T	1		Public use controlled	1-	<b>—</b>				T	1
Upper diversion is functional	11	F		Barriers in place			H				$\mathbf{T}$
Erosion under control	12	┢	1-1	Grazing controlled	1-			······································	+	+	1
Photo transect installed		┢──	너	P&A marker installed &/egible	1			·····	+-	+	+'
	+	┢┙	19	Well sign removed	+	-	[]	<b>├</b> /	+	+	+
Have wellhead cages and jersey barriers been removed	1-		┢─┤		-	-	$\mathbf{H}$	/	+-	+	+
Have reclamation pictures been taken	12	┣_	$\square$	Growth at least 70%	-	ļ	Ц	/	+-	4	+
Growth at least 70%	1	1_		Trash and debris emoved from tocation			Ц			1	+
Agency Inspection Date: 05/15/18	1	١.		Final reclamation photos taken					1	1	
Sundry is ready to file	V	1-		Agency Inspection Date:	-						
	T			FAN Ready to be filed		<b>—</b>				Т	T
Comments:				Comments:				Comment4:		_	

. • •

1