		•		RE	CEIVED		
					•		
				MAY	2 1 2013		
Form 3160-5	UNITED STAT				APPROVED		
(August 2007)	DEPARTMENT OF THE BUREAU OF LAND MA	OMB No. 1004-0137 Farreipដទ្ធភាភូមិនា៤ភ្នំសាក្តីទេ					
				5. Lease Serial No.	Ind Management		
SU	NDRY NOTICES AND REP	6. If Indian, Allottee or Tribe Name					
	e this form for proposals						
	d well. Use Form 3160-3 (A						
1. Type of Well	UBMIT IN TRIPLICATE - Other ins	structions on page 2.		7. If Unit of CA/Agreement, N	lame and/or No.		
	X Gas Well Other		8. Well Name and No. San Juan 32 Federal 15 2R				
2. Name of Operator		<u>, , , , , , , , , , , , , , , , , , , </u>		9. API Well No.	52 rederal 15 2R		
	Hilcorp Energy Compa				045-33691		
3a. Address 382 Road 3100, Aztec,	NM 87410	3b. Phone No. (include a 505-599-3		10. Field and Pool or Explorat Basin	ory Area Fruitland Coal		
4. Location of Well (Footage, Sec., T.,		· · · · · · · · · · · · · · · · · · ·		11. Country or Parish, State			
Surface Unit K (NES	W), 1640' FSL & 1770' FWL	_, Sec. 15, T32N, R	09W	San Juan	, New Mexico		
	THE APPROPRIATE BOX(ES)	·			ER DATA		
TYPE OF SUBMISSION		TY	PE OF AC	TION			
Notice of Intent	Acidize	Deepen		. ,	Water Shut-Off		
	Alter Casing						
X Subsequent Report	Casing Repair			•			
Final Abandonment Notice	Change Plans				Interim Reclamation		
		<u> </u>			nate duration thereof		
following completion of the invol Testing has been completed. Fina determined that the site is ready for <b>Hilcorp Energy Compa</b>	ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) ny conducted a legacy int	in a multiple completion o only after all requirements, erim reclamation i	r recompletion including recla nspection	in a new interval, a Form 3160- mation, have been completed an on 5/08/2018 with BL	4 must be filed once and the operator has		
					an e n		
		Fracture Treat Reclamation Well Integrity   New Construction Recomplete X Other   Plug and Abandon Temporarily Abandon Interim Reclamation   Plug Back Water Disposal Interim Reclamation   ails, including estimated starting date of any proposed work and approximate duration thereof. Interim Reclamation   subsurface locations and measured and true vertical depths of all pertinent markers and zones. Bond No. on file with BLM/BLA. Required subsequent reports must be filed within 30 days   si in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once once   only after all requirements, including reclamation, have been completed and the operator has   terrim reclamation inspection on 5/08/2018 with BLM Inspector Bob   n BMPs on the subject well.   IMMOCD   JUN 0 6 2018   DISTRICT III					
				JUN	0 6 2018		
				DISTRI	CT III		
14. I hereby certify that the foregoing i	s true and correct. Name (Printed/Type	ed)					
Christine Brock			perations/R	egulatory Technician			
				-guiltory recurrent	······································		
Signature WWS	tine Groc	Date s	5/21/2018				
	THIS SPACE FO	R FEDERAL OR S	TATE OFF				
Approved by	/				1/1		
Swere N	n pr		Title &	IN NRS	Date 6/1/18		
Conditions of approval, if any, are attac	hed. Approval of this notice does not w	warrant or certify					
that the applicant holds legal or equitab	le title to those rights in the subject lea		Office	$\leq$			
entitle the applicant to conduct operation Title 18 U.S.C. Section 1001 and Title		e for any person knowing	and willfulle	to make to any denotment of an	ency of the United States any		
false, fictitious or fraudulent statements			y and whitully i	to make to any department of ag	ency of the Officer States any		
(Instruction on page 2)		NMOCL					

L

RCC Reclamation Completion		Location Name: ST 32 Fed 15 #28	ζ			Date: Revisio	n 3 (3/	/21/17)	
API#: 30-045-33691		UL-Sec-Twn-Rng: K - 15-032N-009W			Lat/Long: 36.98171 -107.7692				
Surface Owner:			Lease# SF-078687			County/State: San Juan, NM			
Pipeline Owner: ENT			Twin/Co-Locate Well Name & Operator:						
Onstre: Eric Smith	Age	ncy Ins	Sor: 6 Swotyn Contractor:				Seed Mix:		
Interim Reclamation	Completed	Incomplete	Final Reclamation	Completed	Incomplete	M	Remediation	Completed	Incomplete
Have pit sample results been approved			3rd party pipeline removed	17			Facilities stripped	17	
Has water been removed from pit	Ň.		Anchors removed	V			Certificate of waste issued & approved	IZ.	
Have pit marker photos been taken	- Y		Equipment and piping removed				Depth:	K	
Has certificate of waste been issued & approved			Power poles removed				Widih:	1	
Have all pit contents been removed	- ŶI		Calhodic protection removed				Length:		
Has sample after content removal been taken	- XI		Vegetative cages removed	1			Date of Excevation Start:		
is location contoured	151		CMP's removed				Date of Excavation End;	T	
Is there 4' of cover over pit	- XI	$\neg \neg$	Non native gravel burled or removed	1			Date of Backfill Start:	$\mathbf{T}$	$\square$
Mas top soil been spread evenly	12	$\neg$	Noxious weeds removed or sprayed				Date of Backfil End:	1-	
Has all non-native gravel been buried or removed	171		Insvasive weeds removed or sprayed				Yards Hauled Out:		
Has of liner been removed	<b>-</b> [x]	$\neg \neg$	Contouring complete				Impacted Soil Hauted To:		┢╍┾╼
Has el trash been removed	- <del>l</del> êl	+	Top soil spread		┝╌┥		Yards Haulad In:	+	
Have all weeds been removed	-lữt		Diversions clean and functional				Fresh Soli Havled In From:		┢┼╍
Teardrop allows vehicle access to all facilities	-151	-	Silt trap clean and functional		⊢-1		Approval to backfil	-	┼╾┼╸
Drainage ditches allow adequate run off	-18-1		Cattle guard / gates removed		┢╌╢	-	Back fil mechanically compacted	+	┢╋╋
All non-traffic areas disked property	- 문		Cellar / mouse holo covered		┝╌┤	-	Facilities reset	+	┢┼╋
	1	_		<b></b>	$\square$	4		+	┢╌┟╌
All non-traffic areas seeded			Erosion under control			_	Trash and debri removed	_	$\vdash$
Seeded areas have been mulched	<u> ×</u>		Location property ripped				Close Out Completed		
s weads have been removed or sprayed	<b>-</b>		Location property disked				Soil Removal Sundry Ready to be Ted		
invasive weeds have been removed or sprayed			Location seeded						
Banters set to deter traffic	1 <del>,</del>		Photo transect installed				/		$\square$
Sit traps are functional			Access road property closed		-1	-			
Culverts are functional	- Íži		Public use controlled		1		·	+	
Upper diversion is functional	니카	+	Barriere in place		┢─┤		├─── <b>─</b> ───/──	+	++-
Eroston under control	-121		Grazing controlled		⊢∔		<i> </i>	+	⊢⊢
Photo transect installed	<u>- 1×</u>		P&A marker installed & legible	-	┝╍┥		<u>├─────/───────────────────────────────</u>		┢╼╋╼
					⊢┥	_	<u>├──</u> ───/───────────────────────────────	4	┝╌┠╴
Have wellhead cages and jersey barriers been removed	1×1	-	Weil sign removed					+	┢┥┝
Have reclamation pictures been taken	<u> × </u>		Growth at least 79%		$\square$			1	
Growth at least 70%	X		Trash and debrin removed from location						
Agancy Inspection Date: 5/8/19	11		Final reclamation photos taken			7			
Sundry is ready to file	121		Agency Inspection Date:				/	1	
			FAN Ready to be filed		H+	-		1	
Comments:			Comments:		L	-	Comments:	<u> </u>	·
			/						