Form C-144 Revised April 3, 2017

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application
Type of action: Below grade tank registration Permit of a pit or proposed alternative method Closure of a pit, below-grade tank, or proposed alternative method Modification to an existing permit/or registration Closure plan only submitted for an existing permitted or non-permitted pit, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
I. Operator: BP America Production Company Address: 200 Energy Court, Farmington, NM 87401 Facility or well name: EE ELLIOTT A 002 API Number: 3004509446 U/L or Qtr/Qtr P Section 15 Township 30N Range 09W County: San Juan Center of Proposed Design: Latitude 36.80688 Surface Owner: Federal State Private Tribal Trust or Indian Allotment
Pit: Subsection F, G or J of 19.15.17.11 NMAC Temporary: Drilling Workover Permanent Emergency Cavitation P&A Multi-Well Fluid Management Low Chloride Drilling Fluid yes no Lined Unlined Liner type: Thickness mil LLDPE HDPE PVC Other String-Reinforced Liner Seams: Welded Factory Other Volume: bbl Dimensions: L x W x D
Below-grade tank: Subsection I of 19.15.17.11 NMAC Volume: 95
4. Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.
Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)								
Screen Netting Other								
Monthly inspections (If netting or screening is not physically feasible)								
7.								
Signs: Subsection C of 19.15.17.11 NMAC								
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers								
☐ Signed in compliance with 19.15.16.8 NMAC								
Variances and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.								
9. Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptance are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	ptable source							
General siting								
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No							
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No							
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No							
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No							
 Within an unstable area. (Does not apply to below grade tanks) Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ☐ No							
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	Yes No							
Below Grade Tanks								
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)								
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							
Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial application.	☐ Yes ☐ No							
 Visual inspection (certification) of the proposed site; Aerial photo; Satellite image 								
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No							

Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit Non-low chloride drilling fluid	
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NI Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.1 and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	NMAC 5.17.9 NMAC
11. Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC	
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documentation attached. Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC A List of wells with approved application for permit to drill associated with the pit. Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.1 and 19.15.17.13 NMAC Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Previously Approved Design (attach copy of design) API Number: or Permit Number:	15.17.9 NMAC

ì

Form C-144 Oil Conservation Division Page 3 of 6

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H2S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	documents are
Proposed Closure: 19.15.17.13 NMAC	
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well Factorial Removed Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method	Tuid Management Pit
14.	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
15.	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. In 19.15.17.10 NMAC for guidance.	
Ground water is less than 25 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	Yes No
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	Yes No

 adopted pursuant to NMSA 1978, Section 3-27-3, as amended. Written confirmation or verification from the municipality; Written approval obtained from the municipality 	☐ Yes ☐ No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geolog Society; Topographic map 	ical Yes No
Within a 100-year floodplain FEMA map	Yes No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure Plan Check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 1 Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirement Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standal Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	9.15.17.11 NMAC ats of 19.15.17.11 NMAC
Operator Application Certification:	
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge	and belief.
Name (Print): Title:	
Signature: Date:	
e-mail address: Telephone:	
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachm	
OCD Representative Signature: Approval Date:	2. (101)
	13,500
Title: Commental Specialist OCD Permit Number:	
Closure Report (required within 60 days of closure completion): 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and sur. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Pleas section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date: 05/18/2	e do not complete this
20.	
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Confidence of the Confidence of the Confidenc	Closed-loop systems only)
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. For mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure for private land only)	Please indicate, by a check

Form C-144 Oil Conservation Division Page 5 of 6

22.	
Operator Closure Certification:	
	this closure report is true, accurate and complete to the best of my knowledge and sure requirements and conditions specified in the approved closure plan.
Name (Print): Erin Garifalos	Title: Field Environmental Coordinator
Signature: UTIN GWTiffalos	Date: June 25, 2018
e-mail address: erin.garifalos@bpx.com	Telephone: (832) 609-7048

BP AMERICA PRODUCTION COMPANY

SAN JUAN BASIN, NORTHWEST NEW MEXICO

BELOW-GRADE TANK CLOSURE PLAN

EE ELLIOTT A 002

API No. 3004509446

Unit Letter P Section 15 T 30N R 09W

This plan will address the standard protocols and procedures for closure of below-grade tanks (BGTs) on BP America Production Company (BP) well sites. As stipulated in Paragraph A of 19.15.17.13 NMAC, BP shall close a BGT within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the New Mexico Oil Conservation Division (NMOCD) requires because of imminent danger to fresh water, public health, safety or the environment. If deviations from this plan are necessary, any specific changes will be included on form C-144 and approved by the NMOCD. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofit with a BGT that complies with the BP NMOCD approved BGT design attached to the BP Design and Construction Plan. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC, if not previously retrofitted to comply with the BP NMOCD approve BGT Design attached to the BP Design and Construction Plan, prior to any sale or change in operator pursuant to 19.15.9.9 NMAC. BP shall close the permitted BGT within 60 days of cessation of the BGTs operation or as required by the transitional provisions of Subsection B, D, or E of 19.15.17.17 NMAC.

General Closure Plan

1. BP shall notify the surface owner by certified mail that it plans to close a BGT. Evidence of mailing of the notice to the address of the surface owner shown in the county tax records demonstrates compliance with this requirement.

Notice is attached.

2. BP shall notify the division District III office verbally or by other means at least 72 hours, but not more than one (1) week, prior to any closure operation. The notice shall include the operator's name, and the location to be closed by unit letter, section, township and range. If the BGT closure is associated with a particular well, then the notice shall also include the well's name, number and API number.

Notice was provided and is attached.

- 3. BP shall remove liquids and sludge from the BGT prior to implementing a closure method and dispose of the liquids and sludge in a NMOCD's division-approved facility. The facilities to be used are:
 - a. BP Crouch Mesa Landfarm, Permit NM-02-003 (Solids)
 - b. JFJ Landfarm, Permit NM-01-010(B) (Solids and Sludge)
 - c. Basin Disposal, Permit NM-01-0005 (Liquids)
 - d. Envirotech Inc Soil Remediation Facility, Permit NM-01-0011 (Solids and Sludge)
 - e. BP Operated E.E. Elliott SWD #1, API 30-045-27799 (Liquids)

- f. BP Operated 13 GCU SWD #1, API 30-045-28601 (Liquids)
- g. BP Operated GCU 259 SWD, API 30-045-20006 (Liquids)
- h. BP Operated GCU 306 SWD, API 30-045-24286 (Liquids)
- i. BP Operated GCU 307 SWD, API 30-045-24248 (Liquids)
- j. BP Operated GCU 328 SWD, API 30-045-24735 (Liquids)
- k. BP Operated Pritchard SWD #1, API 30-045-28351 (Liquids)

All liquids and sludge in the BGT were removed and sent to one of the above NMOCD approved facilities for disposal.

4. BP shall remove the BGT and dispose of it in a NMOCD approved facility or recycle, reuse, or reclaim it in a manner that the NMOCD approves. If a liner is present and must be disposed of it will be cleaned by scraping any soils or other attached materials on the liner to a de minimus amount and disposed at a permitted solid waste facility, pursuant to Subparagraph (m) of Paragraph (1) of Subsection C of 19.15.35.8 NMAC. Documentation as to the final disposition of the removed BGT will be provided in the final closure report.

The BGT was transported for recycling.

5. BP shall remove any on-site equipment associated with a BGT unless the equipment is required for well production.

All equipment associated with the BGT has been removed.

6. BP shall test the soils beneath the BGT to determine whether a release has occurred. BP shall collect at a minimum: a five (5) point composite sample and individual grab samples from any area that is wet, discolored or showing other evidence of a release and analyze for BTEX, TPH and chlorides. The testing methods for those constituents are as follows;

Constituents	Testing Method	Release Verification	Sample
	95 bbl BGT	(mg/Kg)	results
Benzene	US EPA Method SW-846 8021B or 8260B	10	< 0.019
Total BTEX	US EPA Method SW-846 8021B or 8260B	50	< 0.078
TPH	US EPA Method SW-846 418.1 or 8015 extended	100	57
Chlorides	US EPA Method 300.0 or 4500B	620	< 30

Notes: mg/Kg = milligram per kilogram, BTEX = benzene, toluene, ethylbenzene, and total xylenes, TPH = total petroleum hydrocarbons. Other EPA methods that the division approves may be applied to all constituents listed. Chloride closure standards will be determined by which ever concentration level is greatest.

Soil under the BGT was sampled for chloride, TPH and BTEX with all concentrations below the stated limits. The field report and laboratory reports are attached.

7. BP shall notify the division District III office of its results on form C-141.

C-141 is attached.

8. If it is determined that a release has occurred, then BP will comply with 19.15.30 NMAC and 19.15.29 NMAC, as appropriate.

Sampling results indicate a release has occurred but is below regulatory limits. Attached is a laboratory report and C-141.

9. If the sampling demonstrates that a release has not occurred or that any release does not exceed the concentrations specified above, then BP shall backfill the excavation, with compacted, non-waste containing, earthen material; construct a division-prescribed soil cover, re-contour and re-vegetate the location. The location will be reclaimed if it is not with in the active process area

Sampling results indicate a release has occurred but is below regulatory limits. Attached is a laboratory report and field report. The location will be reclaimed when the well is plugged and abandoned.

10. BP shall reclaim the BGT location and all areas associated with the BGT including associated access roads to a safe and stable condition that blends with the surrounding undisturbed area. BP shall substantially restore the impacted surface area to the condition that existed prior to oil and gas operations by placement of the soil cover as provided in Subsection H of 19.15.17.13 NMAC, re-contour the location and associated areas to a contour that approximates the original contour and blends with the surrounding topography and re-vegetate according to Subsection I of 19.15.17.13 NMAC.

The area has been backfilled and BGT location's surface condition is clear, but within the site's operational area. The location will be reclaimed when the well is plugged and abandoned.

11. The soil cover for closures where the BGT has been removed or remediated to the NMOCD's satisfaction shall consist of the background thickness of topsoil or one foot of suitable material to establish vegetation at the site, whichever is greater. The soil cover will be constructed to the site's existing grade and all practicable efforts will be made to prevent ponding of water and erosion of the cover material.

The area has been backfilled and BGT location's surface condition is clear, but within the site's operational area. The location will be reclaimed when the well is plugged and abandoned.

12. BP shall seed the disturbed area the first growing season after closure of the BGT. Seeding will be accomplished by drilling on the contour whenever practical or by other division-approved methods. Vegetative cover will be, at a minimum, 70% of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation), consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintenance of that cover through two successive growing seasons. During the two growing seasons that prove viability, there shall be no artificial irrigation of the vegetation.

The area has been backfilled and BGT location's surface condition is clear, but within the site's operational area. The location will be reclaimed when the well is plugged and abandoned.

13. BP shall seed, plant and re-seed pursuant to Paragraph (3) of Subsection I of 19.15.17.13 NMAC, until the location successfully achieves the required vegetative cover.

The area has been backfilled and BGT location's surface condition is clear, but within the site's operational area. The location will be reclaimed when the well is plugged and abandoned.

- 14. Pursuant to Paragraph (5) of Subsection I of 19.15.17.13 NMAC, BP shall notify the NMOCD when it has seeded or planted and when it successfully achieves revegetation.
 - The area has been backfilled and BGT location's surface condition is clear, but within the site's operational area. The location will be reclaimed when the well is plugged and abandoned.
- 15. Within 60 days of closure completion, BP shall submit a closure report on NMOCD's form C-144, and will include the following;
 - a. proof of closure notification (surface owner and NMOCD)
 - b. sampling analytical reports; information required by 19.15.17 NMAC;
 - c. disposal facility name and permit number
 - d. details on back-filling, capping, covering, and where applicable re-vegetation application rates and seeding techniques and
 - e. site reclamation, photo documentation.

Closure report on C-144 form is included including photos of reclamation completion.

16. BP shall certify that all information in the report and attachments is accurate, truthful, and compliant with all applicable closure requirements and conditions specified in the approved closure plan.

Certification section of C-144 has been completed.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

			Rele	ase Notific	eation	and Co	rrective A	ction	1			
						OPERA			Initia	al Report		Final Report
				ion Compan			Garifalos	7040				
Address 200 Energy Court, Farmington, NM 87401 Telephone No. (832) 609- Facility Name EE ELLIOTT A 002 Facility Type: Natural Ga									ell			
Surface Own				Mineral (.300450	2//6	
Surface OW	ici, i edi	Siai		-		OF REI	FASE		7111110	.000400.	3440)
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/	West Line	County		
P	15	30N	09W	1,130	Sou	ıth	990	Eas	st	S	an	Juan
			Latitud	e 36.80688	Lo	ongitude -1	07.76180	NAD	83			
						OF RELI						
Type of Relea	se:: none)			CIC		Release:: unkno	own		Recovered::		
Source of Rel	ease: belo	w grade ta	nk - 95 k	obl	our of Occurrenc	e:	Date and n/a	Hour of Disc	overy:			
Was Immedia		Given?		No Not Re	aguired	If YES, To	Whom?					
By Whom?			105	NO LI NOUN	equired	Date and H	our					
By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.												
			Yes 🗸									
If a Watercou	rse was Im	pacted, Descr	ibe Fully.*									
Describe Caus	se of Probl	em and Reme	dial Action	Taken.* Samı	olina c	of the soil	beneath the	BGT	was do	ne durino	ı rem	noval.
					_		d for Chlorid					
				closu	re sta	ndards. F	ield reports	and I	aborato	y results	are a	attached.
Describe Area	Affected:	and Cleanup A	Action Tak	en.* No actio	n nec	essary F	inal laborato	orv ar	nalvsis d	letermine	ed no)
						n is requi		or y ar	lary old C		, a 110	´
							knowledge and un					
							d perform correct arked as "Final Re					
should their o	perations h	ave failed to a	dequately	investigate and r	emediate	contamination	on that pose a three	eat to gr	round water	, surface wat	er, hun	nan health
federal, state,				ance of a C-141	report do	bes not reneve	e the operator of r	espons	ibility for co	ompiiance wi	tn any	otner
1	vii.	11 -0 A	,				OIL CONS	SERV	ATION	DIVISIO	N	
Signature:	run g	arifalo	4									
Printed Name	Frin G	arifalos			- F	Approved by	Environmental Sp	pecialis	t:			
				dinatar								
Title: Field					F	Approval Date	2:		Expiration I	Date:		
E-mail Addres	ss: erin.	garitalos	@bpx	.com	Approval:			Attached				
Date: June	25, 2018	3	Phone:	(832) 609-70)48							

^{*} Attach Additional Sheets If Necessary

bp



BP America Production Company 380 Airport Rd Durango, CO 81303 Phone: (970) 247 6800

May 11, 2018

Bureau of Land Management Whitney Thomas 6251 College Suite A Farmington, NM 87402

VIA EMAIL

Re: Notification of plans to close/remove a below grade tank Well Name: EE ELLIOTT A 002 API# - 3004509446

Dear Mrs. Thomas,

As part of the NM "Pit Rule": 19.15.17.13 Closure Requirements, Paragraph J. BP America Production Company (BP) is required to notify the surface owner of BP's plans to close/remove a below grade tank. BP wishes to inform you of our plans to close/remove the below grade tank on its well pad located on your surface. BP plans to commence this work on or about May 17, 2018. If there aren't any unforeseen problems, the work should be completed within 10 working days.

As a point of clarification, BP will be closing the below grade tank and either operating without one or replacing it with an above ground tank, the well site will continue to operate.

If witnessing of the tank removal is required please contact me for a specific time (832)-609-7048.

Sincerely,

Erin Garifalos

BP America Production Company

From: Buckley, Farrah (CH2M HILL)

To: Smith, Cory, EMNRD; Fields, Vanessa, EMNRD (Vanessa.Fields@state.nm.us)

Cc: jeffcblagg@aol.com; blagg_njv@yahoo.com; Garifalos, Erin

Subject: BP Pit Close Notification - EE ELLIOTT A 002

Date: Friday, May 11, 2018 10:48:57 AM

BP America Production Company 380 Airport Rd Durango, CO 81303 Phone: (970) 247 6800

SENT VIA E-MAIL TO: <u>CORY.SMITH@STATE.NM.US</u>; <u>VANESSA.FIELDS@STATE.NM.US</u>

May 11, 2018

New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

RE: Notice of Proposed Below-Grade Tank (BGT) Closure

EE ELLIOTT A 002 API# 30-45-09446 (P) Section 15 – T30N – R09W San Juan County, New Mexico

Dear Mr. Cory Smith and Mrs. Vanessa Fields,

In regards to the captioned subject and requirements of the NMOCD pit rule, this letter is notification that BP is planning to close a 95bbl BGT that will no longer be operational at this well site. We anticipate this work to start on or around May 17, 2018.

Should you have any questions, please feel free to contact BP at our Durango office.

Sincerely,

Erin Garifalos

Field Environmental Coordinator - San Juan

Cell: 832-609-7048

Farrah Buckley BGT Project Support 970-946-9199 -cell

This email and any attachments are intended only for the addressee(s) listed above and may contain confidential, proprietary, and/or privileged information. If you are not an intended recipient, please immediately advise the sender by return email, delete this email and any attachments, and destroy any copies of same. Any unauthorized review, use, copying disclosure or distribution of this email and any attachments is prohibited.

CLIENT: BP	BLAGG ENGINEERING, INC. P.O. BOX 87, BLOOMFIELD, NM 87413 (505) 632-1199	API #:3004509446 TANK ID (if applicble): A
FIELD REPORT:	(circle one): BGT CONFIRMATION / RELEASE INVESTIGATION / OTHER:	PAGE #: 1 of 1
SITE INFORMATION	I: SITE NAME: EE ELLIOTT A # 2	DATE STARTED: 05/15/18
QUAD/UNIT: P SEC: 15 TWP:	30N RNG: 9W PM: NM CNTY: SJ ST: NM	DATE FINISHED:
1/4 -1/4/FOOTAGE: 1,130'S / 99		ENVIRONMENTAL
LEASE #: SF078139	PROD. FORMATION: PC CONTRACTOR: BP - J. GONZALES	SPECIALIST(S): NJV
REFERENCE POINT		12 GL ELEV.: 6,163'
1) 95 BGT (SW/DB)		/BEARING FROM W.H.: 134', \$49E
2)		/BEARING FROM W.H.:
3)	GPS COORD.: DISTANCE	/BEARING FROM W.H.:
4)	GPS COORD.: DISTANCE	/BEARING FROM W.H.:
SAMPLING DATA:	CHAIN OF CUSTODY RECORD(S) # OR LAB USED: HALL	OVM READING
		8015B/8021B/300.0 (CI) NA
2) SAMPLE ID:		ν ν ν ν ν ν ν ν ν ν ν ν ν ν ν ν ν ν ν
3) SAMPLE ID:	SAMPLE DATE: SAMPLE TIME: LAB ANALYSIS:	
	SAMPLE DATE: SAMPLE TIME: LAB ANALYSIS:	
5) SAMPLE ID:	SAMPLE DATE: SAMPLE TIME: LAB ANALYSIS: SOIL TYPE: SAND SILTY SAND SILT / SILTY CLAY / CLAY / GRAVEL OTHER IMPO	
COHESION (ALL OTHERS): NON COHESIVE SLIGHTLY CONSISTENCY (NON COHESIVE SOILS): LC MOISTURE: DRY (SLIGHTLY MOIST) MOIST / W SAMPLE TYPE: GRAB (COMPOSITE) # DISCOLORATION/STAINING OBSERVED: YES N SITE OBSERVATION APPARENT EVIDENCE OF A RELEASE OBSERVE EQUIPMENT SET OVER RECLAIMED AREA:	HC ODOR DETECTED: YES NO EXPLANATION - ET / SATURATED / SUPER SATURATED OF PTS. 5 ANY AREAS DISPLAYING WETNESS: YES NO EXPLANATION - OF EXPLANTION - OF EXPLANATION - OF EXPLANATION - OF EXPLANATION - OF	PLANATION -
EXCAVATION DIMENSION ESTIMATION:		ESTIMATION (Cubic Yards) : NA
DEPTH TO GROUNDWATER: >100' N	EAREST WATER SOURCE: >1,000' NEAREST SURFACE WATER: <1,000' N	MOCD TPH CLOSURE STD: 1,000 ppm
SITE SKETCH	BGT Located : off on site PLOT PLAN circle: attached	OVM CALIB. READ. = NA ppm RF =1.00
	\	OVM CALIB, GAS = NA ppm
TC W.F		TIME: NA am/pm DATE: NA
PROD. TANK NOTES: BGT = BELOW-GRADE TANK; E.D. = EXCAVATIO	PBGTL T.B. ~6.5' B.G. STEEL CONTAINMENT RING X - S.P.D. ON DEPRESSION; B.G. = BELOWGRADE; B = BELOW, T.H. = TEST HOLE; ~= APPROX.; W.H. = WELL HEAD;	MISCELL. NOTES WO: REF #: P-974 VID: VHIXONEVB2 PJ #: Permit date(s): 06/02/10 OCD Appr. date(s): 03/02/17 Tank OVM = Organic Vapor Meter ID ppm = parts per million A BGT Sidewalls Visible: Y / N BGT Sidewalls Visible: Y / N
T.B. = TANK BOTTOM; PBGTL = PREVIOUS BEL	OWAGRADE TANK LOCATION; SPD = SAMPLE POINT DESIGNATION; R.W. = RETAINING WALL; NA - NOT EWALL; DW - DOUBLE WALL; SB - SINGLE BOTTOM; DB - DOUBLE BOTTOM.	Magnetic declination: 10° E

revised: 11/26/13 BEI1005E-6.SKF

Analytical Report

Lab Order 1805853

Date Reported: 5/18/2018

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Blagg Engineering

Client Sample ID: 5PC-TB @ 6.5' (95)

Collection Date: 5/15/2018 2:35:00 PM

Project: Lab ID:

EE ELLIOTT A 2

1805853-001

Matrix: SOIL

Received Date: 5/16/2018 6:45:00 AM

Analyses	Result	PQL Qua	al Units	DF	Date Analyzed	Batch
EPA METHOD 300.0: ANIONS					Analyst	MRA
Chloride	ND	30	mg/Kg	20	5/16/2018 1:57:41 PM	38151
EPA METHOD 8015M/D: DIESEL RANGE	ORGANICS				Analyst	TOM
Diesel Range Organics (DRO)	ND	9.9	mg/Kg	1	5/16/2018 12:51:13 PM	38140
Motor Oil Range Organics (MRO)	57	50	mg/Kg	1	5/16/2018 12:51:13 PM	38140
Surr: DNOP	98.2	70-130	%Rec	1	5/16/2018 12:51:13 PM	38140
EPA METHOD 8015D: GASOLINE RANG	iΕ				Analyst	NSB
Gasoline Range Organics (GRO)	ND	3.9	mg/Kg	1	5/16/2018 11:17:48 AM	38114
Surr: BFB	86.0	15-316	%Rec	1	5/16/2018 11:17:48 AM	38114
EPA METHOD 8021B: VOLATILES					Analyst	NSB
Benzene	ND	0.019	mg/Kg	1	5/16/2018 11:17:48 AM	38114
Toluene	ND	0.039	mg/Kg	1	5/16/2018 11:17:48 AM	38114
Ethylbenzene	ND	0.039	mg/Kg	1	5/16/2018 11:17:48 AM	38114
Xylenes, Total	ND	0.078	mg/Kg	1	5/16/2018 11:17:48 AM	38114
Surr: 4-Bromofluorobenzene	97.5	80-120	%Rec	1	5/16/2018 11:17:48 AM	38114

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- PQL Practical Quanitative Limit
- % Recovery outside of range due to dilution or matrix
- Analyte detected in the associated Method Blank
- E Value above quantitation range
- Analyte detected below quantitation limits Page 1 of 5 J
- P Sample pH Not In Range
- RL Reporting Detection Limit
 - Sample container temperature is out of limit as specified

C	hain-c	of-Cus	stody Record	Turn-Around T	ime:	SAME				н	AI	-	NI	/TE	20	RI IA	4EI	NTA	
Client:	BLAG	G ENGR.	/ BP AMERICA	☐ Standard	☑ Rush _	DAY)	_		_										
				Project Name:					ANALYSIS LABORATOR										
Mailing A	ddress:	P.O. BO	X 87	EI	E ELLIOTT A	A # 2		490)1 Ha										
		BLOOM	FIELD, NM 87413	Project #:			4901 Hawkins NE - Albuquerque, NM 87109 Tel. 505-345-3975 Fax 505-345-4107												
Phone #:		(505) 63	2-1199							71	7.5.	Ana		-	1000				
email or F	ax#:			Project Manag	er:														
QA/QC Pad Standa			Level 4 (Full Validation)		ERIN GARII	FALOS	(8021B)	only)	(MRO)		101	2	PO4,50	PCB's			ter - 300.1)		۵
Accreditat	tion:			Sampler:	NELSON VE	LEZ	¥ (8	(Gas	DRO /	7	(1)	3	102,1	/ 8082			/ water		sample
□ NELAP		□ Other		STATE OF THE PARTY	¥¥es		1	TPH	-	418	504	S	03,1	/ se		(AC	300.0		
□ EDD (1	Гуре)			Sample Temp	erature: 🏑	4	#	BE +	(GR	hod	pod 3	8 Metals	CI,N	icid	(A)	ni-V		ble	posi
Date	Time	Matrix	Sample Request ID	Container Type and # Meu#ed	Preservative Type	HEAL No. /305 85 3	BTEX ←₩Ŧ	BTEX + MTBE	TPH 8015B (GRO	TPH (Method 418.1)	EDB (Method 504.1)	RCRA 8 M	Anions (F,Cl,NO ₃ ,NO ₂ ,PO ₄ ,SO ₄)	8081 Pesticides	8260B (VOA)	8270 (Semi-VOA)	Chloride (soil	Grab sample	5 pt. composite
5/15/18	1435	SOIL	5PC-TB@ 6.5 (95)	4 oz 1	Cool	-201	٧		٧								٧		٧
1.0/10																			
																	-		
1 4 10 4																			
Date: 5/15/18	Time:	Relinquishe	Elin V	Received by:	cho to	Date Time 5/5/18 1648		narks:	8	REFE	RENCE	# WHE	N APP	LICA	BLE;		VITH CC	RRESPO	NDING V
Date: Time: Relinquished by:				Received by:	20	Date Time			/ID: \	VHIX	ONEV P - 97	B2	, vn	L	·				

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1805853 18-May-18

Client:

Blagg Engineering

Project:

EE ELLIOTT A 2

Sample ID MB-38151

SampType: mblk

TestCode: EPA Method 300.0: Anions

Client ID:

PBS

Batch ID: 38151

RunNo: 51317

Prep Date: 5/16/2018 Analysis Date: 5/16/2018 PQL

SeqNo: 1669707

Units: mg/Kg HighLimit

%RPD **RPDLimit**

Qual

Analyte Chloride

ND 1.5

LCSS

SampType: Ics

TestCode: EPA Method 300.0: Anions

Sample ID LCS-38151

RunNo: 51317

Prep Date: 5/16/2018 Batch ID: 38151

Result

Analysis Date: 5/16/2018

SeqNo: 1669708

Units: mg/Kg

%RPD

Analyte

Client ID:

Result PQL

15.00

SPK value SPK Ref Val %REC LowLimit

95.9

110

14

SPK value SPK Ref Val %REC

90

RPDLimit Qual

Chloride

1.5

HighLimit

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

Holding times for preparation or analysis exceeded H

Not Detected at the Reporting Limit ND

PQL Practical Quanitative Limit

% Recovery outside of range due to dilution or matrix

Analyte detected in the associated Method Blank В

E Value above quantitation range

J Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Detection Limit Sample container temperature is out of limit as specified Page 2 of 5

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#:

1805853

18-May-18

Client:

Blagg Engineering

Project:

EE ELLIOTT A 2

Sample ID LCS-38140	SampType	e: LCS	TestCode: EPA Method 8015M/D: Diesel Range Organics							
Client ID: LCSS	Batch ID: 38140 RunNo: 51307									
Prep Date: 5/16/2018	Analysis Date	5/16/2018	SeqNo: 1667893 Units: mg/Kg							
Analyte	Result P	QL SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual	
Diesel Range Organics (DRO)	50	10 50.00	0	99.9	70	130				
Surr: DNOP	4.4	5.000		88.8	70	130				

Sample ID MB-38140	SampT	ype: ME	BLK	TestCode: EPA Method 8015M/D: Diesel Range Organics								
Client ID: PBS	Batch ID: 38140			F	RunNo: 5	1307						
Prep Date: 5/16/2018	Analysis D	Analysis Date: 5/16/2018 SeqNo: 1667894 Units: mg/Kg										
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Diesel Range Organics (DRO)	ND	10										
Motor Oil Range Organics (MRO)	ND	50										
Surr: DNOP	10		10.00		102	70	130					

Qualifiers:

* Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

PQL Practical Quanitative Limit

S % Recovery outside of range due to dilution or matrix

B Analyte detected in the associated Method Blank

E Value above quantitation range

J Analyte detected below quantitation limits

Page 3 of 5

P Sample pH Not In Range

RL Reporting Detection Limit

W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#:

1805853

18-May-18

Client:

- 18 gr

Blagg Engineering

Project:

Analyte

EE ELLIOTT A 2

Sample ID MB-38114

SampType: MBLK

TestCode: EPA Method 8015D: Gasoline Range

LowLimit

Client ID: PBS Batch ID: 38114

PQL

5.0

5.0

RunNo: 51311

Prep Date: 5/15/2018 Analysis Date: 5/16/2018

SeqNo: 1669115

Units: mg/Kg

%RPD **RPDLimit**

Gasoline Range Organics (GRO)

ND

SPK value SPK Ref Val %REC

Qual

LCSS

5/15/2018

Result

92.2

HighLimit

Surr: BFB

920

1000

316

Sample ID LCS-38114

SampType: LCS Batch ID: 38114

RunNo: 51311

TestCode: EPA Method 8015D: Gasoline Range

15

Units: mg/Kg

Analyte Gasoline Range Organics (GRO) Analysis Date: 5/16/2018 Result

SPK value

SPK Ref Val 0

%REC 105

SeqNo: 1669116

LowLimit 75.9 HighLimit

%RPD **RPDLimit**

Qual

Surr: BFB

Client ID:

Prep Date:

26 1000 25.00 1000

102

15

131 316

Page 4 of 5

Qualifiers:

Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

Holding times for preparation or analysis exceeded

Not Detected at the Reporting Limit ND

Practical Quanitative Limit **PQL**

% Recovery outside of range due to dilution or matrix

В Analyte detected in the associated Method Blank

E Value above quantitation range

Analyte detected below quantitation limits

P Sample pH Not In Range

RL Reporting Detection Limit

Sample container temperature is out of limit as specified



Hall Environmental Analysis Laboratory 4901 Hawkins NE Albuquerque, NM 87109

TEL: 505-345-3975 FAX: 505-345-4107 Website: www.hallenvironmental.com

Sample Log-In Check List

Cli	ent Name:	BLAGG		Work	Order Num	ber: 180	5853			Rcp	tNo: 1	
				7.1					×	•	• •	
Red	ceived By:	Anne Tho	rne	5/16/20	18 6:45:00	AM ·		6	Jone A	<u></u>	,	
Con	mpleted By:	Anne Tho			18 7:14:05	AM .			anne A	-		
	viewed By: bulled b	In	ATUS/1	5/16/	(8							
Cha	ain of Cust	ody				· .						
1. 1	s Chain of Cu	stody compl	ete?	**		Yes	V		No 🗌	Not Present		
2. 1	How was the s	ample delive	ered?			Cou	<u>rier</u>					•
Lo	g In			S 100			_				_	
3. , \	Was an attemp	ot made to c	ool the samp	les?		Yes	V		No 🗀	NA L		
4. V	Vere all sampl	es received	at a tempera	ture of >0° C t	to 6.0°C	Yes	V		No 🗆	NA [
5. 5	5. Sample(s) in proper container(s)?						V		No 🗆		•	
6. S	ufficient samp	le volume fo	or indicated te	est(s)?		Yes	Y		No 🗌		, .	
7. A	re samples (e	xcept VOA	and ONG) pro	perly preserve	d?	Yes	V		No 🗌			
8. Was preservative added to bottles?						Yes			No 🗸	NA [
9. v	OA vials have	zero heads	pace?			Yes			No 🗌	No VOA Vials		
10. Were any sample containers received broken?						Yes	es 🗆		No 🗹	# 46		
11 0		k matah hati	tla labala?			Yes			No 🗆	# of preserved bottles checked for pH:		
	oes paperwor Note discrepar)		res	•		NO 🗀		2 or >12 ur	less noted)
12. Are matrices correctly identified on Chain of Custody?						Yes	V		No 🗌	Adjusted?		
3. Is it clear what analyses were requested?						Yes	V		No 🗌			
14. Were all holding times able to be met? (If no, notify customer for authorization.)						Yes	V		No 🗌	Checked by	:	
(1	r no, notiny cus	stomer for a	utnorization.)									
Spe	cial Handlir	ng (if app	licable)									
15. V	Vas client noti	fied of all dis	screpancies v	with this order?		Yes		-	No .	NA 🖸		
	Person N	lotified:		MINISTER PROPERTY AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDR	Date	T	ANN AND AND ASSESSED.		MONEYO CHECKMONING			*
	By Whon	n:			Via:	eMa	ail [Phone	Fax	☐ In Person		
.	Regardin	g: [and a street					
į	Client Ins	structions:			-							
16.	Additional rem	arks:										
17.	Cooler Inform	nation										
	Cooler No	Temp ºC	Condition	Seal Intact	Seal No	Seal Da	ite	Sigr	ned By			
	1	2.4	Good	Yes								



