NMOCD

JUL 0 5 2018

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

DISTRICT 111

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District/III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test		June 28, 2018					DJ SIMMONS			_ AP	0 <u>45-06138</u>				
Property Name	HANSON B COM									Section	36				
Pressure (Shut-	n or Producing) Prod		ucing Tubing		Casing					3					
					INTERMED	IATE TO A	TMOSPH	IERE INDIVIDUALLY	y FO	R 15 MIN		EACH RADENHEAD	INTE	RMEDIA	FE
TESTING	PRESSURES: BRADENHEAD				INTERMEDIATE					DRADENHEAD			INTE	KMEDIA.	I.E.
TIME	ВН	INT	CSG	INT	CSG							FLOWED		FLOV	VED
5 minutes	0		3			i		Steady Flow							
10 minutes	0		3					Surges							+
15 minutes	0		3					Down to Nothing			,	(<i>A A A A A A A A A A</i>
20 minutes					<u> </u>			Nothing							
25 minutes					ļ			Gas					- 6		
30 minutes								Gas & Water							
								Water							
If bradenhead f	lowed wate	r, check all	of the desc	riptions th	at apply bel	ow:									
CLEAR		-	FRESH		SALTY		_	SULFUR _			BL	ACK			
REMARKS:		5 MINUT	E SHUT-IN	BR.	ADENHEAD	0		INTERMEDIATE_		-					
KEWARKS.					1	Blew down to r	othing wi	thin 10 sec.							
-					•										
		··													
															
Ву	Kelvin Fowler						Witne	ess							
	Operator						_								
			(Positi	ion)											