Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

JUL 1 1 2018

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

NMNM18463

| | | | MINIMINITO403 | | | | |
|---|--|---|---|--|--|--|--|
| Do not use ti | RY NOTICES AND REP his form for proposals | n Field Office If Indian, Allottee or Todd Management | ribe Name | | | | |
| abandoned w | ell. Use Form 3160-3 (A | (PD) for such proposa | 15. | | | | |
| SUBMI | T IN TRIPLICATE - Other instr | 7. If Unit of CA/Agreem | 7. If Unit of CA/Agreement, Name and/or No. | | | | |
| 1. Type of Well | | | | | | | |
| | Gas Well Other | | CHACO 2308 04P #150 | 8. Well Name and No. CHACO 2308 04P #150H | | | |
| 2. Name of Operator Enduring Resources, LLC | | | 9. API Well No. 30-045-35497 | 9. API Well No. 30-045-35497 | | | |
| 3a. Address 332 Cr 3100 Aztec, NM 874 | 110 | 3b. Phone No. (include area co 505-636-9743 | | ploratory Area | | | |
| 4. Location of Well <i>(Footage, Sec.</i> SHL: 1312' FSL & 285' FEL SEC BHL: 393' FSL & 228' FEL SEC | 4 23N 8W | | 11. Country or Parish, St San Juan, NM | ate | | | |
| 12. | CHECK THE APPROPRIATE E | OX(ES) TO INDICATE NATU | RE OF NOTICE, REPORT OR OTHER | R DATA | | | |
| TYPE OF SUBMISSION | | TY | PE OF ACTION | | | | |
| Notice of Intent | Acidize | Deepen | ☐Production(Start/Resume) | ☐ Water ShutOff | | | |
| Modice of filterit | ☐ Alter Casing | ☐ Hydraulic Fracturing | Reclamation | ☐ Well Integrity | | | |
| Subsequent Report | Casing Repair | ☐ New Construction | Recomplete | Other | | | |
| | ☐Change Plans | ☐ Plug and Abandon | ☐Temporarily Abandon | AMENDED/ | | | |
| Final Abandonment Notice | Convert to Injection | □Plug Back | ☐ Water Disposal | CORRECTION TO COMPLETION | | | |
| during Resources would like to a reviously reported landing info as (25/14-Land well at 5782' w/ 14.5 | : | | " FN at 5646', 1817ts 6F2.575" T55 42. | 71 5 8ABEUR IN 189 PUR Btal | | | |
| ould have reported landing info | as: | | 11.11 | 1.0.000 | | | |
| 25/14- Landed well at 5782' . RIH | w/ 14.5' KB as follows 1/2 MS, 1 | 85 jts of 2-7/8″ 6.5# J55. Packe | / | VEIELD OFFICE | | | |
| tached is an updated wellbore. | | | Ву: | | | | |
| 14. I hereby certify that the foregoing | ng is true and correct. Name (Pri | nted/Typed) | / | | | | |
| Lacey Granillo | h | Title Permit S | Title Permit Specialist | | | | |
| Signature Signature | 280 | Date 7/11/18 | Date 7/11/18 | | | | |
| | THE SPACE | FOR FEDERAL OR S | STATE OFICE USE | | | | |
| Approved by | | | | | | | |
| | 1 | Title | Da | te | | | |
| Conditions of approval, if any, are certify that the applicant holds leg- which would entitle the applicant to | al or equitable title to those rights | | - | | | | |
| | | | | | | | |



DICTRICT III

NMOCD

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CHACO 2308-04P #150H API # 30-45-35497

| Location | | | | | | Spud Date: | 1/22/2014 | Elevation: 6870' |
|--|---|--|---------------------|------------|-------------|---|---|--|
| SHL: 1312' FSL | 285' FEL | Sec: 4 | Twnshp: 23N | Rge: 8W | | Completion: | 5/25/2014 | County San Juan |
| BHL: 393' FSL | 228' FEL | Sec: 3 | Twnshp: 23N | Rge: 8W | | Pool Name: | NAGEEZI GALLUP | |
| wellbore update | : 7/11/18 lg | | 12 Ho | 1/4" le | | set @ 427' | 9-5/8" 13 jnts 36# J-55 ST8 , float collar @ 392 | _ |
| Tops | MD | TVD | | | | cmt to su | Osx of Type I-II. Circ., 10b rface. | DIS OY |
| Ojo Alamo Kirtland Pictured Cliffs Lewis Chacra Cliff House Menefee Point Lookout Mancos Gallup | 1068' 1275 ' 1660 ' 1776 ' 2083' 3200' 3236 ' 4118' 4337 ' 4700' | 1064 ' 1265 ' 1635 ' 1747 ' 2042' 3115' 3149 ' 3999' 4217 ' 4579 ' | 8 3/ Hole | | X X X | 23#, FC @ 5: (670sx/174b 100sx/23bb | e: 7" csg set @ 5863', 139ts 819'. Cmt'd w/ Lead @ obls) of Halcem, followed by ls) of Varicem. w/ 20bbls of § k to surface. | Tail @ |
| Landed well at 5782 6.5# J55. Packer set | | | /2 MS, 185 jts of | | I | TOL @ 5703'. | Prod Liner: 4 1/2" csg s of N-80 11.6#. LC @ 10 TOL @ 5703'. Cmt'd 380sx of Extend Good Cement to Surfa | 418', RSI @ 10412 ['] , acem. Circ., 20 Bbl |
| | | | Ho | | | | | TD @ 10521' |
| A STATE OF THE PARTY OF THE PAR | End | uring Reso | ources | | | | | PBTD @ 10418. |
| | | | 40" diameter. Frac' | d w/ 14 | | -+++-+ | | ++++-++++++ |
| | stages of 20/40 sa | ind | | | | -+++++ | •+++++++ | -+++-++ |

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018 WELL COMPLETION OR RECOMPLETION REPORT AND LOG 5. Lease Serial No. NMNM-18463 6. If Indian, Allottee or Tribe Name Well ⊠Oil Well Dry Other 1a. Type of Well Hydraulic Fracturing Deepen Work Over Plug Back Diff. Zones b. Type of Completion New Well 7. Unit or CA Agreement Name and No. Other: 8. Lease Name and Well No. Name of Operator Chaco 2308-04P #150H **Enduring Resources, LLC** 9. API Well No. 3a. Phone No. (Include area code) Address 332 Cr 3100 505-636-9743 30-045-35497 Aztec, NM 87410 4. Location of Well (Report location clearly and in accordance with Federal requirements) * 10. Field and Pool or Exploratory NAGEEZI GALLUP AMENDED 11. Sec., T., R., M., on Block and Survey or Area At surface **SEC 4 23N 8W** 12. County or Parish 13. State SHL: 1312' FSL & 285' FEL SEC 4 23N 8W San Juan NM BHL: 393' FSL & 228' FEL SEC 3 23N 8W 16. Date Completed 5/25/14 17. Elevations (DF, RKB, RT, GL)* 15. Date T.D. Reached 14. Date Spudded 6870 D&A Ready to Prod. 1/22/14 4/12/14 MD 20. Depth Bridge Plug Set: 19. Plug Back T.D.: 10418' MD 5222' TVD 18. Total Depth: 10521' MD 5222' TVD TVD 21. Type Electric & Other Mechanical Logs Run (Submit copy of each) 22. Was well cored? **⊠**No Yes (Submit analysis) Was DST run? No Yes (Submit report) Directional Survey? ПNо Form 3160-4 **UNITED STATES** (June 2015) 23. Casing and Liner Record (Report all strings set in well) No. of Sks. & Type of Cement Stage Cementer Depth Slurry Vol. (BBL) Hole Size Size/Grade Wt. (#ft.) Top (MD) Bottom (MD) Cement Top* Amount Pulled 222 36 240 surface 9-5/8", J-55 427' MD 12-1/4" 3180 822 surface 8-3/4" 7".J55 23 5863' MD 4-1/2", N-80 11.6 5703 10500' MD 380 1195 TOL 5703' 6-1/8" 24. Tubing Record Packer Dept (MD) Depth Set (MD) Packer Depth (MD) Size Depth Set (MD) Packer Depth (MD) Size Dept Set (MD) Size 2-7/8",6.5#,L- 5782' 5648' 80 EUE 8rd 26. Perforation Record 25. Producing Intervals No. Holes Perf. Status Тор Bottom Perforated Interval Size Formation GL 14th 5906'-6089' 40 20 GL 13th 6186'-6371' 40 20 GL 12th 6490'-6692" 40 20 GL 11th 6794'-6983' 40 20 GL 10th 7080'-7278' 40 20 GL 9th 7378'-7602' 40 20 GL 8th 7918'-7720' 20 40 GL 7th 8022'-8224' 40 20 GL 6th 8338'-8562' 40 20 GL 5th 8676'-8992' 40 20 GL 4th 9174'-9482' 20 40

9600'-9810'

9932'-10132'

10230'-10382'

40

40

40

20

20

8

GL 3rd

GL 2nd

GL 1st

^{27.} Acid, Fracture, Treatment, Cement Squeeze, Post hydraulic fracturing chemical disclosures on FracFocus.org

| Depth Interval | Amount, Type of Material and Date of Chemical Disclosure upload on FracFocus.org | | | | | | | |
|----------------|--|--|--|--|--|--|--|--|
| 5906'-6089' | GL 14 th stage with 265,000#, 20/40 PSA Sand | | | | | | | |
| 6186'-6371' | GL 13 th stage with 268,301# , 20/40 PSA Sand | | | | | | | |
| 6490'-6692' | GL 12 th stage with 270,300# 20/40 PSA Sand | | | | | | | |
| 6794'-6983' | GL 11 th stage with 268,927#,20/40 PSA Sand | | | | | | | |
| 7080'-7278' | GL 10 th stage with 219,700# , 20/40 PSA Sand | | | | | | | |
| 7378'-7602' | GL 9 th stage with 211,000#,20/40 PSA Sand | | | | | | | |
| 7918'-7720' | GL 8 th stage with 211,140#, 20/40 PSA Sand | | | | | | | |
| 8022'-8224' | GL 7 th stage with 217,200# , 20/40 PSA Sand | | | | | | | |
| 8338'-8562' | GL 6 th stage with 218,160#, 20/40 PSA Sand | | | | | | | |
| 8676'-8992' | GL 5 th stage with 215,049#, 20/40 PSA Sand | | | | | | | |
| 9174'-9482' | GL 4 th stage with 215,810#, 20/40 PSA Sand | | | | | | | |
| 9600'-9810' | GL 3 rd stage with 214,800# , 20/40 PSA Sand | | | | | | | |
| 9932'-10132' | GL 2 nd stage with 217,300# , 20/40 PSA Sand | | | | | | | |
| 10230'-10382' | GL 1st stage with 217,300 # 20/40 PSA Sand | | | | | | | |

| Date First | Test Date | Hours | Test | Oil | Gas | Water | Oil Gravity | Gas | Production Method |
|-------------------------|--------------------------------------|-----------------------|--------------------|------------|-------------|--------------|---------------------------|--------------------------|-------------------|
| Produced 5/29/14 | 5/28/14 | Tested 24 hr | Production | 330 | MCF 3307 | BBL 850 | Corr. API. | Gravity | Flowing |
| Choke Size 48/64" | Tbg. Press. Flwg. SI 680 | Csg. Press. 740 | 24 Hr. Rate | Oil BBL | Gas MCF | Water BBL | Gas/Oil Ratio | Well Status Producing | |
| | iction - Inter | - | | | | | | | |
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | Water BBL | Oil Gravity Corr. API. | Gas Gravity | Production Method |
| Choke Size | Flwg. SI | Csg. Press. | 24 Hr. Rate | Oil BBL | Gas MCF | Water BBL | Gas/Oil Ratio | Well Status | |
| *(See instr | uctions and | spaces for | additional da | ta on pag | ge 2) | | | | |
| 28b. Produ | iction - Inter | val C | | | | | | | |
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | Water BBL | Oil Gravity Corr. API. | Gas Gravity | Production Method |
| Choke Size | Tbg. Press. Flwg. SI | Csg. Press. | 24 Hr. Rate | Oil BBL | Gas MCF | Water BBL | Gas/Oil Ratio | Well Status | |
| 28c. Produ | iction - Inter | val D | | 1 | | | | | |
| Date First Produced | Test Date | Hours Tested | Test Production | Oil BBL | Gas MCF | Water BBL | Oil Gravity Corr. API. | Gas Gravity | Production Method |
| Choke Size | Tbg. Press. Flwg. SI | Csg. Press. | 24 Hr. Rate | Oil BBL | Gas MCF | Water BBL | Gas/Oil Ratio | Well Status | 1 |
| 28. Dispos | ition of Gas | (Solid, us | sed for fuel, ve | nted, etc. | .) | | | | |

Show all important zones of porosity and contents thereof: Cored intervals and all drill-stem tests, including depth interval tested, cushion used, time tool open, fl and shut-in pressures and

recoveries.

| | Ton Dottom | | D | | N | Тор | | | | |
|--|------------------|---------------------|------------------------------------|-----------------------|---|-------------|--|--|--|--|
| Formation | Тор | Bottom | Descriptions, Cont | tents, etc. | Name | Meas. Depth | | | | |
| OJO ALAMO | 994 | 1064 | | | | | | | | |
| KIRTLAND | 1205 | 1265 | | | | | | | | |
| PICTURED CLIFFS | 1687 | 1635 | | | | | | | | |
| LEWIS | 1820 | 1747 | | | | | | | | |
| CHACRA | 2115 | 2042 | | | | | | | | |
| CLIFF HOUSE | 3250 | 3115 | | | | | | | | |
| MENEFEE | 3001 | 3149 | | | | | | | | |
| POINT LOOKOUT | 4112 | 3999 | | | | | | | | |
| GL | 4389 | 4217 | | | | | | | | |
| GALLUP | 4757 | 4579 | | | | | | | | |
| | | | | | | | | | | |
| 32. Additional remark | s (include plu | gging procedu | re). | | | | | | | |
| | | | acing a check in the appropriate b | hoves: | | | | | | |
| Electrical/Mecha | | | | DST Report | ☑Directional Survey | | | | | |
| | | | Geologic Report | | MDirectional Survey | | | | | |
| Sundry Notice fo | r plugging and c | cement verification | on Core Analysis | Other: | | | | | | |
| | | | | | | | | | | |
| 34 I hereby certify th | at the foregoin | ng and attached | d information is complete and cor | rect as determined fi | rom all available records (see attached instruc | tions) * | | | | |
| 34. I hereby certify that the foregoing and attached information is complete and correct as determined from all available records (see attached instructions) * Name (please print) Lacey Granillo Title Permit Specialist | | | | | | | | | | |
| Signature Date 7/11/18 | | | | | | | | | | |
| | | 71 |) | | | | | | | |
| | | | , | | | | | | | |
| | | V | | | | | | | | |