Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

| SUNDRY NOTICES AND REPORTS ON WELLS | |
|---|---|
| Do not use this form for proposals to drill or to re-enter an | 7 |
| abandoned well. Use form 3160-3 (APD) for such proposal | c |

| Bi | UREAU OF LAND MANA | GEMENT | | | 5. Lease Serial No. | | | | |
|---|--|-------------------------------------|--|------------------|--|------------------------|--|--|--|
| | NOTICES AND REPO | | | | NMNM120380 | | | | |
| Do not use thi abandoned wel | s form for proposals to II. Use form 3160-3 (APL | drill or to re D) for such p | -enter an proposals. | | 6. If Indian, Allottee o | r Tribe Name | | | |
| SUBMIT IN T | TRIPLICATE - Other inst | ructions on | page 2 | | 7. If Unit or CA/Agree | ement, Name and/or No. | | | |
| Type of Well | ner | | - Name of the second | | 8. Well Name and No. BOLT 1 | | | | |
| Name of Operator DUGAN PRODUCTION COR | 9. API Well No. 30-045-35790-00-X1 | | | | | | | | |
| 3a. Address 709 E MURRAY DRIVE FARMINGTON, NM 87499 | | 3b. Phone No Ph: 505.32 | . (include area code) 5.1821 | | 10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL | | | | |
| 4. Location of Well (Footage, Sec., T | ., R., M., or Survey Description) |) | | | 11. County or Parish, S | State | | | |
| Sec 10 T23N R10W SENW 17 36.243660 N Lat, 107.887085 | | | | | SAN JUAN COL | JNTY, NM | | | |
| 12. CHECK THE AF | PPROPRIATE BOX(ES) | TO INDICA | TE NATURE OI | F NOTICE, | REPORT, OR OTH | IER DATA | | | |
| TYPE OF SUBMISSION | | | TYPE OF | ACTION | | | | | |
| □ Notice of Intent | ☐ Acidize | ☐ Dee | pen | ☐ Product | ion (Start/Resume) | ☐ Water Shut-Off | | | |
| ☐ Notice of Intent | ☐ Alter Casing | ☐ Hyd | raulic Fracturing | ☐ Reclama | ation | ☐ Well Integrity | | | |
| Subsequent Report | ☐ Casing Repair | □ New | Construction | ☐ Recomp | lete | Other | | | |
| ☐ Final Abandonment Notice | ☐ Change Plans | Plug | and Abandon | ☐ Tempor | arily Abandon | Drilling Operations | | | |
| 68 | ☐ Convert to Injection | ☐ Plug | Back | ☐ Water D | Disposal | | | | |
| following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fi Supplemental information for tattached. | pandonment Notices must be file in al inspection. | ed only after all | requirements, includi | ing reclamation | n, have been completed a | nd the operator has | | | |
| | | | | | | | | | |
| | | | | | | 1000 | | | |
| | | | | | 17 | MOCD 23 2018 | | | |
| | | | | | JUL | 2 3 2018 | | | |
| | | * | | | DIST | RICT III | | | |
| 14. I hereby certify that the foregoing is | true and correct. Electronic Submission #4 For DUGAN PRODUC mmitted to AFMSS for proc | CTION CORP | DRATION, sent to | the Farming | iton | | | | |
| Name (Printed/Typed) ALIPH RE | | | | | RING SUPERVISOR | 2 | | | |
| | | | | | | | | | |
| Signature (Electronic S | ubmission) | | Date 07/17/20 | 018 | | | | | |
| | THIS SPACE FO | R FEDERA | L OR STATE | OFFICE US | SE | | | | |
| Approved By ACCEPT | Parent Property Prope | | JACK SAV TitlePETROLE | AGE UM ENGINE | EER | Date 07/18/2018 | | | |
| Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu | itable title to those rights in the | | Office Farmingt | ton | | | | | |
| Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s | U.S.C. Section 1212, make it a catalements or representations as | crime for any pe to any matter w | rson knowingly and ithin its jurisdiction. | willfully to ma | ke to any department or | agency of the United | | | |



COMPANY MAN

HALLIBURTON

iCem[®] Service

DUGAN PRODUCTION CORP-EBUS

For: MARTY FOUTZ
Date: Thursday, July 12, 2018

DUGAN Job Date: Friday, July 13, 2018

Sincerely,
LEMONT JOJOLA

Cementing Job Summary

| | | | | | | | | | ith Safety | | | | | | | |
|-------------|-------------------------------|-----------------|-----------------------|--|-----------------------------|--|---|---|--|--|------------|------------------------------------|----------------|--|-------|-------|
| Sold To #: | | | | p To #: | 388803 | | Quo | te #: 002 | 2462472 | | - | Orde | #: 090 | 4992346 | | |
| Customer: | DUGAN | PRODU | JCTIO | CORP | -EBUS | | Cust | tomer Re | p: MARTY | FOUTZ | | | | | | |
| Nell Name | | | | | - Inches and the sandgarden | ell #: 1 | | | A. Carrier and Car | APLUW | | 30-045 | -35790 | -00 | | |
| ield: BAS | | LAND | City (S | AP): NA | GEEZI | Co | ounty/Pari | sh: SAN | JUAN | Annual Property and Personal Property and Pe | | ASSESSMENT OF THE PERSONS NAMED IN | MEXIC | The section is not a second or the second | | |
| COAL | | | , , | | | | | | | | | | | | | |
| Legal Des | cription: | 10-23N | -10W-1 | 772FNL | -1669F | WL | | | k9 | | | - | | and the same of th | | |
| Contracto | | | | | | | Platform N | lame/Nur | m: D&D 1 | | | | | | | |
| Job BOM: | The second name of the second | 3 | - | | | 1 0 | | | | | | | | | | |
| Vell Type: | | | | The state of the s | - | T | | | | | - | | | | | |
| Sales Pers | | | | 2823 | - | Spyc | Supervise | or Lemo | nt Joinla | | - | | | | | |
| 30103 1 613 | 1011. 1 1/12/ | MAICINIC | DAN IAZ | 2020 | 98.7 mm. 1 | DIVE | Job | Or. Lenio | The bojoica | TEROTO LINE | Vigin H | | | | | |
| | 100 | | | | | | JUD | | | Company Company | | | Parallel Barre | | | |
| ormation | Name | 1 | - | | | | | | | | | | | | | |
| ormation | 7 | 1 | Тор | | | | Bottom | | T | | | | | - | | |
| orm Type | Sopul (IIIO | | . op | | - | in the same of the | BHST | | | | | | - | | | |
| ob depth ! | MD | | 1150ft | | - | | Job Depth | TVD | - | | - | | | | | |
| Vater Dept | | | . 1001 | | | | Wk Ht Abo | | | | | | | | | |
| Perforation | | 2) | From | | | | To | | | | - | | | | | |
| 2110/840/11 | Sober line | | 10111 | | | | | | 1 | | | | - | | | |
| | | - | - | 4 | | | Well Data | 3 | | - | - | | | | | |
| Descrip | tion | New/L | lsed | Size | ID Wel | | A THE RESERVE THE PARTY OF THE | Grade | Top | MD | Botton | Top | Botton | | | |
| Doddilp | 14047 | | in in | | | lbm/ft | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | -125 | ft | | MD | TVD | TVD | | |
| | | | | | | | | | | 1 | | ft ft | | ft | | |
| Casing | | | | 8.625 | 8.097 | 24 | | STC | J-55 J-55 | 0 | | 120 | | | | |
| Casing | | | | 5.5 | 4.95 15.5 | | 1 | LTC | | 0 | | | | | | |
| Open Hole S | Section | | | | 7.875 | | | | | 120 | 120 | | | | | |
| | | | | | | | | | | | | | | | | |
| | - | - | | | | | | | | | | | - | | | |
| | | | | | | THE RESERVE TO SHARE THE PARTY OF THE PARTY | and Acce | ssories | | | | | | | | |
| Type | Siz | 8 | Qty | Make | Depti | 1 | | | Type | 5 | Size | | Qty | Make | | |
| | in | | | | ft | | | | | | in | - | | 1100 | | |
| Suide Shoe | CHL-1911 | | | | 1215 | | | | Top Plug | | 5.5 | _ | | HES | | |
| loat Shoe | 5.5 | | | | - | | | | Bottom Plu | | 5.5 | | | HES | | |
| loat Collai | | | | | + | 100 | | | SSR plug s | The second secon | 5.5 | - | 4 | HES | | |
| nsert Float | | | | | - | | | | lug Conta | | 5.5 5.5 | - | 1 | HES | | |
| Stage Tool | 5.5 | | | | | | | | Centralizers | 5 | 5.5 | | | HES | | |
| | | | | | | | - | | | - | | | | | | |
| | | Province sheets | in the second | i ligarithad | | | Fluid Data | | | | Winter Co. | | | | | |
| Stage/Plug | - 4. A | | | | | | Linia Dag | а | | | | | | | | |
| arana Lini | y #. 1 | | | | | | | | | | | | | | | |
| | Stage T | vna T | | Elula 4 | lame | 1 | Qty | T Ohy Hal | M Mixing | Viold | 8.1 | lix I | Rate | Total Mix | | |
| Fluid# | Stage Type | | Stage Type Fluid Name | | | riuid r | 18(110 | | City | City Uoi | Density | ft3/sack | | | bl/mi | Fluid |
| Fluid# | | | | | | | | | ibm/gal | | | al | n | Gai | | |
| Fluid # | | F - 1 10/4 | | | | - | 10 | bbl | 8.33 | - | - | - CAT | 5 | Jai | | |
| | Eroch M | latos | E _r | och Malak | or Conne | | 10 | 1 13131 | 0.33 | 1 | 1 | - 1 | 0 | | | |
| Fluid# | Fresh W | | Fre | sh Wate | er Space | er | | 55. | 1 | 1 | 1 | - 1 | | | | |
| | Fresh W Space | | Fre | sh Wate | er Space | er | |] | | | | | | - | | |
| | | | Fre | esh Wate | er Space | er | | | | | | | | | | |
| 1 | Space | er | Fre | | | er | | | M Mivin- | Viola | 1 11 | Alw I | Pate | Total Miss | | |
| | | er | Fre | Fluid 1 | | er | Qty | Qty Uol | | | | 1 | Rate | | | |
| 1 | Space | er | Fre | | | er | | | Density | ft3/sack | FI | uld b | bl/mi | Fluid | | |
| 1 | Space | ype | | | lame | | | | Density Ibm/gal | ft3/sack | FI | 1 | | Total Mix Fluid Gal 10.07 | | |

Cementing Job Summary

| 1 | 0.07 Gal | | FRESH WATER | | | | | | | | | |
|---------|----------------|-----------|------------------------|-----------------|-----------|------------------------------|-------------------|---------------------|---|---------------------------|--|--|
| | | | | | | | | | | | | |
| Fluld # | Stage Type | | Fluid Name | Qty | Qty UoM | Mixing Density Ibm/gal | Yield ft3/sack | Mix Fluid Gal | Rate bbl/mi n | Total Mix Fluid Gal | | |
| 3 | Tail Cemer | t HALO | CEM (TM) SYSTEM | 100 | sack | 13,5 | 1.38 | | 5 | 5.85 | | |
| 5 | 5.85 Gal | | | | FRESH W | ATER | A | | - | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Fluid # | Stage Type | | Fluid Name | Qty | Qty UoM | Mixing Density Ibm/gai | Yleid ft3/sack | Mix Fluid Gal | Rate bbl/mi | Total Mix Fluid Gal | | |
| 4 | Displaceme | nt | Displacement | 28 | bbl | 8.33 | | | 5 | | | |
| | | | | (Charles of the | | er de le co | | | | | | |
| Cement | Left In Pipe | Amount | ft | | Reason | - | | | Shoe Join | t | | |
| | Mix Water: | pH ## | Mix Water Chloride: | Mix Water## ppm | | | | | Mix Water Temperature:## °F °C | | | |
| Cemen | t Temperature: | ## °F °C | Plug Displaced by: | # lb/gal k | g/m3 XXXX | D | sp. Temp | erature: | ## °F °C | | | |
| | Plug Bumped? | Yes/No | Bump Pressure: | | | | Float | s Held? | Yes/No | | | |
| Ce | ment Returns: | ## bbl m3 | Returns Density: | | | Retu | rns Temp | erature: | ## °F °C | | | |
| omment | 1 | | | * | | | | | *************************************** | | | |

Summary Report

Sales Order #: 0904992346 Crew: 0904992346 WO #: PO#: NA Job Start Date: 07/12/2018 06 00 PM AFE#: NA

Customer:

DUGAN PRODUCTION CORP-

EBUS

UWI / API Number: 30-045-35790-00

Well Name:

BOLT

Well No:

BASIN FRUITLAND COAL Job Type:

CMT PRODUCTION

CASING BOM

County/Parish: State:

SAN JUAN **NEW MEXICO**

Service Supervisor: Lemont Jojola

1

Latitude:

Field:

36,243660

Cust Rep Name:

MARTY FOUTZ

Longitude: Sect / Twn / Rng: 10/23/10

-107.887083

Cust Rep Phone #:

| Remarks: | | | | | | | | | |
|--|---|------|--|--|--|--|--|--|--|
| | | | | | | | | | |
| The Information Stated Herein Is Correct | Customer Representative Signature Customer Representative Printed Name | Date | | | | | | | |

Customer: DUGAN PRODUCTION CORP-EBUS

Job: PRODUCTION Case: DUGAN | SO#: 904992346

2.0 Real-Time Job Summary

| Job Eve | ent Log | | | | | | | | | | |
|---------|-------------|-------------------------------|-------------------------------|-----------|----------|--------|---------------------------|------------------------|------------------------------|--------------------------|---|
| Туре | Seq. No. | Activity | Graph Label | Date | Time | Source | PS Pump Press (psl) | DH Density (ppg) | PS Pump Rate (bbl/min) | Pump Stg Tot (bbl) | Comments |
| Event | 1 | Call Out | Call Out | 7/12/2018 | 13:00:00 | USER | | | | | CEMENT CREW CALLED OL |
| Event | 2 | Depart Yard Safety Meeting | Depart Yard Safety Meeting | 7/12/2018 | 14:50:00 | USER | | 20,000,000 | | | SAFETY MEETING HELD WITH CEMENT CREW |
| Event | 3 | Depart Home for Location | Depart Home for Location | 7/12/2018 | 15:00:00 | USER | | | | | 1-PICKUP 11583927, 1- RE TIGER 12638114, 1- BULK TRUCKS 11338219 - 10001398 |
| Event | 4 | Arrive At Loc | Arrive At Loc | 7/12/2018 | 16:00:00 | USER | | | | | CEMENT CREW ARRIVES O |
| Event | 5 | Comment | Comment | 7/12/2018 | 16:05:00 | USER | | | | | RIG AND CASING CREW AF RUNNING IN HOLE WITH CASING AT TIME OF ARRIVAL |
| Event | 6 | Other | Tubulars | 7/12/2018 | 16:10:00 | USER | | | | | TD = 1215 FT, TP = S 1/2" 15.5# SET @ 1215 FT, S1 = 56.7 FT, OH = 7 7/8", SURFACE = 8 5/8" 24# SET @ 126" |
| Event | 7 | Other | Water Test | 7/12/2018 | 16:15:00 | USER | | | | | TEMPERATURE = 60 DEGREES, CHLORIDES = 0, PH = 7 |
| Event | 8 | Pre-Rig Up Safety Meeting | Pre-Rig Up Safety Meeting | 7/12/2018 | 18:15:00 | USER | | | | | SAFETY MEETING HELD WITH CEMENT CREW |
| Event | 9 | Rig-Up Equipment | Rig-Up Equipment | 7/12/2018 | 18:20:00 | USER | | | | | CEMENT CREW RIGS UP EQUIPMENT |
| Event | 10 | Pre-Job Safety Meeting | Pre-Job Safety Meeting | 7/12/2018 | 18:44:03 | USER | -45.00 | -0.97 | 0.00 | 0.00 | SAFETY MEETING HELD WITH EVERYONE ON LOCATION |

iCem Service

(v. 4.5.139)

Created: Thursday, July 12, 2018

Customer: DUGAN PRODUCTION CORP-EBUS

Job: PRODUCTION

Case: DUGAN | 50#: 904992346

| Event | 11 | Start Job | Start Job | 7/12/2018 | 18:52:14 | COM5 | -22.00 | 8.31 | 0.00 | 0 00 | |
|-------|----|------------------------------|------------------------------|-----------|----------|------|---------|-------|------|-------|---|
| Event | 12 | Pressure Test | Pressure Test | 7/12/2018 | 19:15:58 | USER | 3079.00 | 8.38 | 0.00 | 1.90 | PRESSURE TEST GOOD TO 2700 PSI |
| Event | 13 | Check Weight | Check Weight | 7/12/2018 | 19:23:21 | COM5 | 2543.00 | 8.46 | 0.00 | 1.90 | CHECK CEMENT WEIGHT = 12.4# |
| Event | 14 | Pump Spacer | Pump Spacer | 7/12/2018 | 19:24:12 | USER | 9.00 | 8.29 | 0.00 | 0.00 | PUMPED 10 BBLS H20 |
| Event | 15 | Pump Cement | Pump Lead Cement | 7/12/2018 | 19:27:15 | USER | 117.00 | 11.80 | 4.10 | 1.00 | 145 SKS 1.95 CUFT/SK 10.07 GAL/SK = 50.4 BBLS @ 12.4# 34.8 BBLS H2O REQ |
| Event | 16 | Pump Tall Cement | Pump Tall Cement | 7/12/2018 | 19:40:26 | USER | 49.00 | 13.38 | 4.10 | 4.20 | 100 SKS 1.38 CUFT/SK 5.85 GAL/SK = 24.6 BBL5 @ 13.5# 14 BBL5 H2O REQ |
| Event | 17 | Check Weight | Check Weight | 7/12/2018 | 19:44:06 | COM5 | 84.00 | 13.79 | 4.10 | 19.10 | CHECK CEMENT WEIGHT = 13.5# |
| Event | 18 | Cement Returns to Surface | Cement Returns to Surface | 7/12/2018 | 19:47:02 | USER | 105.00 | 13.52 | 4.10 | 31.10 | CALCULATED 35 BBLS OF CEMENT BACK TO SURFACE, ACTUALLY CIRCULATED 28 BBLS OF CEMENT BACK TO SURFACE |
| Event | 19 | Shutdown | Shutdown | 7/12/2018 | 19:47:37 | USER | 109.00 | 13.53 | 4.10 | 33.40 | SHUTDOWN DROP PLUG |
| Event | 20 | Pump Displacement | Pump Displacement | 7/12/2018 | 19:56:36 | USER | 376.00 | 8.38 | 2.40 | 22.40 | CALCULATED 27.6 BBLS TO DISPLACE CEMENT, ACTUALLY PUMPED 28 BBLS TANK TO TANK MARK TO MARK |
| Event | 21 | Bump Plug | Bump Plug | 7/12/2018 | 19:58:12 | USER | 695.00 | 8.38 | 2.30 | 26.30 | CALCULATED 630 PSI TO LAND PLUG, PLUG BUMPED @ 440 PSI PRESSURED UP TO 1100 PSI |
| Event | 22 | Check Floats | Check Floats | 7/12/2018 | 19:59:35 | USER | 133.00 | 8.35 | 0.00 | 26.30 | CHECK FLOATS, FLOATS HELD 1/2 BBLS BACK |
| Event | 23 | Shutdown | Shutdown | 7/12/2018 | 20:00:22 | USER | 7.00 | 8.34 | 0.00 | 26.30 | SHUTDOWN END JOB, THANK YOU FOR CHOOSING HALLIBURTON LEMONT |

iCem Service

(v. 4.5.139) Created: Thursday, July 12, 2018


Customer: DUGAN PRODUCTION CORP-EBUS

Job: PRODUCTION

Case: DUGAN | SO#: 904992346

| | | | EW |
|--|--|--|----|
| | | | |
| | | | |

| Event | 24 | Pre-Rig Down Safety Meeting | Pre-Rig Down Salety Meeting | 7/12/2018 | 20:10:00 | USER | 68.00 | 8.75 | 3.30 | 8.60 | SAFETY MEETING HELD WITH CEMENT CREW |
|-------|----|-----------------------------------|-----------------------------------|-----------|----------|------|-------|------|------|------|---|
| Event | 25 | Rig-Down Equipment | Rig-Down Equipment | 7/12/2018 | 20:15:00 | USER | | | | | CEMENT CREW RIGS DOWN EQUIPMENT |
| Event | 26 | Depart Location Safety Meeting | Depart Location Safety Meeting | 7/12/2018 | 20:30:00 | USER | | | | | SAFETY MEETING HELD WITH CEMENT CREW |
| Event | 27 | Depart Location | Depart Location | 7/12/2018 | 20:45:00 | USER | | | | | CENEMT CREW DEPARTS LOCATION |



PS Pump Press (psi) DH Density (ppg) PS Pump Rate (bbl/min) Pump Stg Tot (bbl)

19:38:00

Actual Time (UTC-06:00:00)

▼ HALLIBURTON | iCem® Service

Created: 2018-07 12 10.46-42 (HTC-06-00), Version: 4 5 139

19:54:40

7/12/2018

19:21:20

7/12/2018

19:29:40

19:46:20