District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL	LL OR TO DEEPEN OR PLUG BACK TO A PERMIT" (FORM C-101) FOR SUCH	Form C-103 Revised July 18, 2013 WELL API NO. NM 30-045-35634 / CO 05-067-09924 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. FEE 7. Lease Name or Unit Agreement Name Allison Unit Com 8. Well Number 138H	
2. Name of Operator HILCORP ENERGY COMPANY		9. OGRID Number 372171	
 Address of Operator 382 Road 3100, Aztec NM 87410 		10. Pool name or Wildcat Basin Fruitland Coal- COLORADO	
4. Well Location Unit Letter C 176 feet from the N line and 2615 feet from the W line Section 8 Township 32N Range 6W NMPM County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6134' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Reported on Casing & Cement Sundry 7/7/2018: RAN 92 JTS OF 4.5' 11.6# N-80 LINER W/BOL @ 6294', TOL @ 2889.8".			
7/9/2018: MIRU ND WH. NU BOP. PULL HANGER. RIH W/2 7/8" TBG AND 6 ¼" BIT TO 2903'. TAG COMPOSITE PLUG. PULLED UP ABOVE WINDOW TOP @ 2884'. SWI. SL. SDFN.			
Spud Date: 4/23/2018	Rig Release Date: 7/7/2018	DISTRICT III	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Manchaller TITLE Operations / Regulatory Technician DATE 7/25/2018			
Type or print name Amanda Walker E-mail address: mwalker@hilcorp.com PHONE: 505-324-5122 For State Use Only Deputy Oil & Gas Inspector, PHONE: 505-324-5122			
APPROVED BY: Brand Godl Conditions of Approval (if any):	TITLE District #3	DATE 7/30/18	

-	
0	
-	
0	-

ÀPI: NM'30-045-35634 / CO 05-067-09924 Completion Sundry

7/10/2018: TIH TO COMPOSITE PLUG @ 2903' W/6 ¼" DRILL BIT. RU POWER SWIVEL. DRILL UP COMPOSITE PLUG. DRILLED OUT PLUG IN 60 MINUTES. PUSHED PLUG REMAINS DOWN TO 2946'. DISCUSSED DO DEPTH W/ENGINEER. AGREED 2946' WOULD BE FINAL DEPTH. RD POWER SWIVEL. TIH W/87 JTS, 2 7/8", 6.5# L-80 TBG. LANDED @ 2903'. ND BOP. NU WH. FUNCTION TEST ROD PUMP. TEST GOOD. RIH W/3/4" GUIDED RODS AND PUMP TO A DEPTH OF 2425'. PUMP, 2 ½"X1 ¾"X10'X14' RHAC-Z HVR. SWI. SL. SDFN.

7/11/2018: RIH W//2 1/2" X 1- 3/4" X 10' X 14' RHAC-Z-HVR INSERT PUMP. 1" X 1' LIFT SUB. 3/4" X 8' GUIDED ROD SUB. 21K JWD SHEAR TOOL. 113 GUIDED 3/4" SUCKER RODS. 3/4" PONY RODS 2',4',6' 8'. 1-1/4" X 22' POLISH ROD. LAND PUMP IN 2.280 ID SN AT A DEPTH OF 2876'. PUMP HAS 1"X1' STRANER NIPPLE ON BOTTOM.RODS & PUMP. LND PUMP @ 2876'. PT TBG TO 600PSI. TEST GOOD. SPACE PUMP OUT. LEFT WELL SI.

RDMO @1000hrs ON 7/11/2018.