RECEIVED

Form 3160-5					
(June 2015)	UNITED STATES DEPARTMENT OF THE INTERIOR FEB 12 20 BUREAU OF LAND MANAGEMENT		OI Expi	FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.	
ł					
SUNDRY NOTICES AND REPORTS ON WELLS on Field			6. If Indian, Allottee or	Office 6. If Indian, Allottee or Tribe Name	
Do not use t	his form for proposals	to drill or to re-enter a APD) for such proposa	agement		
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well			7. If Unit of CA/Agr NMNM 135216A	7. If Unit of CA/Agreement, Name and/or No. NMNM 135216A	
	Gas Well Other			8. Well Name and No.	
2. Name of Operator			W Lybrook Unit 746H 9. API Well No.	1	
WPX Energy Production, LLC 3a. Address 3b. Phone No. (include area code)			30-045-35751 (10) Field and Pool or	30-045-35751 10. Field and Pool or Exploratory Area	
PO Box 640 Aztec, NM 874	410	505-333-1816	Lybrook Mancos W	Exploratory rated	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1311' FSL & 2284' FEL, Sec 7, T23N, R8W BHL: 333' FSL & 2027' FEL, Sec 17, T23N, R8W			11. Country or Parish, State San Juan, NM		
12.	CHECK THE APPROPRIATE H	BOX(ES) TO INDICATE NATUR	RE OF NOTICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water ShutOff	
l	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete Temporarily Abandon	Other Completion	
Final Abandonment Notice	Convert to Injection	Plug and Abandon Plug Back	Water Disposal	<u>comprenen</u>	
give subsurface locations and measured and true	vertical depths of all pertinent markers and z the involved operations. If the operation res	ones. Attach the Bond under which the world		s to deepen directionally or recomplete horizontally, e with BLM/BIA. Required subsequent reports mus nce testing has been completed. Final Abandonment	
Notices must be filed only after all requirements is ready for final inspection.)	, including reclamation, have been complete	ed and the operator has detennined that the si	ite NM	OCD	
Notices must be filed only after all requirements is ready for final inspection.) 22/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730	@ 6,500#s for 30 Min GOOD ' RSI TOOL with 8, 0.35" hole	ed and the operator has detennined that the si TEST S.	FEB 7	8 2018	
Notices must be filed only after all requirements is ready for final inspection.) 22/15/17- Perf MC 1 st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, pu Rig up, Run in hole with RBP, w/	@ 6,500#s for 30 Min GOOD ' RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate	ed and the operator has detennined that the si TEST S. e @ 4100 psi avg. Shut down	pumps for 10 min shut down tim	8 2018	
Notices must be filed only after all requirements, is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate V 5' perforated sub attached t	ed and the operator has detennined that the si TEST S. e @ 4100 psi avg. Shut down o bottom of the plug, & set p	pumps for 10 min shut down tim ressure gauges to Start DFIT	8 2018 C T I I I e. Pressure bled off to 399 psi.	
Notices must be filed only after all requirements is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, pu Rig up, Run in hole with RBP, w/ RD 12/16/17-1/6/18 - Monitor DFIT	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate / 5' perforated sub attached t	ed and the operator has detennined that the si TEST s. e @ 4100 psi avg. Shut down bottom of the plug, & set p s. FEB 2 2 2018 RMINGTON FELD OFF	pumps for 10 min shut down tim ressure gauges to Start DFIT	8 2018	
Notices must be filed only after all requirements is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, pu Rig up, Run in hole with RBP, w/ RD 12/16/17-1/6/18 - Monitor DFIT	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate 5' perforated sub attached T TOOH, w/ down hole gauge	ed and the operator has detennined that the side of TEST s. e @ 4100 psi avg. Shut down 6 bottom of the plug, & set p rs. FEB 2 2 2018 RMINGTON FELD OFF	pumps for 10 min shut down tim ressure gauges to Start DFIT	8 2018 C T I I I e. Pressure bled off to 399 psi.	
Notices must be filed only after all requirements is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, put Rig up, Run in hole with RBP, w/ RD 14. J hereby certify that the foregoin 14. I hereby certify that the foregoin	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate 5' perforated sub attached T TOOH, w/ down hole gauge	ed and the operator has detennined that the side of TEST s. e @ 4100 psi avg. Shut down o bottom of the plug, & set p s. FEB 2 2 2018 RMINGTON FELD OFF	pumps for 10 min shut down tim ressure gauges to Start DFIT	C T L L e. Pressure bled off to 399 psi.	
Notices must be filed only after all requirements is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, pu Rig up, Run in hole with RBP, w/ RD 12/16/17-1/6/18- Monitor DFIT 1/7/18-MIRU 14. I hereby certify that the foregoin Lacey Granillo	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate 5' perforated sub attached T. TOOH, w/ down hole gauge FA By ng is true and correct. Name (Pri	ed and the operator has detennined that the side of TEST s. e @ 4100 psi avg. Shut down o bottom of the plug, & set p rs. FEB 2 2 2018 RMINGTOR FELD OFF inted/Typed Title Permit To	tie FEB a pumps for 10 min shut down tim ressure gauges to Start DFIT FICE ech III	8 2018 C T I I I e. Pressure bled off to 399 psi.	
Notices must be filed only after all requirements is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1 st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, put Rig up, Run in hole with RBP, w/ RD 14. I hereby certify that the foregoint Lacey Granillo	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate 5' perforated sub attached T. TOOH, w/ down hole gauge FA By ng is true and correct. Name (Pri	ed and the operator has detennined that the side of TEST s. e @ 4100 psi avg. Shut down 6 bottom of the plug, & set p s. FEB 2 2 2018 RMINGTON FELD OFF mited/Typed/ Title Permit To Date 2/12/18	tie FEB a pumps for 10 min shut down tim ressure gauges to Start DFIT FICE ech III	8 2018 C T I I I e. Pressure bled off to 399 psi.	
Notices must be filed only after all requirements is ready for final inspection.) 12/15/17- PSI Test 4-1/2 Casing Perf MC 1st stage, 13726'-13730 MIRU for DFIT Pressure up, open toe sleeve, pt Rig up, Run in hole with RBP, w/ RD 12/16/17-1/6/18- Monitor DFIT 1/7/18-MIRU 14. I hereby certify that the foregoin Lacey Granillo Signature	@ 6,500#s for 30 Min GOOD V RSI TOOL with 8, 0.35" hole umping DFIT @ 5 bbl min rate 5' perforated sub attached T. TOOH, w/ down hole gauge FA By ng is true and correct. Name (Pri	ed and the operator has detennined that the side of TEST s. e @ 4100 psi avg. Shut down 6 bottom of the plug, & set p s. FEB 2 2 2018 RMINGTON FELD OFF mited/Typed/ Title Permit To Date 2/12/18	tie FEB a pumps for 10 min shut down tim ressure gauges to Start DFIT FICE ech III	B 2018 C F F I I I I I I I I I I	



W Lybrook Unit 746H

1/8/18- PSI Test All Lines Up To 9,500 Lbs, Test Good

Frac MC 1st stage 13726'-13730' - 20, 0.35" holes, 1st stage with 50700 # 20/40 PSA Sand Perf 2nd stage 13522'-13676'-with 20, 0.35" holes. Frac MC 2nd stage with 204,000#, 20/40 PSA Sand Perf 3rd stage 13318'-13472'- with 20, 0.35" holes. Frac MC 3rd stage with 206,500#, 20/40 PSA Sand 1/9/18-Perf 4th stage 13114'-13268'- with 20, 0.35" holes. Frac MC 4th stage with 206,000#, 20/40 PSA Sand Perf 5th stage 12910'-13064'-with 20, 0.35" holes. Frac MC 5th stage with 204,900#, 20/40 PSA Sand Perf 6th stage 12706'-12860'- with 20, 0.35" holes. Frac MC 6th stage with 204,900#, 20/40 PSA Sand 1/10/18-Perf 7th stage 12502'-12656'- with 20, 0.35" holes. Frac MC 7th stage with 205,200#, 20/40 PSA Sand Perf 8th stage 12298'-12452'- with 20, 0.35" holes. Frac MC 8th stage with 204,900#, 20/40 PSA Sand Perf 9th stage 12093'-12248'- with 20, 0.35" holes. Frac MC 9th stage with 204,500#, 20/40 PSA Sand Perf 10th stage 11890'-12044'- with 20, 0.35" holes. Frac MC 10th stage with 204,000#, 20/40 PSA Sand Perf 11th stage 11686'-11840'- with 20, 0.35" holes. Frac MC 11th stage with 204,900#, 20/40 PSA Sand 1/11/18-Perf 12th stage 11482'-11636'- with 20, 0.35" holes. Frac MC 12th stage with 204,600#, 20/40 PSA Sand Perf 13th stage 11278'-11432'- with 20, 0.35" holes. Frac MC 13th stage with 205,500#, 20/40 PSA Sand Perf 14th stage 11074'-11228'- with 20, 0.35" holes. Frac MC 14th stage with 205,500#, 20/40 PSA Sand Perf 15th stage 10870'-11024'- with 20, 0.35" holes. Frac MC 15th stage with 205,200#, 20/40 PSA Sand 1/12/18-Perf 16th stage 10666'-10820'- with 20, 0.35" holes. Frac MC 16th stage with 203,900#, 20/40 PSA Sand Perf 17th stage 10462'-10616'- with 20, 0.35" holes. Frac MC 17th stage with 204,700#, 20/40 PSA Sand Perf 18th stage 10258'-10412'- with 20, 0.35" holes. Frac MC 18th stage with 205,700#, 20/40 PSA Sand Perf 19th stage 10054'-10208'- with 20, 0.35" holes. Frac MC 19th stage with 204,800#, 20/40 PSA Sand 1/13/18-Perf 20th stage 9850'-10004'- with 20, 0.35" holes. Frac MC 20th stage with 204,900#, 20/40 PSA Sand Perf 21st stage 9646'-9800'- with 20, 0.35" holes. Frac MC 21st stage with 206,000#, 20/40 PSA Sand Perf 22nd stage 9442'-9596'- with 20, 0.35" holes. Frac MC 22nd stage with 204,100#, 20/40 PSA Sand Perf 23rd stage 9238'-9392'- with 20, 0.35" holes. Frac MC 23rd stage with 204,900#, 20/40 PSA Sand Perf 24th stage 9034'-9188'- with 20, 0.35" holes. Frac MC 24th stage with 206,200#, 20/40 PSA Sand 1/14/18-Perf 25th stage 8830'-8984'- with 20, 0.35" holes. Frac MC 25th stage with 203,200#, 20/40 PSA Sand Perf 26th stage 8626'-8780'- with 20, 0.35" holes. Frac MC 26th stage with 206,000#, 20/40 PSA Sand Perf 27th stage 8422'-8576'- with 20, 0.35" holes. Frac MC 27th stage with 204,600#, 20/40 PSA Sand Perf 28th stage 8218'-8372'- with 20, 0.35" holes. Frac MC 28th stage with 204,800#, 20/40 PSA Sand 1/15/18-Perf 29th stage 8014'-8168'- with 20, 0.35" holes. Frac MC 29th stage with 205900#, 20/40 PSA Sand Perf 30th stage 7810'-7964'- with 20, 0.35" holes. Frac MC 30th stage with 206900#, 20/40 PSA Sand Perf 31st stage 7602'-7759'- with 20, 0.35" holes. Frac MC 31st stage with 205500#, 20/40 PSA Sand Perf 32nd stage 7394'-7551'- with 20, 0.35" holes. Frac MC 32nd stage with 203500#, 20/40 PSA Sand Perf 33rd stage 7186'-7343'- with 20, 0.35" holes. Frac MC 33rd stage with 201300#, 20/40 PSA Sand 1/16/18-Perf 34th stage 6978'-7135'- with 20, 0.35" holes. Frac MC 34th stage with 205000#, 20/40 PSA Sand Perf 35th stage 6770'-6927'- with 20, 0.35" holes. Frac MC 35th stage with 205000#, 20/40 PSA Sand Perf 36th stage 6562'-6719'- with 20, 0.35" holes. Frac MC 36th stage with 205000#, 20/40 PSA Sand 1/17/18-Perf 37th stage 6354'-6511'- with 20, 0.35" holes. Frac MC 37th stage with 204400#, 20/40 PSA Sand Perf 38th stage 6146'-6303'- with 20, 0.35" holes. Frac MC 38th stage with 204500#, 20/40 PSA Sand Perf 39th stage 5938'-6095'- with 20, 0.35" holes. Frac MC 39th stage with 213571#, 20/40 PSA Sand Perf 40th stage 5730'-5887'- with 20, 0.35" holes. Frac MC 40th stage with 205000#, 20/40 PSA Sand Set Kill plug @ 5680'

RDMO

1/18/18-1/19/18- wait on DO

1/20/18-1/23/18- MIRU- DO Frac plugs. Pull tie back. RSI

1/24/18- Circ

1/25/18-Land Production string /Gas lift system. Landed @ 5463'. 166 Jnts of 2 7/8" 6.5# L-80. Packer set @ 5331', 9 Gas Lift Valves

1/26/18-2/1/18- flow back

2/2/18- Oil Delivery

Choke Size= 40/64", Tbg Prsr=70, Csg Prsr= 585 psi, Sep Prsr= 40 psi, Sep Temp= 55 degrees F, Flow Line Temp= 72 degrees F, Flow Rate= 192 mcf/d, 24hr Fluid Avg= 20.29 bph, 24hr Wtr= 12 bbls, 24hr Wtr Avg= .5 ph, Total Wtr Accum= 12 bbls, 24hr Oil= 475 bbls, 24hr Oil Avg= 19.79 bph, 24hr Fluid= 487 bbls