



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 7-30-2018 Operator Hilcorp API # 30-039-20064

Property Name San Juan 28-5 Unit Well # 68 Location: Unit M Sec 33 Twn 28 Rge 5

Land Type:

State _____
Federal X
Private _____
Indian _____

NMOCD
JUL 30 2018
DISTRICT III

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well ~~(TA)~~ Work over TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 560 psi. for 40 mins. Test passed/failed

REMARKS: Pressured up to 560psi - had drop to 520psi in first 10min -
Had drop to 535psi at 20min - Drop to approx 530psi at 25min. Held at
520psi for last 10min of test - ran test over 10min to make sure stable

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Ensite Supervisor
(Position)

Revised 02-11-02