



[http://emnrd.state.nm.us/oed/District III/3distric.htm](http://emnrd.state.nm.us/oed/District%20III/3distric.htm)

DISTRICT III

(submit 1 copy to above address)

Date of Test 7-12-18 Operator Benson Mountain Greer API #30-0 45-21519
Property Name La Plata Mancos Ltd Well No. 7 Location: Unit Section 29 Township 32 Range 13
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 5 Intermediate N/A Casing 10 Bradenhead 13

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	7		10		
10 min	10		10		
15 min	10		10		
20 min	10		10		
25 min	11		10		
30 min	11		10		

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

CLEAR FRESH SALTY SULFUR BLACK

BRADENHEAD 12 INTERMEDIATE 14

REMARKS: Water when opened - surging - Part in bucket at 5 min
Mainly Gas at 8 min - through rest of 30 min (est
- tubing would be oil - Gas in 30 min.

By Juan Medrado.
(Position)

Witness Monica Kuchling
Gas Samples taken from
BH & prod. casing
water sample taken

E-mail address