



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 25, 2018 Operator SG Interests I, Ltd. API #30-045-24159

Property Name SE Cha Cha Unit Well No. 36 Location: Unit 2 Section 8 Township 28N Range 13W

Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate N/A Casing 18 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>18</u>		
10 min	<u>0</u>		<u>18</u>		
15 min	<u>0</u>		<u>18</u>		
20 min	<u>0</u>		<u>18</u>		
25 min	<u>0</u>		<u>18</u>		
30 min	<u>0</u>		<u>18</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>IN 5 SECONDS</u>	
Nothing		
Gas		
Gas & Water		
Water		

DENIED
FAILURE TO COMPLY WITH
BRADENHEAD TEST
MEMORANDUM DATED
FEBRUARY 2, 2018

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

less than 116 pressure initial Blow Down In
5 seconds.

By Bruce Crawford

Witness _____

Pumper
(Position)

E-mail address _____

NMOCB
JUL 30 2018
DISTRICT III