

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

NMOC

MAR 01 2018

DISTRICT III

Date of Test 2/23/2018 Operator Hilcorp Energy Company API # 3004526112  
Property Name MCCORD Well No. 11E Location: Unit C Section 09 Township 030N Range 013W  
Well Status Flowing Initial PSI: Tubing 143 Intermediate        Casing 143 Bradenhead 136

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min	0		146			Steady Flow	
10 min	0		149			Surges	
15 min	0		151			Down to Nothing	Y
20 min	0		154			Nothing	
25 min	0		157			Gas	
30 min	0		169			Gas & Water	
						Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR        FRESH        SALTY        SULFUR        BLACK       

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR        FRESH        SALTY        SULFUR        BLACK       

5 MINUTE SHUT-IN PRESSURE Bradenhead 3 Intermediate       

REMARKS:

BH has 136# that blew DTN in 20 secs thru 1' valve. BH has 0 pressure throughout 30 min test. 5 min shut-in had 3# that blew to nothing in 2 sec.

Tested By pjim Witness Thomas Versmerch