



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

NMOC

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

III 24 2018

DISTRICT III

Date of Test 7-24-2018 Operator Koch/Mustang Res. API #30-0 45-27386

Property Name AB Geren Well No. 3 Location: Unit L Section 24 Township 29 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>0</u>		
10 min	<u>0</u>	<u>5</u>	<u>0</u>		
15 min	<u>0</u>	<u>5</u>	<u>0</u>		
20 min		<u>5</u>			
25 min		<u>5</u>			
30 min		<u>5</u>			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Light puff to nothing when BH opened - Nothing on BH after five minute shut in.

By [Signature]
Production Mgr
(Position)

Witness [Signature] NMOC

E-mail address djohnson@mustangresourcesllc.com