| Form 3160-5 (August 2007) | UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANA | | RECE | IVED OM | RM APPROVED B No. 1004-0137 ires: July 31, 2010 | |
|---|--|--|--|---|---|--|
| Do not i | UNDRY NOTICES AND REPOR use this form for proposals to c ed well. Use Form 3160-3 (APD | frill or to re-ente | Kan inoton | 6. If Indian, Allottee or Trit | NM-10431 | |
| | SUBMIT IN TRIPLICATE - Other instruct | | | 7. If Unit of CA/Agreement | , Name and/or No. | |
| 1. Type of Well Image: Constraint of Well Image: Oil Well Image: X Gas Well Image: Other othe | | | | 8. Well Name and No. BURNS RANCH 1 | | |
| 2. Name of Operator | Hilcorp Energy Company | | | 9. API Well No. 3003922116 | | |
| 3a. Address 382 Road 3100, Aztec, | Phone No. (include are 505-599-34 | | 10. Field and Pool or Exploratory Area Campo Gallup | | | |
| 4. Location of Well <i>(Footage, Sec., T.</i> Surface Unit A (NENE | .R.,M., or Survey Description) E), 790' FNL & 790' FEL, Sec. 13, T0 | 29N, R004W | | 11. Country or Parish, State RIO ARRIBA | , New Mexico | |
| 12. CHEC | K THE APPROPRIATE BOX(ES) TO | INDICATE NATU | RE OF NOT | ICE, REPORT OR OT | HER DATA | |
| TYPE OF SUBMISSION | 2 | ΤY | PE OF AC | ACTION | | |
| Notice of Intent | Acidize Alter Casing Casing Repair | Deepen Fracture Treat New Construction | R | roduction (Start Resume) eclamation ecomplete | Water Shut-Off Well Integrity Other | |
| X Final Abandonment Notice | Change Plans | Plug and Abandon Plug Back | | emporarily Abandon 'ater Disposal | FAN | |
| | P&A'd on 11/4/2011. Reclamation was inspected and passed on d. | | | | | |
| | | | | Land 3 | | |
| | | | | | | |
| | | | | DISTRICT | | |
| | s true and correct. Name (Printed Typed) | | | | | |
| Kandis Roland | | Title Op | Title Operations/Regulatory Technician - Sr. | | | |
| Signature Madua | laland | | /13/2018 | | | |
| | THIS SPACE FOR F | or certify | Title Office | | JUPat 3 0 2018 | |
| Title 18 U.S.C. Section 1001 and Title | 43 U.S.C. Section 1212, make it a crime for an s or representations as to any matter within its . | | d willfully to m | nake to any department or ag | ency of the United States any | |
| (Instruction on page 2) | | NMOCD. | - | | | |

| North Contraction of the Contrac | | 1 |
|--|---|-------------------------|
| RCC Reclamation Completion | Location Name: BULNS RUNCH #1 Date: 10-24-2017 | Revision 3 (3/21/17) |
| API#: 30-039-21160 | UL-Sec-TWN-Rng: A TZAN RYW Ser 13 Lat/Long: 36.73000, -10 Lease# NM-10431 County/State: RIO ARFIBE | 07.19923 |
| Surface Owner: USFS | Lease# NM-10431 County/State: RIO ARAZRA | 4 NM |
| Pipeline Owner: | Twin/Co-Locate Well Name & Operator: | ,, |
| Onsite: SAMUEL JAQUEL Agency Ins | ctorMl Contractor: Seed Mix: | |
| Interim Reclamation | Final Reclamation | Completed Incomplete |
| Have pit sample results been approved | 3rd party pipeline removed | |
| Has water been removed from pit | Anchors removed Certificate of waste issued & approved | |
| Have pit marker photos been taken | Equipment and piping removed Depth: | |
| Has certificate of waste been issued & approved | Power poles removed Width: | |
| Have all pit contents been removed | Cathodic protection removed | |
| Has sample after content removal been taken | Vegetative cages removed Date of Excavation Start: | |
| Is location contoured | CMP's removed Date of Excevation End: | |
| Is there 4' of cover over pit | Non native gravel buried or removed Date of Backfill Start: | |
| Has top soil been spread evenly | Noxious weeds removed or sprayed Date of Backfill End: | |
| Has all non-native gravel been buried or removed | Insvasive weeds removed or sprayed Yards Hauled Out: | |
| Has pit liner been removed | Contouring complete | |
| Has all trash been removed | Top soil spread Yards Hauled In: | |
| Have all weeds been removed | Diversions clean and functional Fresh Soil Hauled in From: | |
| Teardrop allows vehicle access to all facilities | Silt trap clean and functional K Approval to backfill | |
| Drainage ditches allow adequate run off | Cattle guard / gates removed Back fill mechanically compacted | |
| All non-traffic areas disked properly | Cellar / mouse hole covered / Facilities reset | |
| Ail non-traffic areas seeded | Erosion under control | |
| Seeded areas have been mulched | Location properly ripped | |
| Noxious weeds have been removed or sprayed | Location property disked V Soll Removal Sundry Ready to be Filed | |
| Invasive weeds have been removed or sprayed | Location seeded | |
| Barriers set to deter traffic | Photo transect installed | |
| Silit traps are functional | Access road properly closed | |
| Culverts are functional | Public use controlled | |
| Upper diversion is functional | | |
| Erosion under control | Barriers in place | |
| Photo transect installed | P&A marker installed &Jegible | |
| | | |
| Have wellhead cages and jersey barriers been removed | | |
| Have reclamation pictures been taken | Growth at least 70% | |
| Growth at least 70% | Trash and debris removed from location | |
| Agency Inspection Date: | Final reclamation photos taken | |
| Sundry is ready to file | Agency Inspection Date: 10-24-2017 | |
| | FAN Ready to be filed | |
| Comments: | Comments: Remove fenere Submit F.A.N. | |

.



Southwestern Region 3 Carson National Forest Jicarilla Ranger District 1110 Rio Vista Lane, Unit 2 Bloomfield, New Mexico 87413 Phone: (505) 632-2956 FAX: (505) 632-3173

Sundry Review Checklist

Activity Type:

Plug & Abandon (P&A) Re-entry/Sidetrack

Other: FAN

| Company Name Hilcorp Energy | y Company | Well Name | anch #1 | | |
|--------------------------------|----------------|-----------|---------|--|--|
| API Number | Legal Location | | | | |
| 30-039-22116 | r 29 N | RYW | Sec /3 | | |
| Frotages 790 FNL, 790 FEL | | | | | |

| Specialist Review | Review By (initial) | Review Date | Comments |
|----------------------------------|------------------------|-------------|----------------------------|
| Conditions of Approval (COAs) | | | |
| Archeology | | | |
| Wildlife | | | |
| Construction/Reclamation | | | |
| Other: Approval o | f Fine | 1 Abando. | Date Completed: 10/24/2017 |
| Onsite/Field Visit Required | No | Yes | Date Completed: 10/24/2017 |
| Original COAs apply | | | |
| Forest Service Concurrence | ! | | 301110 |
| Lingrilla District Pong | 2 | | Data |

Jicarilla District Ranger

Date