



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 15 AUG 2018 Operator HILLTOP API # 30-0 39 30047

Property Name SAN JUAN 29-S Well # 23B Location: Unit B Sec 6 Twn 29 Rge S

Well Type:

State \_\_\_\_\_  
Federal \_\_\_\_\_  
Private \_\_\_\_\_  
Indian \_\_\_\_\_

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal \_\_\_\_\_  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas \_\_\_\_\_  
Pressure observation \_\_\_\_\_

Temporarily Abandoned Well (Y/N): \_\_\_\_\_ TA Expires: \_\_\_\_\_

Surf Pres. \_\_\_\_\_ Tbg. SI Pres. \_\_\_\_\_ Max. Inj. Pres. \_\_\_\_\_  
Casinghead Pres. \_\_\_\_\_ Tbg. Inj. Pres. \_\_\_\_\_  
Surf Inj. Pres. \_\_\_\_\_  
Surf Casing Pres. \_\_\_\_\_

Pressured annulus up to \_\_\_\_\_ psi. for \_\_\_\_\_ mins. Test passed/failed

REMARKS: 100 PSI SPRING, 60 MINUTE CLOCK  
THE CASING WAS PRESSURED UP TO 570 PSI AND  
PRESSURE FELL TO 520 PSI AND HELD FOR THE LAST 15  
MINUTES

By Craig Ward  
(Operator Representative)

Witness [Signature]  
(NMOCD)

Consultant  
(Position)

**NMOCD**

**AUG 16 2018**

Revised 02-11-02

**DISTRICT III**