



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

NMOCD

AUG 16 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-16-2018 Operator Hilecorp Energy API #30-0 45-06123

Property Name Brookhaven Com^E Well No. 6 Location: Unit I Section 36 Township 28 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 0 Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>—</u>	<u>0</u>	<u>20</u>	<u>—</u>	<u>20</u>
10 min	<u>—</u>	<u>0</u>	<u>20</u>	<u>—</u>	<u>20</u>
15 min	<u>—</u>	<u>0</u>	<u>20</u>	<u>—</u>	<u>20</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		<u>X</u>
Nothing	<u>X</u>	
Gas		<u>X</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Light puff on intermediate when opened. Nothing on intermediate after 5min shut in. Nothing on BH when opened, nothing on BH after 5min shut in

By Jeff HMM

Witness J. K. H NMOCD

(Position)

E-mail address _____