



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

NMOCD

AUG 14 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-14-18 Operator Hilcap Energy Co. API #30-0 45-29344

Property Name Purine Well No. 1 Location: Unit 0 Section 11 Township 29 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 1 Intermediate 1/4 Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>5</u>		
10 min	<u>0</u>		<u>5</u>		
15 min	<u>0</u>		<u>5</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>2</u>
Nothing	<u>1</u>
Gas	<u>2</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/4

REMARKS:

Nothing when opened. Nothing when
opened after 5 min shut in

By [Signature]

Witness [Signature]

(Position)

E-mail address _____