

NEW MEXICO EMERGY, MIMERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

1 200				· · · ·
VAHE	1		17	
1 8 117		1	20	

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

A 5 1/2	
	10 Th 12 Th

Date of Test_	8/8/201	8 Operator	Roddy Production Co. A	PI #30-045-32962			
Property Name <u>Lucerne Federal</u> Well No. <u>9</u> Location: Unit <u>F</u> Section <u>17</u> Township <u>28N</u> <u>Range11W</u>							
Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate MR Casing 6 Bradenhead 0							
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg		FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE					
TIME 5 min 0	<u>6</u>		Steady Flow				
10 min <u>0</u>	<u>b</u>		Surges				
15 min 0	6		Down to Nothing				
20 min			Nothing X				
25 min							
30 min			Gas & Water				
			Water				
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR FRESH SALTY SULFURBLACK							
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE							
REMARKS: Wellow Casing flow							
By Jeremy Divine Witness							
Foreman (Position	on)						
E-mail address <u>jdivine@crownquest.com</u>							