OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District/III/3distric.htm

DISTRICT III

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test		July 17, 2018				Operator SAN JUAN RESOURCES AP					P1 #30-0 45-33768				
Property NameMEMO		MEMG	GEM WALTERS 34			Well No.	1	Location: Unit	I_S	Section	34	Towns 32N	Ran	ge_13W_	
Pressure (Shut-In or Producing)		cing)	Producing		Tubing 110			Intermediate		Casing	135	_ Bradenhead .	0		
	OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURES: BRADENHEAD INTERMEDIATE														
	PRESSURES:										BRADENHEAD			DIATE	
TESTING TIME	BH	RADENHEA INT	CSG	INTERN	CSG	1						FLOWED	F	LOWED	
TIVIE	DII	11/1	CSG	1111	CSG	1			_			TLOWED	**	LOWED	
5 minutes	0		135					Steady Flow	_						
10 minutes	0		135					Surges	_						
15 minutes	0		135					Down to Nothing	_						
20 minutes	0		135					Nothing	_		X				
25 minutes	0		135					Gas							
30 minutes	0		135					Gas & Water							
								Water							
If bradenhead flowed water, check all of the descriptions that apply below:															
11 bradeinead 1	iowed water	, check an													
CLEAR			FRESH		SALTY			SULFUR			BLA	ACK			
REMARKS:		5 MINUTI	E SHUT-IN	BRA	ADENHEAD	0	-	INTERMEDIATE							
Bradenhead had no pressure at all during the entire test. This is a plunger lift well.															
Ву		Theo Hampton					Wit	ness							
	Lease Operator														
	(Position)							NMOCO							
								MIN C O D							
							AUG 0 8 2018								