



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOCd

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

SEP 08 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-6-18 Operator H: Corp API #30-0 45-07529
Property Name Aztec Well No. 5 Location: Unit 14 Township 28 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate 0 Casing 18 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	17	0	18
10 min	0	0	17	0	18
15 min	0	0	18	0	18
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	/	/
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

top of bh plate has new welding fixed
34 Nothing when opened - Nothing when opened after 5
min shut in Int - Nothing when opened. Nothing
By Dan Paul Witness Meda Ching
When opened after 5 min
Shut in

(Position)

E-mail address _____