OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

DISTRICT 111

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	Test July 31 2018 Operator M&G Drilling Com							pany			45-32488				
Property Name		SCHLOSSER 27				104	_Location: Unit	P	Section	27	Township	28N	Range	11W	
Well Status (Shut-Inor Producing) Ini				Initial PSI:	Tubing	_3	_ Intermediate	None	Casing	14	_Bradenhead	,	0		
	OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH														
		PRESSURES:							FLOW CHARACTERISTICS						
TESTING	вн	Bradenhe INT		INT Int	ERM				PDADE	NHEAD		IN	TERMEI	MATE	
TIME	БП	INI	Csg	11111	Csg]			DRADE	NHEAD			TERMEL	MATE	
5 minutes	0	-	14			-	Steady Flow								
10 minutes	0		14				Surges	-							
15 minutes	0		14				Down to Nothin								
20 minutes							Nothing								
25 minutes							Gas								
30 minutes							Gas & Water								
							Water								
If bradenhead flowed water, check all of the descriptions that apply below:															
CLEAR	CLEAR FRESH SALTY SULFUR BLACK														
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE															
REMARKS:															
	16		1												
Ву	Agml/s	limm				Witnes	s								
			(Daviday)			-									
(Position) E-mail address															
											NMO	CD			
								AUG 2 7 2018							