OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC , NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	Aug. 7	2018	Operator	M&G Dri	lling Com	pany		API	#30-0	45-32514			
Property Name		KRAUSE		Well No.	115	Location: Unit	I	Section	28	Township	28N	Range	11W
Well Status (Shut-I	n or Froducing		Initial PSI:	Tubing	10	Intermediate	None	Casing	4	Bradenhead		0	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

		PR	RESSURE	S:		FLOW CHARACTERISTICS				
	Bradenhead INTERM									
TESTING	BH	INT	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE		
TIME 5 minutes	0		4			Steady Flow				
10 minutes	0		4			Surges				
15 minutes	0		4			Down to Nothing	V			
20 minutes						Nothing				
25 minutes						Gas	V			
30 minutes						Gas & Water				
						Water				
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR										
E-mail address			(Position)			Portibular Devices of several	7. m.		
							NMOCD			
						AUG 2 7 2018				
							DISTRICT			