OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC , NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test July 31 2018 Operator M&G Drilling Company API #30-0 45-33835		
Property Name KRAUSE 33 Well No. 103 Location: Unit H Section 33 Township 28N Ra	nge 11W	
Well Status (Shut-In or Froducing)  Initial PSI: Tubing 5 Intermediate Mone Casing 6 Bradenhead		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURES: FLOW CHARACTERISTICS		
Bradenhead INTERM  TESTING BH INT Csg Int Csg BRADENHEAD INTE	RMEDIATE	
TIME 5 minutes  O  6  Steady Flow		
10 minutes O 6 Surges		
15 minutes O 6 Down to Nothing		
20 minutes Nothing		
25 minutes Gas		
30 minutes Gas & Water		
Water		
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFUR BLACK		
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE		
REMARKS:		
By WitnessWitness		
(Position)		
E-mail addressNMOCD		
AUG 27 2018		
DISTRICT 111		