

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

AUG 23 2018

FORM APPROVED
OMB No. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

5. Lease Serial No.

N0-G-1403-1908

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit of CA/Agreement, Name and/or No.
NMNM 135216A

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No.

W Lybrook Unit #743H

2. Name of Operator

Enduring Resources IV, LLC

9. API Well No.

30-045-35729

3a. Address

332 Cr 3100 Aztec, NM 87410

3b. Phone No. (include area code)

505-636-9743

10. Field and Pool or Exploratory Area

Lybrook Mancos W

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SHL: 1209' FSL & 1346' FWL, Sec 8, T23N, R8W

BHL: 940' FNL & 335' FEL, Sec 17 T23N, R8W

11. Country or Parish, State

San Juan, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other Flared
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	with Gas
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	Sample

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

This well flared during the stimulation activity on the following wells and is back on production.

ACCEPTED FOR RECORD

Heros 2308 09L Com 2H (30-045-35687), 3H (30-045-35848), 4H (30-045-35847), 5H (30-045-35877) & Athena 2308 14L #3H (30-045-35876).

Flared: 8/2/18-8/8/18

Total Flared Volumes: 12.30 mcf

Attached Gas Sample

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Lacey Granillo

Title Permit Specialist

Signature

Date 8/23/18

THE SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

2

Diablo Analytical BTU Report

GPA 2145-03 Analysis

Sample Information

Sample Information	
Sample Name	WLU 743
Station Number	
Taken By	Alpine Analysis LLC
Operator	Travis Tapp
Method Name	StandardNatGas.met
Injection Date	2018-07-12 10:23:55
Report Date	2018-07-12 10:27:43
EZReporter Configuration File	default Standard Sample.cfgx
Source Data File	2018-07-12 10-23-38 (GMT -06-00)WLU 743.dat
EZReporter Data File	WLU 743-20180712-102743.ezrx
Data Source	Agilent EZChrom Connector

Component Results

Component Name	Ret. Time	Peak Area	Norm%	Gross HV (Dry) (BTU / Ideal cu.ft.)	Relative Gas Density (Dry)	GPM (Dry) (Gal. / 1000 cu.ft.)
Nitrogen	0.321	47571906.0	79.50256	0.0	0.76895	8.752
Methane	0.333	5163934.0	12.53394	126.9	0.06943	2.126
Carbon Dioxide	0.381	97344.0	0.16443	0.0	0.00250	0.028
Ethane	0.429	1285215.0	2.05890	36.5	0.02138	0.551
Hydrogen Sulfide	0.601	0.0	0.00000	0.0	0.00000	0.000
Propane	0.531	5256548.0	3.08674	77.8	0.04700	0.851
i-Butane	0.579	911009.0	0.45943	15.0	0.00922	0.150
n-Butane	0.612	2428885.0	1.20086	39.3	0.02410	0.379
i-Pentane	0.717	747013.0	0.33208	13.3	0.00827	0.122
n-Pentane	0.760	773646.0	0.33053	13.3	0.00823	0.120
Hexanes Plus	0.000	943118.0	0.33053	0.0	0.00000	0.000
Water	0.000	0.0	0.00000	0.0	0.00000	0.000
Total:			100.00000	322.1	0.95907	13.079

Results Summary

Result	Dry	Sat. (Base)
Total Raw Mole% (Dry)	83.86510	
Pressure Base (psia)	14.730	
Temperature Base	60.0	
Water Mole%	-	1.74067
Gross Heating Value (BTU / Ideal cu.ft.)	322.1	316.5
Gross Heating Value (BTU / Real cu.ft.)	322.4	316.8
Relative Density (G), Real	0.9595	0.9539
Compressibility (Z) Factor	0.9991	0.9989
Total GPM	13.079	12.954