

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley, Division Director
Oil Conservation Division



September 12, 2018

Benson-Montin-Greer Drilling Corp
Attn: Matt Diamond
4900 College Blvd
Farmington, NM 87402-7402

Re: 2018 Bradenhead Test
Well: La Plata #2 , UL F Sec 30 Twn 32N Rge 13W, API # 30-045-21847

Dear Mr. Diamond,

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **October 12, 2018**, and initiate remedial activity before **December 11, 2018**. The initial Surface Casing psi was 26. The initial Production Casing psi was 26. The five minute Surface Casing shut in pressure was 32. The well was shut in at the separator when we arrived. The production casing pressure and bradenhead pressure climbed while bradenhead was open indicating there is direct communication between bradenhead and production casing.

Wellbore schematic was received on location at time of test.

Reference: RBDMS MPK1819357133 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File